PT. SMART CAKRAWALA AVIATION

WORK ORDER

Form: SCA/MTC/030

Subject : **10 Hours // 7 Days Inspection & Add**	No.	WO/210-SNX/IX/2022
	Date	5 September 2022
	A/C Reg.	PK-SNX EC130T2-8829
Reference : MP EC 130 T2 Rev. 02	Prepared By	TS
	Checked By	CI
	Approved By	TM

To : Engineer In Charge

Description :

1. Perform 10 Hours // 7 Days Inspection & Add
2. Make an entry in Maintenance Log.
3. Return the Completed Work Order and Form to PPC.

#If any finding, please close the routine card, and transferred to inspection card.

Additional Work :

— Nil.

Compliance Statement	Sign & Date 10-9-'22 Company Lic. No.: SCA	Signature
%	(Engineer In Charge)	(Technical Manager)

2022/09/10 20:00

ITEM CODE NO.	TASK	INITIAL
PC070	Swashplate bearing No grease runs, no change in paint color or paint flaking.	
PC071	Scissors, swashplates, rod swivel bearings Condition, attachment, abnormal play (manual check).	
PC072	Swashplate/pitch change rod end-fitting – interfaces No impact mark or paint flaking on swashplate attachment yokes.	
PC073	Pitch change rods Condition, no radial play in end-fittings.	

ITEM CODE NO.	TASK	INITIAL
PC078	Visible part of the Starflex Star (1) arm (2): • no delamination, condition of the paint. If in doubt or damage is found (AMM 62-21-00,6-1). • Bushings (3) at the end of the arms of the STARFLEX (1) No gap between adhesive bead and bushing. If in doubt or damage is found (AMM 62-21-00,6-1).	
PC079	Spherical thrust bearings No elastomer damage, delamination, splits, blisters, extrusions or cracks (other than minor and unchanging surface irregularities), elastomer protuberance at the laminated area/small reinforcing structure interface.	
PC080	Frequency adapters (PRE MOD 076232) If in doubt or damage is found (AMM 62-21-00,6-4). No elastomer damage, delamination, splits, blisters, extrusions or cracks (other than minor and unchanging surface irregularities). If in doubt or damage is found (AMM 62-21-00,6-7).	
PC081	Ventilated frequency adapters (POST MOD 076232) No elastomer damage, delamination, splits, blisters, extrusions or cracks (other than minor and unchanging surface irregularities). If in doubt or damage is found (AMM 62-21-00,6-7). Check that ventilation holes are not obstructed (on both sides). On adapters fitted with drilled bush 365A31-1018-21 or 22, ensure lockwire is in place in holes on trailing edge side.	

2022/09/10 20:04

2022/09/10 20:00

AIRCRAFT CHECK WORK SUMMARY
(Form: SCA/MTC/051)

DATE OF ISSUED	JO/WO #	TYPE OF MAINTENANCE	DATE OF ACCOMPLISHED
5 Sept 2022	WO/210-SNX/IX/2022	INSP. 10H/7D & ADD	10 - 9 - 2022

A/C Type	Mfg. Serial Number	A/C Registration
EC 130 T2	8829	PK-SNX

AIRCRAFT DATA

Subject	Pos #	Serial Number (SN)	TTSN/TCSN
Engine	#1	53467	729:44 / N1:894, N2:34%
	#2	-	
Propeller/Rotor	#1		
	#2	-	
Landing Gear	NLG	-	
	LH MLG	-	
	RH MLG	-	

PACKAGE COVERED

No	Subject	Qty	Remark
1	Non-Routine Card	-	
2	Inspection Card	1	
3	Work Order	1	
4	Summary Inspection List	1	
5	Material and Tool List	-	
6	Escalation form	-	
7	CRS (SMI / Unscheduled Maintenance)	1	

INSPECTION CARD (IC) LIST (Finding during maintenance)

No	Taskcard Ref	Subject	Status		Name/ Sign & Stamp
			Open	Close	
IC-001					
IC-002					
IC-003					

Prepared by : Technical Support	Checked by : Chief Maintenance	Verified by : Chief Inspector	Approved by : Technical Manager
Hani	Dodit	Yanuar	Istiono

smartaviation

SUMMARY INSPECTION ITEMS
(Form: SCA/MTC/050)

WO Ref: WO/210-SNX/IX/2022

NO.	TASK CARD NO.	DESCRIPTION	DATE	EST MHR	NAME	STAMP
1	CHAPTER 6	10 H / 7 DAYS INSPECTION	10/9'22	-	Imran	
2	CHAPTER 26	P CHECK	10/9'22	-	Imran	
3	CHAPTER 16	15 H / 7 DAYS INSPECTION	10/9'22	-	Imran	

2022/09/10 20:01

smartaviation

INSPECTION CARD
(Form: SCA/MTC/ 048)

TECHNICAL DEPARTMENT

1. CARD #	2. JO/WO #	3. ORIGINATOR	4. CARD REF	5. DATE
				10-9-22
6. A/C REG/MSN	7. A/C TYPE	8. TRADE	12. VENDOR ORDER #	
AK-SNX/8829	GC135			
9. ZONE	10. STA	11. MTC TYPE		

13. DESCRIPTION/DEFECT-IF FINDING OF CPCP INSPECTION, PLEASE COMPLETE SET. 20	14 PPC/ENG	15 DATE
NIL		

16. CORRECTIVE ACTION	17 MECH	18 ENG. LIC	19 DATE
NIL Performed at A/C TT : ..... A/C TC /LDG :			

20. CORROSION INFORMATION

LOCATION	CAUSE OF DAMAGE
	☐ Environment
	☐ Internal Leakage
CORROSION ☐ Isolated ☐ Widespread	☐ Chemical Spill
CORROSION LVL ☐ 1 ☐ 2 ☐ 3	☐ LAV/Galley Spill
PROPOSED ACTION ☐ Doublers	☐ Blocked Drain
☐ Others	☐ Wet Insulation Blanket
.....	☐ Other

21. If the defect is RII, Please Sign this card finally by RII Inspector	INSP	DATE
NOTICE OF INSPECTOR		

22. PARTS REQUIRED

PART DESCRIPTION	PART NO	QTY	SERIAL NO		STATUS	
			ON	OFF	CLOSE	OPEN

23. TOOLS REQUIRED

DESCRIPTION	PART NO. / MODEL	NEXT CALIBRATION DATE	STATUS

2022/09/10 20:01

2022/09/10 20:01

PT. SMART CAKRAWALA AVIATION

CERTIFICATE RETURN TO SERVICE

SCHEDULED MAINTENANCE INSPECTION
(CRS-SMI)

A/C TYPE	: EC 130 T2	TTSN	: 729 : 44 .
A/C REG	: PK-SNX	TCSN	: N_1 = 894, N_2 = 346
MSN	: 8829	DATE	: 10-9-2022

TYPE OF INSPECTION : 10 HOURS // 7 DAYS INSPECTION & ADD TASK
DUE AT : 735:14 Hrs or 10.09.2022
REFF : MP EC 130 T2 REV. 02

EXCEPTION

nil

AUTHORIZED PERSON

I hereby certify that this aircraft has been maintained accordance with CASR and Maintenance Program. Aircraft safe and airworthy for flight

NAME	CAT	AMEL/OTR NO	SIGN&STAMP	DATE
Iwan	AIRFRAME & POWER PLANT	2016		10 9 '22
	EIRA			

THE NEXT DUE TYPE OF INSPECTION : 110 Hrs.

DUE AT : 733:29.

Form: SCA/MTC/049

smartaviation

MAINTENANCE PROGRAM
AIRBUS HELICOPTERS EC 130 T2

Chapter 6 – 10FH // 7D

Reg. Mark	: PK - SNX	Date	: 10 - 9 - 22
MSN	: 8829	Station	: MKW / SP3.
TSN / CSN	: 729:44 / 894 & 346.	WO No.	: WO-210/SNX/IX/2022

ITEM CODE NO.	CHAPTER	TASK	ENGINEER'S SIGNATURE, STAMP & DATE
05/21/00 /000/000 /020	05-21	P-check VC AMM 05-40-00, 6-7	10 - 9 - 22
05/21/00 /000/000 /030	05-21	P-check - Optional equipments Note: Maintenance operations can be carried out by an aircrew member. VC AMM 05-40-00, 6-8	10 - 9 - 22
53/00/00 /000/000 /050	53-00	Structure Salt-laden atmosphere Rinsing and Drying. CLN AMM 12-20-00, 3-3	10 - 9 - 22
*** End of 10FH // 7D Inspection Items ***			

PERSONNEL PRTICIPATING IN THIS INSPECTION

NAME	POSITION	SIGNATURE	LICENSE NUMBER
–	–	–	–

RETURN TO SERVICE

The work recorded above has been carried out in accordance with the requirements of the Civil Aviation Safety Regulation for the time being in force and in that respect the aircraft is considered for Release to Service.

Name	: Imron	Stamp	:
Signature	:	Place/Date	: SP3 / 10 - 9 - 22

2022/09/10 20:01

2022/09/10 20:02

smartaviation

MAINTENANCE PROGRAM
AIRBUS HELICOPTERS EC 130 T2

Chapter 16 – Arriel 2D 15FH // 7D Inspection

Reg. Mark	: PK - SNX	Date	: 10 - 9 - 22.
MSN	: 8829	Station	: SP3.
TSN / CSN	: 729:44 / 894 & 346.	WO No.	: : WO/210-SNX/IX/2022

ITEM CODE NO.	CHAPTER	TASK	ENGINEER'S SIGNATURE, STAMP & DATE
N/A	N/A	Record the corrective maintenance operations performed in the engine log book, if any.	10-9-22
N/A	N/A	Make sure that the automatic cycle counting is correct. EMM 05-10-02-200-801	10-9-22
N/A	N/A	In the engine log book, record the total number of C1 and C2 cycles consumed as counted by the EECU. EMM 05-10-02-200-801	10-9-22
N/A	N/A	Visually examine the engine and the engine floor for leakage.	10-9-22
N/A	N/A	Visually examine the engine attachments and fire protections for signs of impact or deterioration. Refer to Helicopter Manual **Note: Fire protections of shut off valve and HMU**	10-9-22
N/A	N/A	Record the values from the creep damage counter in the engine logbook. EMM 05-15-00-200-801	10-9-22
N/A	N/A	Record in the engine logbook the accumulation of flying hours. EMM 05-10-02-200-801	10-9-22
N/A	N/A	Check that the HP gas generator rotates freely (no abnormal noises) and visually check that the engine is in good condition. Note: **Manually or during a dry crank cycle**	10-9-22
N/A	N/A	Manually check that the power turbine rotates freely (no abnormal noises). EMM 05-10-02-200-801	10-9-22

2022/09/10 20:02

smartaviation

MAINTENANCE PROGRAM
AIRBUS HELICOPTERS EC 130 T2

Chapter 16 – Arriel 2D 15FH // 7D Inspection

ITEM CODE NO.	CHAPTER	TASK	ENGINEER'S SIGNATURE, STAMP & DATE
N/A	N/A	Inspection of oil level in tank and top up if required. Refer to Helicopter Manual Note: **Within 15 minutes following engine shut-down.**	SMART CAKRAWALA 22 AVIATION 10-9-22
N/A	N/A	Make sure that there are no foreign objects: examine near the air intakes and the exhaust zone. Install the blanks.	SMART CAKRAWALA 22 AVIATION 10-9-22
*** End of Arriel 2D 15FH // 7D Inspection Items ***			

PERSONNEL PRTICIPATING IN THIS INSPECTION			
NAME	POSITION	SIGNATURE	LICENSE NUMBER
—	—	—	.
	.		

RETURN TO SERVICE

The work recorded above has been carried out in accordance with the requirements of the Civil Aviation Safety Regulation for the time being in force and in that respect the aircraft is consider fit for Release to Service.

Name : Imron

Stamp : SMART CAKRAWALA 22 AVIATION

Signature :

Place/Date : SP-3 / 10-9-22

2022/09/10 20:02

Reg. Mark : PK - SNX

Date : 10-9-22

Station : SP 3.

FML No :



ITEM CODE NO.	TASK	INITIAL	ITEM CODE NO.	TASK	INITIAL
STATION 1					
PC001	Door jambs, canopy arches. Condition, no cracks.	/mw	PC003	Sideslip indicator. Condition.	/mw
PC002	Pitot tube. Condition, cover removed or fitted as necessary.	/mw	PC004	MGB - Engine oil cooler air inlet. Condition, no obstruction or foreign bodies, blanking cover removed or fitted as necessary.	/mw
STATION 2					
PC005	Front door jettison system Condition, no cracks (especially at the link).	/mw	PC019	Rear cargo door Closed and locked.	/mw
PC006	Left cabin access doors Condition, attachment, locking, no abnormal play.	/mw	PC020	LH side MGB and engine cowlings Opening, condition of locking systems, no abnormal play.	/mw
PC007	Landing gear Condition of crosstubes, skids, resistant plates, footstep attachment.	/mw	PC021	Upper cowlings Locked.	/mw
PC008	Static pressure ports Condition, blanks removed or fitted as necessary.	/mw	PC022	NACA air inlet No obstructions (clean if necessary).	/mw
PC009	OAT probes Condition, attachment.	/mw	PC023	MGB Condition, oil level, no leaks.	/mw
PC0010	Antennas under bottom structure Condition.	/mw	PC024	Transmission deck Cleanliness.	/mw
PC011	Landing and taxiing lights Condition.	/mw	PC025	MGB support bars Condition, attachment.	/mw

2022/09/10 20:03

ITEM CODE NO.	TASK	INITIAL	ITEM CODE NO.	TASK	INITIAL
PC012	Scoop Condition, cleanliness.		PC026	Hydraulic system (LH side) Condition, attachment points, pipes, filter clogging indicator retracted, no leaks.	
PC013	Lower cowlings Condition, secured.		PC027	Servos Attachment, no leaks or cracks.	
PC014	Left cargo door Opening, condition, attachment points, no abnormal play.		PC028	Gimbal ring assembly Fitting, safety pins in place and locked.	
PC015	Left cargo door Closed and locked.		PC029	Electrical harnesses Condition, attachment.	
PC016	Rear cargo door Opening, condition, attachment points, no abnormal play.		PC030	Fuel shut-off valve Condition, attachment, no interference.	
PC017	Rear cargo bay FADEC secured and harness condition.		PC031	MGB cowling (LH side) Closed and locked.	
PC018	KANNAD INTEGRA AP-H Emergency Locator Transmitter Condition, security, check "ARM" or "OFF" as necessary.		**NOTE** If the aircraft is grounded for a long period (more than 2 months), set the switch on the ELT to the "OFF" position.		
STATION 2 – ENGINE AND ENGINE BAY					
PC032	Engine air intake Attachment: condition, seal condition.		PC038	Fuel filter Clogging indicator retracted.	
PC033	Firewall Condition, no cracks.		PC039	Oil system No leaks.	
PC034	Engine and accessories General condition, cleanliness, leak-tightness, attachment, pipes, electrical harness.		PC040	Engine mounts Condition, attachment.	
PC035	Engine transmission deck Condition, cleanliness, no leaks.		PC041	Engine deck drain holes No obstructions or debris.	
PC036	Engine casing Attachment flange condition.		PC042	Exhaust pipe Condition, blanking cover removed or fitted, as necessary.	
PC037	Oil filter Clogging indicator retracted.				
STATION 3					
PC043	Tail boom Condition, condition of antennas.		PC048	TRH fairing Condition, damage or cracks, no rotations (paint marks).	
PC044	Drive shaft fairings Attachment, condition of heat shield.		PC049	Tail rotor duct Condition, check distance between blade tips and duct.	

ITEM CODE NO.	TASK	INITIAL	ITEM CODE NO.	TASK	INITIAL
PC045	Tail boom door Opening, attachment, bay condition, closed.	/AW	PC050	Tail rotor blades, visible part Condition, no impact, damage, scratches, erosion. Check play.	/AW
PC046	Horizontal stabilizer, fin Condition, attachment points, condition of external lights and fin antennas.	/AW	PC051	Freewheel Make the freewheel turn by turning the tail rotor. The free turbine must be driven when the tail rotor is turned anti-clockwise. In the clockwise direction, the freeturbine does not drive.	/AW
PC047	Keel, tail guard Condition, attachment.	/AW			
STATION 4					
PC052	TGB Condition, attachment, oil level.	/AW	PC055	Horizontal stabilizer, fin Condition, attachment points, external light condition.	/AW
PC053	Guide vanes, duct Condition.	/AW	PC056	Tail boom Condition, condition of antennas.	/AW
PC054	Tail rotor pitch change control rod Condition, attachment, no radial play in end- fitting.	/AW	PC057	Drive shaft fairings Attachment, condition of heat shield.	/AW
STATION 5					
PF058	NACA air inlet No obstructions (clean if necessary).	/AW			
STATION 5 – ENGINE AND ENGINE BAY					
PC059	Engine air intake Attachment: condition, condition of seals. Blanking cover removed or fitted, as necessary.	/AW	PC065	Engine magnetic plugs - No chips on aft or forward plugs (without electrical indication).	/AW
PC060	Firewall Condition, no cracks.	/AW	PC066	Engine mounts Condition, attachment.	/AW
PC061	Engine and accessories General condition, cleanliness, leak-tightness, attachment, pipes, electrical harnesses.	/AW	PC067	Engine deck drain holes No obstructions or foreign bodies.	/AW
PC062	Engine transmission deck Condition, cleanliness, no leaks.	/AW	PC068	Engine cowling Closed and locked.	/AW
PC063	Engine casing Attachment flange condition.	/AW	PC069	Nozzle Blanking cover installed or removed as necessary.	/AW
PC064	Oil system No leaks.	/AW			
STATION 5 – MAIN ROTOR SHAFT					

2022/09/10 20:03

2022/09/10 20:04

ITEM CODE NO.	TASK	INITIAL
PC070	Swashplate bearing No grease runs, no change in paint color or paint flaking.	
PC071	Scissors, swashplates, rod swivel bearings Condition, attachment, abnormal play (manual check).	
PC072	Swashplate/pitch change rod end-fitting – interfaces No impact mark or paint flaking on swashplate attachment yokes.	
PC073	Pitch change rods Condition, no radial play in end-fittings.	

ITEM CODE NO.	TASK	INITIAL
PC078	Visible part of the Starflex Star (1) arm (2): • no delamination, condition of the paint. If in doubt or damage is found (AMM 62-21-00,6-1). • Bushings (3) at the end of the arms of the STARFLEX (1) No gap between adhesive bead and bushing. If in doubt or damage is found (AMM 62-21-00,6-1).	
PC079	Spherical thrust bearings No elastomer damage, delamination, splits, blisters, extrusions or cracks (other than minor and unchanging surface irregularities), elastomer protuberance at the laminated area/small reinforcing structure interface.	
PC080	Frequency adapters (PRE MOD 076232) If in doubt or damage is found (AMM 62-21-00,6-4). No elastomer damage, delamination, splits, blisters, extrusions or cracks (other than minor and unchanging surface irregularities). If in doubt or damage is found (AMM 62-21-00,6-7).	
PC081	Ventilated frequency adapters (POST MOD 076232) No elastomer damage, delamination, splits, blisters, extrusions or cracks (other than minor and unchanging surface irregularities). If in doubt or damage is found (AMM 62-21-00,6-7). Check that ventilation holes are not obstructed (on both sides). On adapters fitted with drilled bush 365A31-1018-21 or 22, ensure lockwire is in place in holes on trailing edge side.	

ITEM CODE NO.	TASK	INITIAL
PC074	Rotor shaft, all visible parts particularly under the – hub Paint condition, no cracks, scratches, blistering, corrosion nor tool marks.	
PC075	1/4 turn non-electrical magnetic plug of flared housing. Remove 1/4 turn plug, if there are metal particles, apply (AMM 05-50-00,6-1), if there are no metal particles, do a second check, if there are metal particles, apply (AMM 05-50-00,6-1), if there are no metal particles, install the 1/4 turn plug.	

ITEM CODE NO.	TASK	INITIAL
PC082	Self-lubricating ball joints No debris or play.	
PC083	Anti-vibrator Attachment.	



ITEM CODE NO.	TASK	INITIAL
PC076	MAIN ROTOR HEAD Attachment, general condition.	
PC077	STARFLEX Star (1): no delamination (splinters).	

ITEM CODE NO.	TASK	INITIAL
PC084	MAIN ROTOR BLADES Attachment, general condition of the skin (lower surface, upper surface and trailing edge), trim tabs and polyurethane protective strips. Visually check for no delamination, scratches, cracks, impacts or distortions. No erosion holes on leading edge, no gaps or impacts. Condition of the electrical bonding braid. If in doubt or if a defect is found (AMM 62-11-00,6-1).	
PC085	Right cargo door Opening, condition, attachment points, no abnormal play.	

2022/09/10 20:04

ITEM CODE NO.	TASK	INITIAL
STATION 5 – MAINTENANCE AREA		
PC086	Fuses All fuses set.	
PC087	Right cargo door Closed and locked.	
PC088	GPU receptacle, access flap Closed or GPU connected, as applicable.	
PC089	RH MGB cowling Opening, condition of locking systems, no abnormal play.	
PC090	Transmission deck Cleanliness.	
PC091	MGB support bars Condition, attachment, swivelling.	
PC092	Oil cooler, fan and pipes Condition, no leaks, fan attachment, fan blade condition.	
PC093	Servos Attachment, no leaks or cracks.	
PC094	Hydraulic system (RH side) Attachment, pipes condition, no leaks, filter clogging indicator retracted.	
PC095	Hydraulic system reservoirs Levels, no leaks.	
STATION 5 – CABIN INTERIOR		
PC105	Cabin General cleanliness.	
PC106	Seats Condition, attachment points.	
PC107	Belts/harnesses General condition, no wear, visible damage to the strap and reel in good working order.	

ITEM CODE NO.	TASK	INITIAL
PC096	Engine oil tank Oil level, pipes condition, no leaks.	
PC097	Electrical harnesses Condition, attachment.	
PC098	Gimbal ring assembly Fitting, safety pins in place and locked.	
PC099	RH side MGB cowling Closed and locked.	
PC100	Landing gear Condition of crosstubes, skids, wear resistant plates, footstep attachment.	
PC101	All lower central fairings Closed and locked.	
PC102	RH cabin access doors Condition, attachment, locking, no abnormal play.	
PC103	Front door jettison system Condition, no cracks (especially at the link).	
PC104	Subdoor Condition, attachment.	
PC110	Fire extinguisher Attached - Checked.	
PC111	Fuses All set.	
PC112	Battery switch ON, check battery voltage.	

2022/09/10 20:04

ITEM CODE NO.	TASK	INITIAL	ITEM CODE NO.	TASK	INITIAL
PC108	Belt attachments General condition, wear, loosening and locking.	/mr	PC113	VEMD Check flights of the day reports: (MAINT mode, FLIGHT REPORT page) VEMD flight times, Ng and Nf cycles: check written in white characters and above 0, Check advisory messages FAILURE or OVERLIMIT DETECTED, Record flights of the day data in aircraft and engine log-books.	/mr
PC109	Door Jettison system Checked - Plastic guard in place.	/mr	PC114	Battery switch OFF.	/mr
OPTIONAL EQUIPMENT – ENGINE SAND FILTER					
PC1115	With the engine cowling closed, check the following: - the condition of the filter support cowling, - the external condition of the filter, - the condition and cleanliness of the separator tubes, - the condition of the ejector nozzles.	N/A	PC116	Open the engine cowling and check the following: - the condition of the particle separator unit, - the condition and cleanliness of the separator tubes, - the condition of the elbow union, - the condition of the pipes, - the condition of the air manifold, - the tightness of the air intake, - the internal cleanliness of the air manifold, - the condition and attachment of the electro-valve with hoses and P2 supply union.	N/A
			PC117	Close the engine cowling.	/mr
OPTIONAL EQUIPMENT – AIR CONDITIONING					
PC118	Open the MGB left cowling.	/mr	PC120	If a leak is detected at the MGB intake: replace the MGB intake seal (AMM 63-21-00,8-1).	/mr
PC119	Check the condition of the air conditioning compressor drive belt (AMM 21-51-02,6-2) If an oil leak is detected at the MGB.	/mr	PC121	Close the MGB left cowling.	/mr
OPTIONAL EQUIPMENT – INSTALLATION OF WINDSHIELD WIPERS					

ITEM CODE NO.	TASK	INITIAL	ITEM CODE NO.	TASK	INITIAL
PC122	Check the condition of the installation (no corrosion, impacts..).		PC124	Check the condition of the wiper and in particular, the good condition of the scraper.	N/A
PC123	Check the condition of attachments.				
*** End of P Check Items ***					

RETURN TO SERVICE

The work recorded above has been carried out in accordance with the requirements of the Civil Aviation Safety Regulation for the time being in force and in that respect the aircraft is consider fit for Release to Service.

Name : _____ Stamp : _____

Signature : _____ Place/Date : SP3 / 10-9-22

2022/09/10 20:05

2022/09/10 20:05

smartaviation

Additional Work Sheet
10 Hours // 7 Days &
ADD Inspection

Aircraft Registration: **PK-SNX**

Parts Used Sheet

~~WO# Nr.~~ **WO/210-SNX/IX/2022**

Special Tool Used

No.	Description	Due Date	Engineer
		none	

Part Used

Date	Part Nr.	Serial Nr.	Description	Qty	Engineer
			none		

2022/09/10 20:06

smartaviation

Additional Work Sheet
10 Hours // 7 Days &
ADD Inspection

Aircraft Registration: **PK-SNX**

WO# Nr: **WO/210-SNX/IX/2022**

Parts Used Sheet

Part Used

Date	Part Nr.	Serial Nr.	Description	Quantity	Engineer
			none		