



PT. SMART CAKRAWALA AVIATION

WORK ORDER

Form: SCA/MTC/030

Subject : Inspection Document 06 & Add. Task due at 3000 Hours.	No.	WO/076-SNV/IX/2022
	Date	1 S 2022
	A/C Reg.	PK-SNV C208B-5551
Reference : MP C208B REV. 12	Prepared By	TS
	Checked By	CI
	Approved By	TM

To : Engineer In Charge

Description :

1. Perform Inspection Document 06 & Add Task due at 3000 Hours.
2. Make an entry in Maintenance Log.
3. Return the Completed Work Order and Form to PPC.

#If any finding, please close the routine card, and transferred to inspection card.

Additional Work : - NIL -


Compliance Statement - CARRIED OUT -	Sign & Date Company Lic. No.: SCA 021 06-10-2022 (Engineer In Charge) RIZAL GHARAU	Signature (Technical Manager)
--	--	--------------------------------------

AIRCRAFT CHECK WORK SUMMARY
(Form: SCA/MTC/051)

DATE OF ISSUED	JO/WO #	TYPE OF MAINTENANCE	DATE OF ACCOMPLISHED		
19 Sept 2022	WO/076-SNV/IX/2022	Insp. Doc.06 and Add Task	06-10-2022		
A/C Type		Mfg. Serial Number	A/C Registration		
C208B		C208B-5551	PK-SNV		
AIRCRAFT DATA					
Subject	Pos #	Serial Number (SN)	TTSN/TCSN		
Engine	#1	PCE-VA0723	2996:37/5021		
	#2	-			
Propeller/Rotor	#1	1801158	2996:37/5021		
	#2	-			
Landing Gear	NLG		2996:37/5021		
	LH MLG		2996:37/5021		
	RH MLG		2996:37/5021		
PACKAGE COVERED					
No	Subject	Qty	Remark		
1	Non-Routine Card	-			
2	Inspection Card	1	✓		
3	Work Order	1	✓		
4	Summary Inspection List	1	✓		
5	Material and Tool List	-			
6	Escalation form	-			
7	CRS (SMI / Unscheduled Maintenance)	1	✓		
INSPECTION CARD (IC) LIST (Finding during maintenance)					
No	Taskcard Ref	Subject	Status		Name/ Sign & Stamp
			Open	Close	
<u>IC-001</u>	32-40-00	REPLACED LH BRAKE LINING		✓	PIPPAL-G AU 
<u>IC-002</u>	32-40-00	REPLACED RH BRAKE LINING		✓	PIPPAL-G AU 
<u>IC-003</u>	74-20-00	REPLACED IGNITER		✓	PIPPAL-G AU 
<u>IC-004</u>					
<u>IC-005</u>					
<u>IC-006</u>					

<u>IC-007</u>					
<u>IC-008</u>					
<u>IC-009</u>					
<u>IC-010</u>					
<u>IC-011</u>					
<u>IC-012</u>					
<u>IC-013</u>					
<u>IC-014</u>					
<u>IC-015</u>					

Prepared by :
Technical Support



Hani

Checked by :
Chief Maintenance



Dodit

Verified by :
Chief Inspector



Yanuar

Approved by :
Technical Manager



Istiono



SUMMARY INSPECTION ITEMS (Form: SCA/MTC/050)

WO Ref: WO/076-SNV/IX/2022

NO.	TASK CARD NO.	DESCRIPTION	DATE	EST MHR	NAME	STAMP
1	B03	PT6A-140 ENGINE GROUND RUN PERFORMANCE	06/22 /10		RIDZAL.G	
2	CHAPTER 12	INSPECTION DOCUMENT 06	06/22 /10		RIDZAL.G	
3	CHAPTER 51	ENGINE PT6A-140 100 HOUR INSPECTION/ MINOR INSPECTION	06/22 /10		RIDZAL.G	
4	CHAPTER 52	ENGINE PT6A-140 200 HOUR INSPECTION	06/22 /10		RIDZAL.G	
5	CHAPTER 53	ENGINE PT6A-140 200 HOUR / 6 MONTHS INSPECTION	06/22 /10		RIDZAL.G	
6	CHAPTER 55	ENGINE PT6A-140 600 HOUR INSPECTION	06/22 /10		RIDZAL.G	
7	CHAPTER 56	ENGINE PT6A-140 1000 HOUR INSPECTION	06/22 /10		RIDZAL.G	
8	SCA/MTC/0 23	EMERGENCY EQUIPMENT CHECK	05/22 /10		RIDZAL.G	



PT. SMART CAKRAWALA AVIATION

CERTIFICATE RETURN TO SERVICE

SCHEDULED MAINTENANCE INSPECTION (CRS-SMI)

A/C TYPE : CESSNA C208B	TTSN : 2936:37
A/C REG : PK-SNV	TCSN : 5021
MSN : C208B-5551	DATE : 05-10-22

TYPE OF INSPECTION : INSPECTION DOCUMENT 06 & ADD TASK
 DUE AT : 3000 HOURS
 REFF : MP C208B REV. 12

EXCEPTION

- NO EXCEPTION -

AUTHORIZED PERSON

I hereby certify that this aircraft has been maintained accordance with CASR and Maintenance Program.
 Aircraft safe and airworthy for flight

NAME	CAT	AMEL/OTR NO	SIGN&STAMP	DATE
RIZDAL GRAZALI	AIRFRAME & POWER PLANT	3694 SCA 021	 	06/2022 10
	EIRA			

THE NEXT DUE TYPE OF INSPECTION : 100 HOURS
 DUE AT : 3100 HOURS

Form: SCA/MTC/049

		INSPECTION CARD (Form: SCA/MTC/048)			TECHNICAL DEPARTMENT		
1. CARD #		2. JO/WO #		3. ORIGINATOR		4. CARD REF	5. DATE
1C-001		WB/076-SNV/1K/2022				D121001	06-10-2022
6. A/C REG/MSN		7. A/C TYPE		8. TRADE		12. VENDOR ORDER #	
PK-SNV/5551		C208B EX		MLG			
9. ZONE		10. STA		11. MTC TYPE			
MLG		KOE					
13. DESCRIPTION/DEFECT-IF FINDING OF CPCP INSPECTION, PLEASE COMPLETE SET. 20 LH BRAKE LINING ON PRESSURE PLATE FOUND WORN OUT						14 PPC/ENG	15 DATE
							06/22 10
16. CORRECTIVE ACTION REPLACED LH BRAKE LINING WITH NEW ONE. 1AW C208B MM 32-40-00 Performed at A/C TT: 2006:37 A/C TC/LDG: 9021						17 MECH	18 ENG. LIC
							06/22 10
20. CORROSION INFORMATION							
LOCATION				CAUSE OF DAMAGE			
CORROSION ☐ Isolated ☐ Widespread CORROSION LVL ☐ 1 ☐ 2 ☐ 3 PROPOSED ACTION ☐ Doublers ☐ Others ☐ Blocked Drain ☐ Wet Insulation Blanket ☐ Other				☐ Environment ☐ Internal Leakage ☐ Chemical Spill ☐ LAV/Galley Spill			
21. If the defect is RII, Please Sign this card finally by RII Inspector						INSP	DATE
NOTICE OF INSPECTOR							
22. PARTS REQUIRED							
PART DESCRIPTION	PART NO	QTY	SERIAL NO		STATUS		
			ON	OFF	CLOSE	OPEN	
BRAKE LINING	056-15300	4	-	-	✓		
23. TOOLS REQUIRED							
DESCRIPTION	PART NO. / MODEL	NEXT CALIBRATION DATE		STATUS			
TORQUE WRENCH							

		INSPECTION CARD (Form: SCA/MTC/ 048)			TECHNICAL DEPARTMENT	
1. CARD #	2. JO/WO #	3. ORIGINATOR	4. CARD REF	5. DATE		
1C-002	W01076-SNV/14/2022		D121005	06-10-2022		
6. A/C REG/MSN	7. A/C TYPE	8. TRADE	12. VENDOR ORDER #			
PK-SNV/5551	C208B EX	MLG				
9. ZONE	10. STA	11. MTC TYPE				
MLG	KOE					

13. DESCRIPTION/DEFECT-IF FINDING OF CPCP INSPECTION, PLEASE COMPLETE SET. 20	14	15
	PPC/ENG	DATE
RH BRAKE LINING FOUND WORN OUT		06/22/10

16. CORRECTIVE ACTION	17	18	19
	MECH	ENG. LIC	DATE
REPLACED RH BRAKE LINING ON PRESSURE PLATE WITH NEW ONE. 1AW C208B MM 32-40-00 Performed at A/C TT: 2456:37 A/C TC/LDG: 5021			06/22/10

20. CORROSION INFORMATION			
LOCATION	CAUSE OF DAMAGE		
	☐ Environment		
	☐ Internal Leakage		
CORROSION ☐ Isolated ☐ Widespread	☐ Chemical Spill		
CORROSION LVL ☐ 1 ☐ 2 ☐ 3	☐ LAV/Galley Spill		
PROPOSED ACTION ☐ Doublers	☐ Blocked Drain		
☐ Others	☐ Wet Insulation Blanket		
	☐ Other		
21. If the defect is RII, Please Sign this card finally by RII Inspector		INSP	DATE
NOTICE OF INSPECTOR			

22. PARTS REQUIRED						
PART DESCRIPTION	PART NO	QTY	SERIAL NO		STATUS	
			ON	OFF	CLOSE	OPEN
BRAKE LINING	066-15300	4	✓	-	✓	

23. TOOLS REQUIRED			
DESCRIPTION	PART NO./MODEL	NEXT CALIBRATION DATE	STATUS
TORQUE WRENCH			OK
GENERAL TOOLS			OK

		INSPECTION CARD (Form: SCA/MTC/048)		TECHNICAL DEPARTMENT	
---	--	---	--	-------------------------	--

1. CARD #	2. JO/WO #	3. ORIGINATOR	4. CARD REF	5. DATE	
1C-003	NO/07/2022		F742002	06-0-2022	
6. A/C REG/MSN	7. A/C TYPE	8. TRADE	12. VENDOR ORDER #		
PK-SNV/5551	C208B EX				
9. ZONE	10. STA	11. MTC TYPE			
ENGINE	10E				

13. DESCRIPTION/DEFECT-IF FINDING OF CPCP INSPECTION, PLEASE COMPLETE SET. 20	14 PPC/ENG	15 DATE
LH SIDE IGNITER WAS WORN OUT		06/10/2022

16. CORRECTIVE ACTION	17 MECH	18 ENG. LIC	19 DATE
REPLACED LH IGNITER WITH A NEW ONE 1AW C208B MM 74-20-00 Performed at A/C TT: 2996:37 A/C TC/LDG: 5021			06/10/2022

20. CORROSION INFORMATION					
LOCATION		CAUSE OF DAMAGE			
		☐ Environment			
		☐ Internal Leakage			
CORROSION ☐ Isolated ☐ Widespread		☐ Chemical Spill			
CORROSION LVL ☐ 1 ☐ 2 ☐ 3		☐ LAV/Galley Spill			
PROPOSED ACTION ☐ Doublers		☐ Blocked Drain			
☐ Others		☐ Wet Insulation Blanket			
		☐ Other			

21. If the defect is RII, Please Sign this card finally by RII Inspector		INSP	DATE
NOTICE OF INSPECTOR			

22. PARTS REQUIRED						
PART DESCRIPTION	PART NO	QTY	SERIAL NO		STATUS	
			ON	OFF	CLOSE	OPEN
IGNITER	CH34055	1	—	—	✓	

23. TOOLS REQUIRED			
DESCRIPTION	PART NO. / MODEL	NEXT CALIBRATION DATE	STATUS
GENERAL TOOLS			OK
TORQUE WRENCH			OK



MAINTENANCE PROGRAM CESSNA C208/C208B

Appendix B03 – PT6A-140 Engine Run Performance Sheet

Reg. Mark : PK - SNV

WO/FML No. : WO/076-SNV/IX/2022

PRE – INSPECTION	
Location	KUPANG
Date	05-10-2022
Cycle	
Filed Barometric	29.80
OAT	35°C
Altitude	335

POST – INSPECTION	
Location	KUPANG
Date	06-10-2022
Cycle	
Filed Barometric	29.85 IN.HG
OAT	37°C
Altitude	335

PRE – INSPECTION		
	Target	Actual
Tq		2397
Np		1880
ITT	°C	841 °C
Ng	%	101.5 %
Wf		540
Oil Press		91 °C
Oil Temp		64 °C
Start Temp		735 °C

POST – INSPECTION		
	Target	Actual
Tq		2397
Np		1890
ITT	°C	840 °C
Ng	%	101.5 %
Wf		556
Oil Press		91 °C
Oil Temp		64 °C
Start Temp		714 °C

Engine Run Up Checks							
Inertial	☒	EPL	☒	OVG	☒	Stby Alt	☒
BOV	☒	Brake	☒	Random	☒		
NOTE: 1. Brake system at Torque 2000 ft-lbs. 3. EPL check can't exceed 4% Ng per second. 5. Low idle at 55.5 - 57% 40Amps. 2. Inertial Separator at Torque 400 ft-lbs. 4. Standby Alt at 80% Ng. 6. High idle at 64 - 66% Ng 40Amps							

Engine Performance Target Table (Cessna C208B EX)

OAT (°C)	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41
Tq (ft.lbs)	2397	2397	2397	2397	2397	2397	2397	2397	2397	2397	2397	2397	2397	2397	2397
Np	1900	1900	1900	1900	1900	1900	1900	1900	1900	1900	1900	1900	1900	1900	1900
ITT (°C)	835	837	839	841	841	841	841	841	841	842	843	844	846	846	846
Ng (%)	102.7	102.7	102.7	102.7	102.7	102.7	102.7	102.6	102.6	102.6	102.6	102.6	102.6	102.6	102.5
WF (PPH)	578	578	578	578	578	578	578	570	565	565	560	560	555	548	548

Note:

1. Make sure that inertial separator in normal condition, no bleed air extracted from the engine and air condition OFF.
2. This table only applies to altitude 0-500 feet MSL. For higher altitude, refer to EMM 72-00-00.
3. Max fuel flow is 580 lb/hr fuel flow is not more than 15 lbs/hr higher than the value shown in table.
4. If parameters are outside the target performance table to EMM chapter 71-00-00.

REMARKS:

- ALL ENGINE PARAMETER
WITHIN LIMIT -

PERFORMED BY

Name	Sign & Stamp	Date	Location
PIDAL - G		06/10/2022	KUPANG



MAINTENANCE PROGRAM **CESSNA C208/C208B**

Chapter 12 – Inspection Document 06

Reg. Mark : PK-SNV
MSN : C208B-5551
TSN / CSN : 7996:37/5021

Date : 05-10-2022
Station : KUPANG
WO No. : WO/076-SNV/IX/2022

ITEM CODE NO.	ZONE	TASK	SIGNATURE	
			SIGN	STAMP
A110001	ALL	Interior and Exterior Placard and Decal Detailed Inspection Task 11-00-00-220		
D121001	121	Brake System Servicing Task 12-10-01-610		
D121003	710	Shimmy Damper Servicing Task 12-10-01-611	N/A	N/A
C122101	700	Landing Gear Lubrication Task 12-21-03-640		
B236001	343 375 376 571 671	Static Discharge System Functional Check Task 23-60-00-720		
A255101	251 252 255 256 257 258	Cargo Nets Detailed Inspection Task 25-51-00-220	N/A	N/A
C270001	215 216 226 373 374 503 525 603 625	Flight Controls Lubrication Task 27-00-00-640		
B273101	211 212 503	Stall Warning System Operational Check Task 27-31-00-710		
C275001	525 527 625 627	Flap Tracks and Rollers Lubrication Task 27-50-00-640		
B281001	575 675	Fuel Vent Line Float Valve Operational Check Task 28-10-03-710		
A281001	521 621	Fuel Filler Assembly Detailed Inspection Task 28-10-01-220		
B301003	122 AUX	Bleed Air Pressure Regulator Functional Check (without TKS and not incorporating CAB93-2) Task 30-10-00-720		
B322001	710	Shimmy Damper Functional Check Task 32-20-02-720		

MAINTENANCE PROGRAM CESSNA C208/C208B

Chapter 12 – Inspection Document 06

ITEM CODE NO.	ZONE	TASK	SIGNATURE	
			SIGN	STAMP
B341101	AUX	Pitot Tube Heaters Operational Check Task 34-11-00-710		
A353001	256	Oxygen Mask Detailed Inspection Task 35-30-00-220		
B761003	AUX	Emergency Power Lever Annunciator Light (EPL) Operational Check Task 76-10-01-710		
*** End of Inspection Document 06 Items ***				

PERSONNEL PARTICIPATING IN THIS INSPECTION			
NAME	POSITION	SIGNATURE	LICENSE NUMBER
RIZDAL GHAZAL	ENGINEER		9684
LEGIYANTO F.	MECHANIC		

RETURN TO SERVICE

The work recorded above has been carried out in accordance with the requirements of the Civil Aviation Safety Regulation for the time being in force and in that respect the aircraft is consider fit for Release to Service.

Name : RIZDAL GHAZALI Stamp : 
Signature :  Place/Date : KUPANG, 06-10-2017



MAINTENANCE PROGRAM CESSNA C208/C208B

Chapter 51 – Engine PT6A-140 100 Hours/Minor Inspection

Reg. Mark	: PK - SNV	Date	: 06-10-2022
MSN	: C208B-5551	Station	: KUPANG
TSN / CSN	: 2996:37/5021	WO No.	: WO/076-SNV/IX/2022

ITEM CODE NO.	ZONE	TASK	SIGNATURE	
			SIGN	STAMP
F710001	130	Do a check of the FCU manual override system for static operation. For the engines installed with a manual override system only.		
F710003	130	Do a compressor performance recovery wash		
F720000	130	Do a visual inspection of the Control Linkages and wiring.		
F720001	130	Do a visual inspection of the engine exhaust duct welds.		
F720002	130	Do a visual inspection of the engine exhaust duct for cracks.		
F720003	130	Do a visual inspection of the gas generator case and the center fireseal.		
F720004	130	Do a visual inspection of the rear fireseal mounting ring.		
F722001	130	Do a visual inspection of the air inlet screen.		
F723000	130	Do a visual inspection with a mirror or a borescope inspection of the First-stage Compressor Rotor and the inlet case for corrosion		
F725005	130	Do a detailed inspection of the turbine exhaust duct.		
F731002	130	Do a check for the fuel pump installation and leaks.		
F731003	130	Do a check of the oil-to- fuel heater installation		
F731035	130	Do a visual Inspection of the Fuel - Oil Heat Exchanger Fuel Filter Element (CLEANING / REPLACEMENT) P/N OFF: <u>AN6235-3A</u> P/N ON: <u>AN6235-3A</u>		



MAINTENANCE PROGRAM **CESSNA C208/C208B**

Chapter 51 – Engine PT6A-140 100 Hours/Minor Inspection

ITEM CODE NO.	ZONE	TASK	SIGNATURE	
			SIGN	STAMP
F731006	130	Do a check of the drain valve for installation and leaks		
		NOTE: There is no need to remove the drain valve if there is no leaks.		
F731007	130	Do a check of the flow divider for installation and leaks.		
F731008	130	Do a visual inspection of the P3 filter and drain valve.		
F731015	130	Do a visual inspection of Fuel Pump outlet filter. (CLEANING / REPLACEMENT) P/N OFF: <u>AN6235-3A</u> P/N ON: <u>AN6235-3A</u>		
F731018	130	Clean or replace the P3 filter based on condition, service experience or environment. Note: If corrossions are found, replace filter.		
F732001	130	Do a check of the FCU for installation, linkages and pneumatic tubes.		
F792000	130	Inspect and clean oil filter for debris.		

PERSONNEL PARTICIPATING IN THIS INSPECTION			
NAME	POSITION	SIGNATURE	LICENSE NUMBER
RIDZAL GHAZALI	ENGINEER		5694
LEGIYAND F.	MECHANIC		

RETURN TO SERVICE			
The work recorded above has been carried out in accordance with the requirements of the Civil Aviation Safety Regulation for the time being in force and in that respect the aircraft is consider fit for Release to Service.			
Name	: RIDZAL GHAZALI	Stamp	:
Signature	:	Place/Date	: KUPANG, 06-10-22

MAINTENANCE PROGRAM **CESSNA C208/C208B**

Chapter 52 – Engine PT6A-140 200 Hours Inspection

Reg. Mark : PK - SNV Date : 06-10-2022
 MSN : C208B-5551 Station : KUPANG
 TSN / CSN : 2996:37/5021 WO No. : WO/076-SNV/IX/2022

ITEM CODE NO.	ZONE	TASK	SIGNATURE	
			SIGN	STAMP
F793001	130	Do a visual inspection of the chip detector for debris.		
*** End of Engine PT6A-140 200 Hours Inspection Items ***				

PERSONNEL PARTICIPATING IN THIS INSPECTION			
NAME	POSITION	SIGNATURE	LICENSE NUMBER
RIDZAL GHAZALI	ENGINEER		9694
LEGIYAND F.	MECHANIC		

RETURN TO SERVICE

The work recorded above has been carried out in accordance with the requirements of the Civil Aviation Safety Regulation for the time being in force and in that respect the aircraft is consider fit for Release to Service.

Name : RIDZAL GHAZALI Stamp : 
 Signature :  Place/Date : KUPANG, 06-10-2022



MAINTENANCE PROGRAM CESSNA C208/C208B

Chapter 53 – Engine PT6A-140 200 Hours or 6 Months Inspection

Reg. Mark : PK - SNV Date : 06-11-2022
MSN : C208B-5551 Station : KUPANG
TSN / CSN : 2996137/5021 WO No. : WO/076-SNV/IX/2022

ITEM CODE NO.	ZONE	TASK	SIGNATURE	
			SIGN	STAMP
F793000	130	Do a visual inspection of the AGB internal scavenge oil pump inlet screen		
*** End of Engine PT6A- 140 200 Hours or 6 Months Inspection Items ***				

PERSONNEL PARTICIPATING IN THIS INSPECTION			
NAME	POSITION	SIGNATURE	LICENSE NUMBER
RIDZAL GHAZALI	ENGINEER		9694
LEGIYANDU F.	MECHANIC.		

RETURN TO SERVICE

The work recorded above has been carried out in accordance with the requirements of the Civil Aviation Safety Regulation for the time being in force and in that respect the aircraft is consider fit for Release to Service.

Name : RIDZAL GHAZALI Stamp :
Signature : Place/Date : KUPANG, 06-11-2022



MAINTENANCE PROGRAM **CESSNA C208/C208B**

Chapter 55 – Engine PT6A-140 600 Hours Inspection

Reg. Mark : PK - SNV Date : 06-10-2022
 MSN : C208B-5551 Station : KUPANG
 TSN / CSN : 2996132/5021 WO No. : WO/076-SNV/IX/2022

ITEM CODE NO.	ZONE	TASK	SIGNATURE	
			SIGN	STAMP
F731005		Do a visual inspection of the fuel pump inlet screen.		
		NOTE: On new aircraft, check filter after each flight until no contamination is evident. Do a check after first flight or ground run whenever any component upstream of filter is replaced.		
F753001		Do a visual inspection of the compressor bleed valve.		
F793002		Do a functional check of the chip detector.		

PERSONNEL PARTICIPATING IN THIS INSPECTION			
NAME	POSITION	SIGNATURE	LICENSE NUMBER
RIDZAL GHAZALI	ENGINEER		9694
LEGIYAND F.	MECHANIC		

RETURN TO SERVICE

The work recorded above has been carried out in accordance with the requirements of the Civil Aviation Safety Regulation for the time being in force and in that respect the aircraft is consider fit for Release to Service.

Name : RIDZAL GHAZALI Stamp :
 Signature : Place/Date : KUPANG, 06-10-2022

MAINTENANCE PROGRAM CESSNA C208/C208B

Chapter 56 – Engine PT6A-140 1000 Hours Inspection

Reg. Mark : PK - SNV Date : 06-10-2022
MSN : C208B-5551 Station : KUPANG
TSN / CSN : 2996:37/5021 WO No. : WO/076-SNV/IX/2022

ITEM CODE NO.	ZONE	TASK	SIGNATURE	
			SIGN	STAMP
F731028	130	Replace the P3 filter. P/N OFF: <u>WF336238</u> P/N ON: <u>WF336238</u>		
F792001	130	Remove and discard the oil filter element. Install a new oil filter element. P/N OFF: <u>3034393 WFC</u> P/N ON: <u>3034353 WFC</u>		
*** End of Engine PT6A-140 1000 Hours Items ***				

PERSONNEL PARTICIPATING IN THIS INSPECTION			
NAME	POSITION	SIGNATURE	LICENSE NUMBER
RIDZAL GHAZALI	ENGINEER		3634
LEGIYANTO F.	MECHANIC		

RETURN TO SERVICE

The work recorded above has been carried out in accordance with the requirements of the Civil Aviation Safety Regulation for the time being in force and in that respect the aircraft is consider fit for Release to Service.

Name : RIDZAL GHAZALI Stamp : 
Signature :  Place/Date : KUPANG, 06-10-2022

	EMERGENCY EQUIPMENT LIST INSPECTION & MONITOR	PT. SMART CAKRAWALA AVIATION DEPARTMENT TEKNIK Form: SCA/MTC/023
---	--	---

DATE : 05-10-2022	A/C REG : PK-SNV
A/C TYPE : C208B EX	CHECKER : RIDZAL . G SIGN: 


No.	Description	P/N	S/N	Next Insp.	Remarks
1	Pilot Life Vest	P01202-201	19080030099	01 Aug 2029	GOOD
2	Co-Pilot Life Vest	P01202-201	19080030019	01 Aug 2029	GOOD
3	Pax Life Vest				
4	Pax Life Vest				
5	Pax Life Vest				
6	Pax Life Vest				
7	Pax Life Vest				
8	Pax Life Vest				
9	Pax Life Vest				
10	Pax Life Vest				
11	Pax Life Vest				
12	Pax Life Vest				
13	Firt Aid Kit	FL 220	0919-1381	01 JAN 2022	GOOD
14	Crash Axe Installed	NPN	NPN	ON CONDITION	GOOD
15	Fire Extinguisher	C 352	F-60589867	30 OCT 2022	GOOD
16	Life Raft (If Installed)				
17	Survival Kit (If Installed)	FL 220	5714	NOV 2022	GOOD
OTHERS					



Additional Work Sheet
Inspection Doc. 06 & Add Task

Parts Used Sheet

[illegible]



WO# Nr: WO/076/SNV/IX/2022

Parts Used Sheet

Part Used

[illegible]