



Photo of First Stage Compressor 3rd Quadrant

Photo of First Stage Compressor 4th Quadrant


3

Perform inspection of Combustion Chamber Liner Assembly.

Defects:

RESULT SATISFACTORY FOUND NO DEFECT

SIGN

STAMP






Photo of Combustion Chamber 1st Quadrant

Photo of Combustion Chamber 2nd Quadrant

Photo of Combustion Chamber 3rd Quadrant

Photo of Combustion Chamber 4th Quadrant




DOCUMENT FORM BORESCOPE INSPECTION FORM

Page | 5

Photo of CT-Blades Trailing Edge 3rd Q



Photo of CT-Blades Trailing Edge 4th Q



7

Perform inspection of PT-Blades

Defects:

RESULT SATISFACTORY FOUND NO DEFECT

SIGN

STAMP



Photo of PT-Blades 1st Q



Photo of PT-Blades 2nd Q






Photo of PT-Blades 3rd Q



Photo of PT-Blades 4th Q





4	Perform Inspection of CT-Stator assembly. <u>Defects:</u> RESULT SATISFACTORY FOUND NO DEFECT	SIGN	STAMP
			
Photo of CT Stator 1st Quadrant  WAT120D/NF V94 ZOOM X1.0 BRT 6 2023/09/08 22:20 PK-SNH PCE-VA0662 OLYMPUS Photo of CT Stator 2nd Quadrant  WAT120D/NF V94 ZOOM X1.0 BRT 6 2023/09/08 22:22 PK-SNH PCE-VA0662 OLYMPUS			
Photo of CT Stator 3rd Quadrant  WAT120D/NF V94 ZOOM X1.0 BRT 6 2023/09/08 22:21 PK-SNH PCE-VA0662 OLYMPUS Photo of CT Stator 4th Quadrant  WAT120D/NF V94 ZOOM X1.0 BRT 6 2023/09/08 22:21 PK-SNH PCE-VA0662 OLYMPUS			
5	Perform inspection of CT-Blades and shroud segments. <u>Defects:</u> RESULT SATISFACTORY FOUND NO DEFECT	SIGN	STAMP
			



**DOCUMENT FORM
BORESCOPE INSPECTION
FORM**


Page | 6

		SIGN	STAMP
8	Install fuel manifold adapter(s) (Ref. 73-10-05).		
9	Perform fuel leak check post fuel nozzle installation		

BORESCOPE PERFORMED BY

Name: Agus Sulaeman

Signature:



Stamp:

