

Reg. Mark : PK-SNX

Date : 24/10/2023

MSN : 53467

Station : FBH

TSN /CSN : 969:17/2337

WO No. : WO/098-PK-SNX/X/2023

ITEM CODE NO	ZONE	TASK	SIGNATURE	
			ENGINEER SIGN & STAMP	RII SIGN & STAMP
62/21/00 /000/000 /145	62-21	Spherical bearing 57910700 (704A33633211) LB4-1231-1 (704A33633208) Check of the elastomer part. GVI AMM05-40-00,6-7	 IRWAN	N/A
62/21/00 /000/000 /185	62-21	Frequency adapter 365A31-1019-25 (-) E-4165F01 (704A33640088) E-4165F11 (704A33640100) Check of the elastomer part. Must not be mixed together. GVI AMM05-40-00,6-7	 IRWAN	N/A

PERSONNEL PARTICIPATION IN THIS INSPECTION

NAME	POSITION	SIGNATURE	LICENSE NUMBER

RETURN TO SERVICE

The work recorded above has been carried out in accordance with the requirements of the Civil Aviation Safety Regulation for the time being in force and in that respect the aircraft in the consider fit for Release to Service.

Name : IRWAN

Place/Date : FBH, 24/10/2023

Sign & Stamp : 
IRWAN

Reg. Mark : PK-SNX

Date : 24/10/2023

MSN : 53467

Station : FBH

TSN /CSN : 969:17 / 2337

WO No. : WO/098-PK-SNX/X/2023

ITEM CODE NO	ZONE	TASK	SIGNATURE	
			ENGINEER SIGN & STAMP	RII SIGN & STAMP
05/21/00 /000/000 /020	05-21	P-check VC AMM 05-40-00, 6-7	 IRWAN	N/A
05/21/00 /000/000 /030	05-21	P-check - Optional equipments Note: Maintenance operations can be carried out by an aircrew member. VC AMM 05-40-00, 6-8	 IRWAN	N/A
53/00/00 /000/000 /050	53-00	Structure Salt-laden atmosphere Rinsing and Drying. CLN AMM 12-20-00, 3-3	 IRWAN	N/A

PERSONNEL PARTICIPATION IN THIS INSPECTION

NAME	POSITION	SIGNATURE	LICENSE NUMBER

RETURN TO SERVICE

The work recorded above has been carried out in accordance with the requirements of the Civil Aviation Safety Regulation for the time being in force and in that respect the aircraft in the consider fit for Release to Service.

Name : IRWAN

Place/Date : FBH, 24/10/2023

Sign & Stamp : 