



PT. SMART CAKRAWALA AVIATION

WORK ORDER

Form: SCA/MTC/030

Subject : Inspection Doc. 06 & Add Task Due at 1000 FH.	No.	WO/022-SNA/IV/2022
	Date	07-Apr-2022
	A/C Reg.	PK-SNA C208B-5634
Reference : MP C208B REV. 10	Prepared By	TS
	Checked By	CI
	Approved By	TM

To : Engineer In Charge

Description :

1. Perform Inspection Doc. 06 & Add Task Due at 1000 FH.
2. Make an entry in Maintenance Log.
3. Return the Completed Work Order and Form to PPC.

#If any finding, please close the routine card, and transferred to inspection card.

Additional Work :

Compliance
Statement

INSPECTION DOC 06
& ADD TASK 90

Sign & Date
Company Lic. No.:

(Engineer In Charge)

17-APRIL-2022



Signature

(Technical Manager)

AIRCRAFT CHECK WORK SUMMARY
(Form: SCA/MTC/051)

DATE OF ISSUED	JOWO #	TYPE OF MAINTENANCE	DATE OF ACCOMPLISHED		
07-Apr-2022	WO/022-SNA/IV/2022	Inspection Doc. 06 & Add Task	17- APRIL 2022		
A/C Type		Mfg. Serial Number	A/C Registration		
C208B		C208B-5634	PK-SNA		
AIRCRAFT DATA					
Subject	Pos #	Serial Number (SN)	TTSN/TCSN		
Engine	#1	PCE-VA0730	991:45 / 1579		
	#2	-			
Propeller/Rotor	#1	200483	991:45 / 1579		
	#2	-			
Landing Gear	NLG		991:45 / 1579		
	LH MLG		991:45 / 1579		
	RH MLG		991:45 / 1579		
PACKAGE COVERED					
No	Subject	Qty	Remark		
1	Non-Routine Card	-			
2	Inspection Card	-			
3	Work Order	1	✓		
4	Summary Inspection List	1	✓		
5	Material and Tool List	-			
6	Escalation form	-			
7	CRS (SMI / Unscheduled Maintenance)	1	✓		
INSPECTION CARD (IC) LIST (Finding during maintenance)					
No	Taskcard Ref	Subject	Status	Name/ Sign & Stamp	
			Open	Close	
<u>IC-001</u>		RH BRAKE LINING WORN OUT		✓	M. AZIZ ANDIRA 23
<u>IC-002</u>		LH INBOARD BRAKE LINING WORN OUT		✓	M. AZIZ ANDIRA 23
<u>IC-003</u>					
<u>IC-004</u>					
<u>IC-005</u>					
<u>IC-006</u>					

<u>IC-007</u>					
<u>IC-008</u>					
<u>IC-009</u>					
<u>IC-010</u>					
<u>IC-011</u>					
<u>IC-012</u>					
<u>IC-013</u>					
<u>IC-014</u>					
<u>IC-015</u>					

Prepared by :
Technical Support

Checked by :
Chief Maintenance

Verified by :
Chief Inspector

Approved by :
Technical Manager

.....

.....

.....

.....



SUMMARY INSPECTION ITEMS (Form: SCA/MTC/050)

WO Ref: WO/022-SNA/IV/2022

NO.	TASK CARD NO.	DESCRIPTION	DATE	EST MHR	NAME	STAMP
1	B03	PT6A-140 ENGINE GROUND RUN PERFORMANCE	17-03-22	0.2 HRS	A212	
2	CHAPTER 12	INSPECTION DOCUMENT 06	17-03-22	1.5 HRS	A212	
3	CHAPTER 51	ENGINE PT6A-140 100 HOUR INSPECTION/ MINOR INSPECTION	17-03-22	2.5 HRS	A212	
4	CHAPTER 52	ENGINE PT6A-140 200 HOUR INSPECTION	17-03-22	0.4 HRS	A212	
5	CHAPTER 53	ENGINE PT6A-140 200 HOUR/6 MONTHS INSPECTION	17-03-22	0.4 HRS	A212	
6	CHAPTER 56	ENGINE PT6A-140 1000 HOUR INSPECTION	17-03-22	0.6 HRS	A212	
7	OOP34003	CONDUCT VISUAL INSPECTION FOR GSA 80/81 SERVOS	16-03-22	1.0 HRS	A212	
8	OOP34004	CONDUCT VISUAL INSPECTION AND CHECK SLIP CLUTCHES OF GSM 85A/86	16-03-22	1.0 HRS	A212	
9	SCA/MTC/0 23	EMERGENCY EQUIPMENT CHECK	16-03-22	0.4 HRS	A212	



PT. SMART CAKRAWALA AVIATION

CERTIFICATE RETURN TO SERVICE

SCHEDULED MAINTENANCE INSPECTION (CRS-SMI)

A/C TYPE : CESSNA 208B	TTSN : 991: 45
A/C REG : PK-SNA	TCSN : 1579
MSN : C208B-5634	DATE : 17-APRIL-2022

TYPE OF INSPECTION	: INSPECTION DOC. 06 & ADD TASK
DUE AT	: 1000 HOURS
REF	: MP C208B REV. 10

EXCEPTION

- NO EXCEPTION -

AUTHORIZED PERSON

I hereby certify that this aircraft has been maintained accordance with CASR and Maintenance Program.
Aircraft safe and airworthy for flight

NAME	CAT	AMEL/OTR NO	SIGN&STAMP	DATE
M. ARIZ ANDIKA	AIRFRAME & POWER PLANT	9633 / SCA 23		17-APRIL-2022
	EIRA			

THE NEXT DUE TYPE OF INSPECTION	: 100 HRS INSPECTION
DUE AT	: 1100:00 HRS

Form: SCA/MTC/049

		INSPECTION CARD (Form: SCA/MTC/ 048)		TECHNICAL DEPARTMENT	
---	--	--	--	-------------------------	--

1. CARD #	2. JOWO #	3. ORIGINATOR	4. CARD REF	5. DATE	
K-002	WO/022-SNA/10/2022	Ari Andika		17- April - 2022	
6. A/C REG/MSN	7. A/C TYPE	8. TRADE	12. VENDOR ORDER #		
PE-SNA	C208B BX				
9. ZONE	10. STA	11. MTC TYPE			

13. DESCRIPTION/DEFECT-IF FINDING OF CPCP INSPECTION, PLEASE COMPLETE SET. 20	14	15
	PPC/ENG	DATE
LH INBOARD BRAKE LINING WORN OUT		

16. CORRECTIVE ACTION	17	18	19
	MECH	ENG. LIC	DATE
REPLACED LH INBOARD BRAKE LINING WITH A NEW ONE Performed at A/C TT : 991 :45 A/C TC /LDG : 1037			17-APRIL 2022

20. CORROSION INFORMATION			
LOCATION	CAUSE OF DAMAGE		
	☐ Environment		
	☐ Internal Leakage		
CORROSION ☐ Isolated ☐ Widespread	☐ Chemical Spill		
CORROSION LVL ☐ 1 ☐ 2 ☐ 3	☐ LAV/Galley Spill		
PROPOSED ACTION ☐ Doublers	☐ Blocked Drain		
☐ Others	☐ Wet Insulation Blanket		
	☐ Other		
21. If the defect is RII, Please Sign this card finally by RII Inspector		INSP	DATE
NOTICE OF INSPECTOR			

22. PARTS REQUIRED						
PART DESCRIPTION	PART NO	QTY	SERIAL NO		STATUS	
			ON	OFF	CLOSE	OPEN
LINING	066-15300	4			✓	

23. TOOLS REQUIRED			
DESCRIPTION	PART NO. / MODEL	NEXT CALIBRATION DATE	STATUS

		INSPECTION CARD (Form: SCA/MTC/ 048)		TECHNICAL DEPARTMENT	
---	--	--	--	-------------------------	--

1. CARD #	2. JOWO #	3. ORIGINATOR	4. CARD REF	5. DATE	
IC-001	WO/022 SCA/14/2022	AZIZ ANDIKA		17- APRIL- 2022	
6. A/C REG/MSN	7. A/C TYPE	8. TRADE	12. VENDOR ORDER #		
PE-SNA	C108 B ex				
9. ZONE	10. STA	11. MTC TYPE			

13. DESCRIPTION/DEFECT-IF FINDING OF CPCP INSPECTION, PLEASE COMPLETE SET. 20	14	15
	PPC/ENG	DATE
RH BRAKE LINING WORN OUT		

16. CORRECTIVE ACTION	17	18	19
	MECH	ENG. LIC	DATE
REPLACED RH BRAKE LINING (SEA) WITH A NEW ONE Performed at A/C TT : 991:45 A/C TC/LDG : 1579			17-APRIL-2022

20. CORROSION INFORMATION			
LOCATION	CAUSE OF DAMAGE		
	☐ Environment		
	☐ Internal Leakage		
CORROSION ☐ Isolated ☐ Widespread	☐ Chemical Spill		
CORROSION LVL ☐ 1 ☐ 2 ☐ 3	☐ LAV/Galley Spill		
PROPOSED ACTION ☐ Doublers	☐ Blocked Drain		
☐ Others	☐ Wet Insulation Blanket		
	☐ Other		
21. If the defect is RII, Please Sign this card finally by RII Inspector		INSP	DATE
NOTICE OF INSPECTOR			

22. PARTS REQUIRED						
PART DESCRIPTION	PART NO	QTY	SERIAL NO		STATUS	
			ON	OFF	CLOSE	OPEN
LINING	066-15300	8			✓	

23. TOOLS REQUIRED			
DESCRIPTION	PART NO. / MODEL	NEXT CALIBRATION DATE	STATUS

Appendix B03 – PT6A-140 Engine Run Performance Sheet

Reg. Mark : PK - SNA

WO/FML No. : WO1022-SNA/10/2022

PRE – INSPECTION	
Location	TIMIKA
Date	16- APRIL - 2022
Cycle	-
Filed Barometric	1011
OAT	38 °C
Altitude	160 FT

POST – INSPECTION	
Location	TIMIKA
Date	17- APRIL - 2022
Cycle	-
Filed Barometric	1009
OAT	35 °C
Altitude	140 FT

PRE – INSPECTION		
	Target	Actual
Tq	2397	2397
Np	1900	1890
ITT	844 °C	820 °C
Ng	102.6 %	101 %
Wf	555	550
Oil Press		93 °C
Oil Temp		67 °C
Start Temp		730 °C

POST – INSPECTION		
	Target	Actual
Tq	2397	2397
Np	1900	1890
ITT	841 °C	806 °C
Ng	102.6 %	100.5 %
Wf	565	551
Oil Press		92 °C
Oil Temp		65 °C
Start Temp		710 °C

Engine Run Up Checks							
Inertial ☒	EPL ☒	OVG ☒	Stby Alt ☒	BOV ☒	Brake ☒	Random ☒	
NOTE: 1. Brake system at Torque 2000 ft-lbs. 3. EPL check can't exceed 4% Ng per second. 5. Low idle at 55.5 - 57% 40Amps. 2. Inertial Separator at Torque 400 ft-lbs. 4. Standby Alt at 80% Ng. 6. High idle at 64 - 66% Ng 40Amps							

Engine Performance Target Table (Cessna C208B EX)

OAT (°C)	27	28	29	30	31	32	33	34	(35)	36	37	(38)	39	40	41
Tq (ft.lbs)	2397	2397	2397	2397	2397	2397	2397	2397	2397	2397	2397	2397	2397	2397	2397
Np	1900	1900	1900	1900	1900	1900	1900	1900	1900	1900	1900	1900	1900	1900	1900
ITT (°C)	835	837	839	841	841	841	841	841	841	842	843	844	846	846	846
Ng (%)	102.7	102.7	102.7	102.7	102.7	102.7	102.7	102.6	102.6	102.6	102.6	102.6	102.6	102.6	102.5
WF (PPH)	578	578	578	578	578	578	578	570	565	565	560	560	555	548	548

Note:

1. Make sure that inertial separator in normal condition, no bleed air extracted from the engine and air condition OFF.
2. This table only applies to altitude 0-500 feet MSL. For higher altitude, refer to EMM 72-00-00.
3. Max fuel flow is 580 lb/hr fuel flow is not more than 15 lbs/hr higher than the value shown in table.
4. If parameters are outside the target performance table to EMM chapter 71-00-00.

REMARKS:

PERFORMED BY			
Name	Sign & Stamp	Date	Location
M. ARUL ANDIKA		17-APRIL-2022	TIMIKA


Reg. Mark	: PK - SNA	Date	: 16 APRIL 2022
MSN	: 208B-5634	Station	: TIMIKA
TSN / CSN	: 991:45 / 1579	WO No.	: WO / 022 - SNA / W / 2022

ITEM CODE NO.	ZONE	TASK	SIGNATURE	
			SIGN	STAMP
A110001	ALL	Interior and Exterior Placard and Decal Detailed Inspection Task 11-00-00-220		
D121001	121	Brake System Servicing Task 12-10-01-610		
D121003	710	Shimmy Damper Servicing Task 12-10-01-611	N/A	
C122101	700	Landing Gear Lubrication Task 12-21-03-640		
B236001	343 375 376 571 671	Static Discharge System Functional Check Task 23-60-00-720		
A255101	251 252 255 256 257 258	Cargo Nets Detailed Inspection Task 25-51-00-220		
C270001	215 216 226 373 374 503 525 603 625	Flight Controls Lubrication Task 27-00-00-640		
B273101	211 212 503	Stall Warning System Operational Check Task 27-31-00-710		
C275001	525 527 625 627	Flap Tracks and Rollers Lubrication Task 27-50-00-640		
B281001	575 675	Fuel Vent Line Float Valve Operational Check Task 28-10-03-710		
A281001	521 621	Fuel Filler Assembly Detailed Inspection Task 28-10-01-220		
B301003	122 AUX	Bleed Air Pressure Regulator Functional Check (without TKS and not incorporating CAB93-2) Task 30-10-00-720		
B322001	710	Shimmy Damper Functional Check Task 32-20-02-720		

MAINTENANCE PROGRAM **CESSNA C208/C208B**

Chapter 12 – Inspection Document 06

ITEM CODE NO.	ZONE	TASK	SIGNATURE	
			SIGN	STAMP
B341101	AUX	Pitot Tube Heaters Operational Check Task 34-11-00-710		
A353001	256	Oxygen Mask Detailed Inspection Task 35-30-00-220		
B761003	AUX	Emergency Power Lever Annunciator Light (EPL) Operational Check Task 76-10-01-710		
*** End of Inspection Document 06 Items ***				

PERSONNEL PARTICIPATING IN THIS INSPECTION			
NAME	POSITION	SIGNATURE	LICENSE NUMBER
M. Azil ANDICA	ENGINEER		9633
CDR NANA	MECHANIC		

RETURN TO SERVICE

The work recorded above has been carried out in accordance with the requirements of the Civil Aviation Safety Regulation for the time being in force and in that respect the aircraft is consider fit for Release to Service.

Name : M. Azil ANDICA Stamp : 

Signature :  Place/Date : TIMIKA / 17 - APRIL - 2022

Chapter 51 – Engine PT6A-140 100 Hours/Minor Inspection

Reg. Mark	: PK - <u>SNA</u>	Date	: <u>17 April 2022</u>
MSN	: <u>208B-5634</u>	Station	: <u>TIMIKA</u>
TSN / CSN	: <u>991:45 / 1579</u>	WO No.	: <u>WO/022-SNA / IV / 2022</u>

ITEM CODE NO.	ZONE	TASK	SIGNATURE	
			SIGN	STAMP
F710001	130	Do a check of the FCU manual override system for static operation. For the engines installed with a manual override system only.		
F710003	130	Do a compressor performance recovery wash		
F720000	130	Do a visual inspection of the Control Linkages and wiring.		
F720001	130	Do a visual inspection of the engine exhaust duct welds.		
F720002	130	Do a visual inspection of the engine exhaust duct for cracks.		
F720003	130	Do a visual inspection of the gas generator case and the center fireseal.		
F720004	130	Do a visual inspection of the rear fireseal mounting ring.		
F722001	130	Do a visual inspection of the air inlet screen.		
F723000	130	Do a visual inspection with a mirror or a borescope inspection of the First-stage Compressor Rotor and the inlet case for corrosion		
F725005	130	Do a detailed inspection of the turbine exhaust duct.		
F731002	130	Do a check for the fuel pump installation and leaks.		
F731003	130	Do a check of the oil-to- fuel heater installation		
F731035	130	Do a visual inspection of the Fuel - Oil Heat Exchanger Fuel Filter Element (CLEANING / REPLACEMENT) P/N OFF: <u>AN 6235-3A</u> P/N ON: <u>AN 6235-3A</u>		

Chapter 51 – Engine PT6A-140 100 Hours/Minor Inspection

ITEM CODE NO.	ZONE	TASK	SIGNATURE	
			SIGN	STAMP
F731006	130	Do a check of the drain valve for installation and leaks		
F731007	130	Do a check of the flow divider for installation and leaks.		
F731008	130	Do a visual inspection of the P3 filter and drain valve.		
F731015	130	Do a visual inspection of Fuel Pump outlet filter. (CLEANING / REPLACEMENT) P/N OFF: <u>AN 6235 - 3A</u> P/N ON: <u>AN 6235 - 3A</u>		
F731018	130	Clean or replace the P3 filter based on condition, service experience or environment. Note: If corrossions are found, replace filter.		
F732001	130	Do a check of the FCU for installation, linkages and pneumatic tubes.		
F792000	130	Inspect and clean oil filter for debris.		
*** End of Engine PT6A-140 100 Hours Inspection Items ***				

PERSONNEL PARTICIPATING IN THIS INSPECTION			
NAME	POSITION	SIGNATURE	LICENSE NUMBER
M. Aziz Andika	ENGINEER		9633
CET NANA	MECHANIC		

RETURN TO SERVICE			
The work recorded above has been carried out in accordance with the requirements of the Civil Aviation Safety Regulation for the time being in force and in that respect the aircraft is consider fit for Release to Service.			
Name	: M. Aziz Andika	Stamp	: 
Signature	: 	Place/Date	: TIMIKA / 17-APRIL-2022

MAINTENANCE PROGRAM CESSNA C208/C208B

Chapter 52 – Engine PT6A-140 200 Hours Inspection


Reg. Mark : PK - SNA Date : 17 April 2022
MSN : 2088 - 5634 Station : TIMIKA
TSN / CSN : 991:45 / 1579 WO No. : WO / 022 - SNA / 10 / 2022

ITEM CODE NO.	ZONE	TASK	SIGNATURE	
			SIGN	STAMP
F793001	130	Do a visual inspection of the chip detector for debris.		
*** End of Engine PT6A-140 200 Hours Inspection Items ***				

PERSONNEL PARTICIPATING IN THIS INSPECTION			
NAME	POSITION	SIGNATURE	LICENSE NUMBER
M. AIR ANDIKA	ENGINEER		9633
CEY NANA	MECHANIC		

RETURN TO SERVICE

The work recorded above has been carried out in accordance with the requirements of the Civil Aviation Safety Regulation for the time being in force and in that respect the aircraft is consider fit for Release to Service.


Name : M. AIR ANDIKA Stamp : 
Signature :  Place/Date : TIM / 17 APRIL 2022

MAINTENANCE PROGRAM CESSNA C208/C208B

Chapter 53 – Engine PT6A-140 200 Hours or 6 Months Inspection

Reg. Mark : PK - SNA Date : 17-APRIL-2022
MSN : 208 B - 5634 Station : TIMIKA
TSN / CSN : 991:45 / 1579 WO No. : WO / 022 - SNA / 11 / 2020

ITEM CODE NO.	ZONE	TASK	SIGNATURE	
			SIGN	STAMP
F793000	130	Do a visual inspection of the AGB internal scavenge oil pump inlet screen		
*** End of Engine PT6A- 140 200 Hours or 6 Months Inspection Items ***				

PERSONNEL PARTICIPATING IN THIS INSPECTION			
NAME	POSITION	SIGNATURE	LICENSE NUMBER
M. ARIZ ANDIKA	ENGINEER		9633
CEP NANA	MEKNIK		

RETURN TO SERVICE

The work recorded above has been carried out in accordance with the requirements of the Civil Aviation Safety Regulation for the time being in force and in that respect the aircraft is consider fit for Release to Service.

Name : M. ARIZ ANDIKA Stamp : 
Signature :  Place/Date : TIMIKA / 17-APRIL-2022

MAINTENANCE PROGRAM CESSNA C208/C208B

Chapter 56 – Engine PT6A-140 1000 Hours Inspection

Reg. Mark : PK - SNA Date : 17 April 2022
MSN : 2086 - 5634 Station : TIMIKA
TSN / CSN : 991:45 / 1579 WO No. : WO 1022-SNA / 11 / 2022

ITEM CODE NO.	ZONE	TASK	SIGNATURE	
			SIGN	STAMP
F731028	130	Replace the P3 filter. P/N OFF: 3038142 P/N ON: 3038142		
F792001	130	Remove and discard the oil filter element. Install a new oil filter element. P/N OFF: 3034393WFC P/N ON: 3034393WFC		
*** End of Engine PT6A-140 1000 Hours Items ***				

PERSONNEL PARTICIPATING IN THIS INSPECTION			
NAME	POSITION	SIGNATURE	LICENSE NUMBER
M. Azil Andika	ENGINEER		9633
CEP NANA	MEKANIK		

RETURN TO SERVICE

The work recorded above has been carried out in accordance with the requirements of the Civil Aviation Safety Regulation for the time being in force and in that respect the aircraft is consider fit for Release to Service.


Name : M. Azil Andika Stamp : 
Signature :  Place/Date : TIMIKA / 17 April 2022

MAINTENANCE PROGRAM CESSNA C208/C208B

Appendix C03 – OOP34003 / GSA 80/81 Servos

Reg. Mark : PK - SNA Date : 16 - April 2022
MSN : 208B-5634 Station : TIMIKA
TSN / CSN : 991:45 / 1579 WO No. : WO 022 - SNA / 10/2022

NO.	ZONE	TASK	SIGNATURE	
			SIGN	STAMP
01	211 212	Conduct visual inspection for GSA 80/81 Servos refer to G1000 Line Maintenance Manual, Doc. No. 190-00869-00, Rev. G		
*** End of Appendix C03 Items ***				

PERSONNEL PARTICIPATING IN THIS INSPECTION			
NAME	POSITION	SIGNATURE	LICENSE NUMBER
M. ARI ANDIKA	ENGINEER		9633
CEP NANA	MEKAME		

RETURN TO SERVICE

The work recorded above has been carried out in accordance with the requirements of the Civil Aviation Safety Regulation for the time being in force and in that respect the aircraft is consider fit for Release to Service.


Name : M. ARI ANDIKA Stamp : 
Signature :  Place/Date : TIMIKA / 16 - APRIL - 2022

MAINTENANCE PROGRAM CESSNA C208/C208B

Appendix C04 – OOP34004 / GSM 85A/86

Reg. Mark	: PK - SNA	Date	: 16 - APRIL - 2022
MSN	: 208 B - 5634	Station	: TIMIKA
TSN / CSN	: 991:45 / 1579	WO No.	: WO / 022 - SNA / 14 / 2022

NO.	ZONE	TASK	SIGNATURE	
			SIGN	STAMP
01	211 212	Conduct visual inspection and check slip clutches of GSM 85A/86, refer to G1000 Line Maintenance Manual, Doc. No. 190-00869-00, Rev. G.		
*** End of Appendix C04 Items ***				

PERSONNEL PARTICIPATING IN THIS INSPECTION			
NAME	POSITION	SIGNATURE	LICENSE NUMBER
M. Azri Andika	ENGINEER		9633
CEP NANA	MEKANIK		

RETURN TO SERVICE

The work recorded above has been carried out in accordance with the requirements of the Civil Aviation Safety Regulation for the time being in force and in that respect the aircraft is consider fit for Release to Service.

Name	: M. Azri Andika	Stamp	: 
Signature	: 	Place/Date	: TIMIKA / 16 - APRIL - 2022



EMERGENCY EQUIPMENT LIST INSPECTION & MONITOR

**PT. SMART CAKRAWALA
AVIATION
DEPARTMENT TEKNIK
Form: SCA/MTC/023**

DATE : 16-APRIL -2022	A/C REG : PF-SNA
A/C TYPE : C 208B EX	CHECKER : Azn ANDIFA SIGN:

No.	Description	P/N	S/N	Next Insp.	Remarks
1	Pilot Life Vest	P01202 - 201	21031090020	MAR - 2030	SERVICEABLE
2	Co-Pilot Life Vest	P01202 - 201	21031090008	MAR - 2030	SERVICEABLE
3	Pax Life Vest				
4	Pax Life Vest				
5	Pax Life Vest				
6	Pax Life Vest				
7	Pax Life Vest				
8	Pax Life Vest				
9	Pax Life Vest				
10	Pax Life Vest				
11	Pax Life Vest				
12	Pax Life Vest				
13	Firt Aid Kit	FL 220 FAK	0221-1898	FEB 2023	SERVICEABLE
14	Crash Axe Installed	NPN	NSN	0/c	SERVICEABLE
15	Fire Extinguisher	C352	G 40531481	JULY 2022	SERVICEABLE
16	Life Raft (If Installed)				
17	Survival Kit (If Installed)	FL 220	105755	JAN 2023	SERVICEABLE
OTHERS					
18	PLASH LIGHT	NPN	NSN	0/c	SERVICEABLE



Aircraft Registration: **PK-SNA**



WO# Nr: WO/022-SNA/IV/2022

Additional Work Sheet
Inspection Doc. 06 & Add Task

Parts Used Sheet

Special Tool Used

[illegible]



Aircraft Registration: **PK-SNA**



WO# Nr: WO/022-SNA/IV/2022

Additional Work Sheet
Inspection Doc. 06 & Add Task

Parts Used Sheet

Part Used

[illegible]