



PT. SMART CAKRAWALA AVIATION

WORK ORDER

Form: SCA/MTC/030

Subject : Inspection 200Hours & Add.Task Insp.	No.	WO/038-SNH/IV/2023
	Date	12 Apr 2023
	A/C Reg.	PK-SNH C208B-5587
Reference : MP C208/208B ISSUED 01	Prepared By	TS
	Checked By	CI
	Approved By	TM
To : Engineer In Charge		
Description : 1. Perform Inspection 200 Hours & Add. Task Inspection Due at 3400 FH. 2. Make an entry in Maintenance Log. 3. Return the Completed Work Order and Form to PPC. #If any finding, please close the routine card, and transferred to inspection card.		
Additional Work : - NIL -		
Compliance Statement	Sign & Date Company Lic. No.: SCA 071 19/04/2023  (Engineer In Charge)	Signature  (Technical Manager)

AIRCRAFT CHECK WORK SUMMARY
(Form: SCA/MTC/051)

DATE OF ISSUED	JO/WO #	TYPE OF MAINTENANCE	DATE OF ACCOMPLISHED		
12 Apr 2023	WO/038-SNH/IV/2023	Inspection 200 Hours & Add. Task	13 - 04 - 2023		
A/C Type	Mfg. Serial Number	A/C Registration			
C208B	C208B-5587	PK-SNH			
AIRCRAFT DATA					
Subject	Pos #	Serial Number (SN)	TTSN/TCSN		
Engine	#1	PCE-VA0662	3337:15/5110		
	#2	-			
Propeller/Rotor	#1	190837	3337:15/5110		
	#2	-			
Landing Gear	NLG		3337:15/5110		
	LH MLG		3337:15/5110		
	RH MLG		3337:15/5110		
PACKAGE COVERED					
No	Subject	Qty	Remark		
1	Non-Routine Card	-			
2	Inspection Card	-	✓		
3	Work Order	1	✓		
4	Summary Inspection List	1	✓		
5	Material and Tool List	-			
6	Escalation form	-			
7	CRS (SMI / Unscheduled Maintenance)	1	✓		
INSPECTION CARD (IC) LIST (Finding during maintenance)					
No	Taskcard Ref	Subject	Status		Name/ Sign & Stamp
			Open	Close	
IC-001	C122101	REPLACED NOSE BEARING WHEEL		✓	 
IC-002	D121001	REPLACED LH BRAKE LINING		✓	 
IC-003	D121001	REPLACED RH BRAKE LINING		✓	 
IC-004	D122101	REPLACED RH MAIN WHEEL BEARING		✓	 
IC-005	74-20-00	REPLACED RH SPARK IGNITER		✓	 
IC-006	D121001	REPLACED RH SHIM BRAKE CALIPER		✓	 

<u>IC-007</u>				
<u>IC-008</u>				
<u>IC-009</u>				
<u>IC-010</u>				
<u>IC-011</u>				
<u>IC-012</u>				
<u>IC-013</u>				
<u>IC-014</u>				
<u>IC-015</u>				

Prepared by :
Technical Support



Hani

Checked by :
Chief Maintenance



Dodit

Verified by :
Chief Inspector



Yanuar

Approved by :
Technical Manager



Istiono



SUMMARY INSPECTION ITEMS (Form: SCA/MTC/050)

WO Ref: WO/038-SNH/IV/2023

NO.	TASK CARD NO.	DESCRIPTION	DATE	EST MHR	NAME	STAMP
1	APPENDIX D08	PT6A-ENGINE GROUND RUN	19/04/2023		RIDZAL.G	(21)
2	APPENDIX C03	200 HRS/12 MTHS INSPECTION	19/04/2023		RIDZAL.G	(21)
3	APPENDIX D10	PT6A-140 200 HRS/6 MTHS ENGINE	19/04/2023		RIDZAL.G	(21)
4	APPENDIX D09	PT6A-140 200 HRS ENGINE	19/04/2023		RIDZAL.G	(21)
5	APPENDIX D08	PT6A-140 100 HRS ENGINE	19/04/2023		RIDZAL.G	(21)
6	SCA/MTC/023	EMERGENCY EQUIPMENT LIST	19/04/2023		RIDZAL.G	(21)

A.



PT. SMART CAKRAWALA AVIATION

CERTIFICATE RETURN TO SERVICE

SCHEDULED MAINTENANCE INSPECTION

(CRS-SMI)

A/C TYPE : CESSNA 208B

TTSN : 5387:15

A/C REG : PK-SNH

TCSN : 5110

MSN : C208B-5587

DATE : 13-04-2023

TYPE OF INSPECTION : INSPECTION 200 HOURS & ADD TASK

DUE AT : 3400 HOURS

REF : MP C208B ISSUED 01

EXCEPTION

- NO EXCEPTION -

AUTHORIZED PERSON

I hereby certify that this aircraft has been maintained accordance with CASR and Maintenance Program.
Aircraft safe and airworthy for flight

NAME	CAT	AMEL/OTR NO	SIGN&STAMP	DATE
RIZAL GHAZALI	AIRFRAME & POWER PLANT	9694 SCA 021	 	13/04/2023
	EIRA			

THE NEXT DUE TYPE OF INSPECTION : 100 HOURS

DUE AT : 3500:00 HOURS

Form: SCA/MTC/049

		INSPECTION CARD (Form: SCA/MTC/048)			TECHNICAL DEPARTMENT	
1. CARD #	2. JOWO #	3. ORIGINATOR	4. CARD REF	5. DATE		
1C-001	W0638-SNH/11/2023		122101	19-04-2023		
6. A/C REG/MSN	7. A/C TYPE	8. TRADE	12. VENDOR ORDER #			
PK-SNH 22083-5587	22083 EX					
9. ZONE	10. STA	11. MTC TYPE				
MLG	MERAUKE					

13. DESCRIPTION/DEFECT-IF FINDING OF CPCP INSPECTION, PLEASE COMPLETE SET. 20	14	15
	PPC/ENG	DATE
NOSE WHEEL BEARING FOUND WORN OUT AND CORROSION	 	19/04/2023

16. CORRECTIVE ACTION	17	18	19
	MECH	ENG. LIC	DATE
REPLACED NOSE WHEEL BEARING WITH NEW ONE (AW 22083 MM CH 32-40-00 Performed at A/C TT : 3397:15..... A/C TC/LDG : 5110.....		 	19/04/2023

20. CORROSION INFORMATION			
LOCATION	CAUSE OF DAMAGE		
	☐ Environment		
	☐ Internal Leakage		
CORROSION ☐ Isolated ☐ Widespread	☐ Chemical Spill		
CORROSION LVL ☐ 1 ☐ 2 ☐ 3	☐ LAV/Galley Spill		
PROPOSED ACTION ☐ Doublers	☐ Blocked Drain		
☐ Others	☐ Wet Insulation Blanket		
	☐ Other		

21. If the defect is RII, Please Sign this card finally by RII Inspector		INSP	DATE
NOTICE OF INSPECTOR			

22. PARTS REQUIRED						
PART DESCRIPTION	PART NO	QTY	SERIAL NO		STATUS	
			ON	OFF	CLOSE	OPEN
BEARING	214-00200	2	MSN	MSN	✓	

23. TOOLS REQUIRED			
DESCRIPTION	PART NO. / MODEL	NEXT CALIBRATION DATE	STATUS

		INSPECTION CARD (Form: SCA/MTC/048)		TECHNICAL DEPARTMENT		
1. CARD#		2. JOWO#		3. ORIGINATOR		
12-002		W01038-SNH/11/2023		D121001		
6. A/C REG/MSN		7. A/C TYPE		8. TRADE		
PK-SNH/5587		C2083 EX				
9. ZONE		10. STA		11. MTC TYPE		
MLG		MERAKU				
13. DESCRIPTION/DEFECT-IF FINDING OF CPCP INSPECTION, PLEASE COMPLETE SET. 20				14. PPC/ENG		
				15. DATE		
LH BRAKE LINING FOUND WORN OUT				 21 19/04/2023		
16. CORRECTIVE ACTION				17. MECH		
				18. ENG. LIC		
REPLACED LH BRAKE LINING ON PRESSURE PLATE WITH NEW ONE IAW C2083 AMM CH 32-40-00 Performed at A/C TT : 3397:15 A/C TC/LDG : 5110				 21 19/04/2023		
20. CORROSION INFORMATION						
LOCATION			CAUSE OF DAMAGE			
CORROSION ☐ Isolated ☐ Widespread CORROSION LVL ☐ 1 ☐ 2 ☐ 3 PROPOSED ACTION ☐ Doublers ☐ Others ☐ Other			☐ Environment			
			☐ Internal Leakage			
			☐ Chemical Spill			
			☐ LAV/Galley Spill			
			☐ Blocked Drain			
			☐ Wet Insulation Blanket			
			☐ Other			
21. If the defect is RII, Please Sign this card finally by RII Inspector				INSP		
NOTICE OF INSPECTOR				DATE		
22. PARTS REQUIRED						
PART DESCRIPTION	PART NO	QTY	SERIAL NO		STATUS	
			ON	OFF	CLOSE	OPEN
LINING	066-15300	4	NSN	NSN	✓	
23. TOOLS REQUIRED						
DESCRIPTION	PART NO. / MODEL	NEXT CALIBRATION DATE		STATUS		

		INSPECTION CARD (Form: SCA/MTC/ 048)			TECHNICAL DEPARTMENT	
---	--	--	--	--	-------------------------	--

1. CARD #	2. JOWO #	3. ORIGINATOR	4. CARD REF	5. DATE	
IC-003	WD038-MK11/2023		P121001	13-04-2023	
6. A/C REG/MSN	7. A/C TYPE	8. TRADE	12. VENDOR ORDER #		
PK-SAH/5587	C200T3EX				
9. ZONE	10. STA	11. MTC TYPE			
MLG	MERAUKE				

13. DESCRIPTION/DEFECT-IF FINDING OF CPCP INSPECTION, PLEASE COMPLETE SET. 20	14 PPC/ENG	15 DATE
RM BRAKE LINING ROUND WORN OUT	 	13/2023 /04

16. CORRECTIVE ACTION	17 MECH	18 ENG. LIC	19 DATE
REPLACED RM BRAKE LINING ON PRESSURE PLATE WITH NEW ONE (AW C200T3 MM 52-40-00 Performed at A/C TT : 3397:15 A/C TC /LDG : 5110		 	13/2023 /04

20. CORROSION INFORMATION					
LOCATION	CAUSE OF DAMAGE ☐ Environment ☐ Internal Leakage ☐ Chemical Spill ☐ LAV/Galley Spill ☐ Blocked Drain ☐ Wet Insulation Blanket ☐ Other				
CORROSION ☐ Isolated ☐ Widespread CORROSION LVL ☐ 1 ☐ 2 ☐ 3 PROPOSED ACTION ☐ Doublers ☐ Others					
21. If the defect is RII, Please Sign this card finally by RII Inspector				INSP	DATE
NOTICE OF INSPECTOR					

22. PARTS REQUIRED						
PART DESCRIPTION	PART NO	QTY	SERIAL NO		STATUS	
			ON	OFF	CLOSE	OPEN
LINING	006-15300	4	NSN	NSN	✓	

23. TOOLS REQUIRED			
DESCRIPTION	PART NO. / MODEL	NEXT CALIBRATION DATE	STATUS

		INSPECTION CARD (Form: SCA/MTC/ 048)			TECHNICAL DEPARTMENT	
---	--	--	--	--	-------------------------	--

1. CARD #	2. JO/WO #	3. ORIGINATOR	4. CARD REF	5. DATE	
1C-004	W01038-SNH/10/2023		D122101	19-04-2023	
6. A/C REG/MSN	7. A/C TYPE	8. TRADE	12. VENDOR ORDER #		
PK-SNH/5587	C2083 EX				
9. ZONE	10. STA	11. MTC TYPE			
MLG	MERAKE				

13. DESCRIPTION/DEFECT-IF FINDING OF CPCP INSPECTION, PLEASE COMPLETE SET. 20	14	15
	PPC/ENG	DATE
RM BEARING WHEEL NUTS ROUND WORN OUT	 	19/2023 04

16. CORRECTIVE ACTION	17	18	19
	MECH	ENG. LIC	DATE
REPLACED RM BEARING WITH ANEW ONE 1AW CROTS MM CH 32-40-00 Performed at A/C TT: 3397-15 A/C TC/LDG: 5110		 	19/2023 04

20. CORROSION INFORMATION						
LOCATION		CAUSE OF DAMAGE				
		☐ Environment ☐ Internal Leakage ☐ Chemical Spill ☐ LAV/Galley Spill ☐ Blocked Drain ☐ Wet Insulation Blanket ☐ Other				
CORROSION ☐ Isolated ☐ Widespread						
CORROSION LVL ☐ 1 ☐ 2 ☐ 3						
PROPOSED ACTION ☐ Doublers ☐ Others						

21. If the defect is RII, Please Sign this card finally by RII Inspector		INSP	DATE
NOTICE OF INSPECTOR			

22. PARTS REQUIRED						
PART DESCRIPTION	PART NO	QTY	SERIAL NO		STATUS	
			ON	OFF	CLOSE	OPEN
BEARING	21V-01400	1	NSN	NSN	✓	

23. TOOLS REQUIRED			
DESCRIPTION	PART NO. / MODEL	NEXT CALIBRATION DATE	STATUS

 INSPECTION CARD (Form: SCA/MTC/ 048)				TECHNICAL DEPARTMENT							
1. CARD #		2. JO/WO #		3. ORIGINATOR		4. CARD REF		5. DATE			
1C-005		WO/038-SNH/V/2023				74-20-00		12-04-2023			
6. A/C REG/MSN		7. A/C TYPE		8. TRADE		12. VENDOR ORDER #					
PK-SNH/5587		C208TS EX									
9. ZONE		10. STA		11. MTC TYPE							
ENGINE		MERAUKE									
13. DESCRIPTION/DEFECT-IF FINDING OF CPCP INSPECTION, PLEASE COMPLETE SET. 20								14		15	
								PPC/ENG		DATE	
RH SPARK IGNITER FOUND WORN OUT								 		19/2023	
										04	
16. CORRECTIVE ACTION						17		18		19	
						MECH		ENG. LIC		DATE	
REPLACED RH SPARK IGNITER WITH A NEW ONE 1AWC208TS EMM CH 74-20-00 Performed at A/C TT: 3397:15 A/C TC/LDG: 9110						 		19/2023			
								04			
20. CORROSION INFORMATION											
LOCATION				CAUSE OF DAMAGE							
				☐ Environment ☐ Internal Leakage ☐ Chemical Spill ☐ LAV/Galley Spill ☐ Blocked Drain ☐ Wet Insulation Blanket ☐ Other							
CORROSION ☐ Isolated ☐ Widespread											
CORROSION LVL ☐ 1 ☐ 2 ☐ 3											
PROPOSED ACTION ☐ Doublers ☐ Others											
21. If the defect is RII, Please Sign this card finally by RII Inspector								INSP		DATE	
NOTICE OF INSPECTOR											
22. PARTS REQUIRED											
PART DESCRIPTION	PART NO	QTY	SERIAL NO		STATUS						
			ON	OFF	CLOSE	OPEN					
SPARK IGNITER	CH34055	1	NSN	NSN	✓						
23. TOOLS REQUIRED											
DESCRIPTION	PART NO. / MODEL	NEXT CALIBRATION DATE	STATUS								

		INSPECTION CARD (Form: SCA/MTC/ 048)			TECHNICAL DEPARTMENT	
---	--	--	--	--	-------------------------	--

1. CARD #	2. JOWO #	3. ORIGINATOR	4. CARD REF	5. DATE	
1C-006	W01038-SNH/14/2023		P121001	19-04-2023	
6. A/C REG/MSN	7. A/C TYPE	8. TRADE	12. VENDOR ORDER #		
PE-SNH/5587	C208TBEX				
9. ZONE	10. STA	11. MTC TYPE			
MLG	MERAUKE				

13. DESCRIPTION/DEFECT-IF FINDING OF CPCP INSPECTION, PLEASE COMPLETE SET. 20	14	15
	PPC/ENG	DATE
RH SHIM BRAKE CALIPER FOUND BROKEN	 	19/04/2023

16. CORRECTIVE ACTION	17	18	19
	MECH	ENG. LIC	DATE
REPLACED RH SHIM BRAKE CALIPER WITH A NEW ONE 1AW C208B AMM CH3240-00 Performed at A/C TT : 3397:15 A/C TC/LDG : 5110		 	19/04/2023

20. CORROSION INFORMATION			
LOCATION	CAUSE OF DAMAGE		
	☐ Environment ☐ Internal Leakage ☐ Chemical Spill ☐ LAV/Galley Spill ☐ Blocked Drain ☐ Wet Insulation Blanket ☐ Other		
CORROSION ☐ Isolated ☐ Widespread CORROSION LVL ☐ 1 ☐ 2 ☐ 3 PROPOSED ACTION ☐ Doublers ☐ Others			

21. If the defect is RII, Please Sign this card finally by RII Inspector	INSP	DATE
NOTICE OF INSPECTOR		

22. PARTS REQUIRED						
PART DESCRIPTION	PART NO	QTY	SERIAL NO		STATUS	
			ON	OFF	CLOSE	OPEN
SHIM	048-02800	1	NSN	NSN	✓	

23. TOOLS REQUIRED			
DESCRIPTION	PART NO. / MODEL	NEXT CALIBRATION DATE	STATUS

Appendix B08 – PT6A-140 Engine Run Performance Sheet

Reg. Mark : PK- SNH

WO/FML No. : WO/038-SNH/1V/2023

PRE – INSPECTION	
Location	
Date	
Cycle	
Filed Barometric	
OAT	
Altitude	

POST – INSPECTION	
Location	<u>MEZAUKE</u>
Date	<u>19-04-2023</u>
Cycle	
Filed Barometric	<u>1010 HPA</u>
OAT	<u>27°C</u>
Altitude	<u>20 FT</u>

PRE – INSPECTION		
	Target	Actual
Tq		
Np		
ITT	°C	°C
Ng	%	%
Wf		
Oil Press		°C
Oil Temp		°C
Start Temp		°C

POST- INSPECTION		
	Target	Actual
Tq		<u>2337</u>
Np		<u>1830</u>
ITT	°C	<u>820 °C</u>
Ng	%	<u>100 %</u>
Wf		<u>551</u>
Oil Press		<u>95 °C</u>
Oil Temp		<u>64 °C</u>
Start Temp		<u>680 °C</u>

Engine Run Up Checks					
Inertial ☒	EPL ☒	OVG ☒	Stby Alt ☒	BOV ☒	Brake ☒
NOTE: 1. Brake system at Torque 2000 ft-lbs. 3. EPL check can't exceed 4% Ng per second. 5. Low idle at 55.5 - 57% 40Amps. 2. Inertial Separator at Torque 400 ft-lbs. 4. Standby Alt at 80% Ng. 6. High idle at 64 - 66% Ng 40Amps					

Engine Performance Target Table (Cessna C208B EX)

OAT (°C)	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41
Tq (ft.lbs)	2397	2397	2397	2397	2397	2397	2397	2397	2397	2397	2397	2397	2397	2397	2397
Np	1900	1900	1900	1900	1900	1900	1900	1900	1900	1900	1900	1900	1900	1900	1900
ITT (°C)	835	837	839	841	841	841	841	841	841	842	843	844	846	846	846
Ng (%)	102.7	102.7	102.7	102.7	102.7	102.7	102.7	102.6	102.6	102.6	102.6	102.6	102.6	102.6	102.5
WF (PPH)	578	578	578	578	578	578	578	570	565	565	560	560	555	548	548

Note:

1. Make sure that inertial separator in normal condition, no bleed air extracted from the engine and air condition OFF.
2. This table only applies to altitude 0-500 feet MSL. For higher altitude, refer to EMM 72-00-00.
3. Max fuel flow is 580 lb/hr fuel flow is not more than 15 lbs/hr higher than the value shown in table.
4. If parameters are outside the target performance table to EMM chapter 71-00-00.

REMARKS:

-ALL ENGINE PARAMETER WITHIN OF LIMIT

PERFORMED BY			
Name	Sign & Stamp	Date	Location
<u>RIODAL G</u>		<u>19/04/2023</u>	<u>MEZAUKE</u>





MAINTENANCE PROGRAM CESSNA 208/208B

Appendix C03 – 200 Hours/12 Months Inspection

Reg. Mark : PK - SMH
MSN : C208B-5987
TSN / CSN : 3397:15/5110

Date : 12-04-2023
Station : MEZAUKE
WO No. : WO1038-SMH/V17023


ITEM CODE NO.	ZONE	TASK	SIGNATURE	
			ENGINEER SIGN&STAMP	RII SIGN&STAMP
A110001	ALL	Interior and Exterior Placard and Decal Detailed Inspection Task 11-00-00-220		
D121001	121	Brake System Servicing Task 12-10-01-610		
D121003	710	Shimmy Damper Servicing Task 12-10-01-611 <i>N/A</i>		
C122101	700	Landing Gear Lubrication Task 12-21-03-640		
C122103	110	Hartzell Propeller Lubrication Task 12-21-04-640	N/A	N/A
B236001	343 375 376 571 671	Static Discharge System Functional Check Task 23-60-00-720		
B243401	122	Marathon Ni-Cad Battery Functional Check (CapCheck) Task 24-34-00-720	N/A	N/A
A255101	251 252 255 256 257 258	Cargo Nets Detailed Inspection Task 25-51-00-220 <i>N/A</i>		
C270001	215 216 226 373 374 503 525 603 625	Flight Controls Lubrication Task 27-00-00-640		
B273101	211 212 503	Stall Warning System Operational Check Task 27-31-00-710		
C275001	525 527 625 627	Flap Tracks and Rollers Lubrication Task 27-50-00-640		
B281001	575 675	Fuel Vent Line Float Valve Operational Check Task 28-10-03-710		
A281001	521 621	Fuel Filler Assembly Detailed Inspection Task 28-10-01-220		

ITEM CODE NO.	ZONE	TASK	SIGNATURE	
			ENGINEER SIGN&STAMP	RII SIGN&STAMP
B301003	122 AUX	Bleed Air Pressure Regulator Functional Check (without TKS and not incorporating CAB93-2) Task 30-10-00-720		
B322001	710	Shimmy Damper Functional Check Task 32-20-02-720		
B341101	AUX	Pitot Tube Heaters Operational Check Task 34-11-00-710		
A353001	256	Oxygen Mask Detailed Inspection Task 35-30-00-220		
B761003	AUX	Emergency Power Lever Annunciator Light (EPL) Operational Check Task 76-10-01-710		
*** End of Inspection 200 Hours/12 Months Items ***				

PERSONNEL PARTICIPATING IN THIS INSPECTION			
NAME	POSITION	SIGNATURE	LICENSE NUMBER
RIDZAL G	ENGINEER		9694







RETURN TO SERVICE

The work recorded above has been carried out in accordance with the requirements of the Civil Aviation Safety Regulation for the time being in force and in that respect the aircraft is consider fit for Release to Service.


Name : RIDZAL GHAZAL Place/Date : MERAUKE 19-04-2023
Sign & Stamp : 

Appendix D08 – Engine PT6A-140 100 Hours/Minor Inspection

Reg. Mark : PK-SNH Date : 19-04-2023
 MSN : 62083-5587 Station : MEPAUKE
 TSN / CSN : 3357:15/5110 WO No. : W01033-SNH/11/2023

ITEM CODE NO.	ZONE	TASK	SIGNATURE	
			ENGINEER SIGN&STAMP	RII SIGN&STAMP
F710001	130	Do a check of the FCU manual override system for static operation. For the engines installed with a manual override system only.		
F710003	130	Do a compressor performance recovery wash		
F720000	130	Do a visual inspection of the Control Linkages and wiring.		
F720001	130	Do a visual inspection of the engine exhaust duct welds.		
F720002	130	Do a visual inspection of the engine exhaust duct for cracks.		
F720003	130	Do a visual inspection of the gas generator case and the center fireseal.		
F720004	130	Do a visual inspection of the rear fireseal mounting ring.		
F722001	130	Do a visual inspection of the air inlet screen.		
F723000	130	Do a visual inspection with a mirror or a borescope inspection of the First-stage Compressor Rotor and the inlet case for corrosion		
F725005	130	Do a detailed inspection of the turbine exhaust duct.		
F731002	130	Do a check for the fuel pump installation and leaks.		
F731003	130	Do a check of the oil-to- fuel heater installation		

Appendix D08 – Engine PT6A-140 100 Hours/Minor Inspection

ITEM CODE NO.	ZONE	TASK	SIGNATURE	
			ENGINEER SIGN&STAMP	RII SIGN&STAMP
F731035	130	Do a visual Inspection of the Fuel - Oil Heat Exchanger Fuel Filter Element (CLEANING / REPLACEMENT) P/N OFF: <u>AN6235-3A</u> P/N ON: <u>AN6235-3A</u>	 	
F731006	130	Do a check of the drain valve for installation and leaks	 	
		NOTE: There is no need to remove the drain valve if there is no leaks.		
F731007	130	Do a check of the flow divider for installation and leaks.	 	
F731008	130	Do a visual inspection of the P3 filter and drain valve.	 	
F731015	130	Do a visual inspection of Fuel Pump outlet filter. (CLEANING / REPLACEMENT) P/N OFF: <u>AN6235-3A</u> P/N ON: <u>AN6235-3A</u>	 	
F731018	130	Clean or replace the P3 filter based on condition, service experience or environment. Note: If corrossions are found, replace filter.	 	
F732001	130	Do a check of the FCU for installation, linkages and pneumatic tubes.	 	
F792000	130	Inspect and clean oil filter for debris.	 	
*** End of Engine PT6A-140 100 Hours/Minor Inspection Items ***				

PERSONNEL PARTICIPATING IN THIS INSPECTION			
NAME	POSITION	SIGNATURE	LICENSE NUMBER
RIDZAL . G	ENGINEER		5694




MAINTENANCE PROGRAM CESSNA 208/208B

Appendix D08 – Engine PT6A-140 100 Hours/Minor Inspection

RETURN TO SERVICE

The work recorded above has been carried out in accordance with the requirements of the Civil Aviation Safety Regulation for the time being in force and in that respect the aircraft is consider fit for Release to Service.

Name : PIODAL . G Place/Date : MERAKU Eng - 04-2023
Sign & Stamp : 



MAINTENANCE PROGRAM CESSNA 208/208B

Appendix D09 – Engine PT6A-140 200 Hours Inspection

Reg. Mark : PK-GNH

Date : 19-04-2023

MSN : C208B-5587

Station : MERAUKE

TSN / CSN : 3397:15/5110

WO No. : WO1038-GNH/V/2023

ITEM CODE NO.	ZONE	TASK	SIGNATURE		DATE
			SIGN	STAMP	
F793001	130	Do a visual inspection of the chip detector for debris.			19/04/2023
*** End of Engine PT6A-140 200 Hours Inspection Items ***					

PERSONNEL PARTICIPATING IN THIS INSPECTION			
NAME	POSITION	SIGNATURE	LICENSE NUMBER
RUDAL-G	ENGINEER		9694

RETURN TO SERVICE

The work recorded above has been carried out in accordance with the requirements of the Civil Aviation Safety Regulation for the time being in force and in that respect the aircraft is consider fit for Release to Service.

Name : RUDAL-G

Place/Date : MERAUKE, 19-04-2023

Sign & Stamp :



EMERGENCY EQUIPMENT LIST INSPECTION & MONITOR

**PT. SMART CAKRAWALA
AVIATION
DEPARTMENT TEKNIK
Form: SCA/MTC/023**

DATE : 19-04-2023	A/C REG : PK-SNH
A/C TYPE : C208B	CHECKER : R. P. D. A. L. G. SIGN:

No.	Description	P/N	S/N	Next Insp.	Remarks
1	Pilot Life Vest	P01202-201	13092030093	JAN 2023	GOOD
2	Co-Pilot Life Vest	P01202-201	13080030081	JAN 2023	GOOD
3	Pax Life Vest				
4	Pax Life Vest				
5	Pax Life Vest				
6	Pax Life Vest				
7	Pax Life Vest				
8	Pax Life Vest				
9	Pax Life Vest				
10	Pax Life Vest				
11	Pax Life Vest				
12	Pax Life Vest				
13	First Aid Kit	FAK FL 220	1249-1450	AUGUST 2023	GOOD
14	Crash Axe Installed			O/C	GOOD
15	Fire Extinguisher	6352	F55344618	NOV 2023	GOOD
16	Life Raft (If Installed)				
17	Survival Kit (If Installed)				
OTHERS					
18.	FLASH LIGHT	-	-	O/C	GOOD



& Additional Task

PK-SNH

WO # N^o: ~~WO/038-SNH/IV/2023~~

Part Used Parts Used Sheet

[illegible]



WO# NR: WO/038-SNH/IV/2023

Additional Work Sheet
Inspection 200 Hours &
Additional Task
Parts Used Sheet

[illegible]