



PT. SMART CAKRAWALA AVIATION

WORK ORDER

Form: SCA/MTC/030

Subject : Inspection 1600Hours & Add.Task Insp.	No.	WO/040-SNG/II/2023
	Date	3 February 2023
	A/C Reg.	PK-SNG C208B-5543
Reference : MP C208/208B ISSUED 01	Prepared By	TS
	Checked By	CI
	Approved By	TM
To : Engineer In Charge		
Description : 1. Perform Inspection 1600 Hours & Add. Task Inspection Due at 3200 FH. 2. Make an entry in Maintenance Log. 3. Return the Completed Work Order and Form to PPC. #If any finding, please close the routine card, and transferred to inspection card.		
Additional Work :		
Compliance Statement WSP 1600 HRS & ADD TASK 40	Sign & Date Company Lic. No.:  (Engineer In Charge) 20 Feb - 2023 	Signature  (Technical Manager)

AIRCRAFT CHECK WORK SUMMARY
(Form: SCA/MTC/051)

DATE OF ISSUED	JO/WO #	TYPE OF MAINTENANCE	DATE OF ACCOMPLISHED
3 Feb 2023	WO/040-SNG/11/2023	Inspection 1600 Hours & Add.Task	20 - FEBRUARY - 2023
A/C Type	Mfg. Serial Number	A/C Registration	
C208B	C208B-5543	PK-SNG	
AIRCRAFT DATA			
Subject	Pos #	Serial Number (SN)	TTSN/TCSN
Engine	#1	PCE-VA0596	3213: 29 / 5273
	#2	-	
Propeller/Rotor	#1	190140	3213: 29 / 5273
	#2	-	
Landing Gear	NLG		3213: 29 / 5273
	LH MLG		3213: 29 / 5273
	RH MLG		3213: 29 / 5273
PACKAGE COVERED			
No	Subject	Qty	Remark
1	Non-Routine Card	-	
2	Inspection Card	-	
3	Work Order	1	
4	Summary Inspection List	1	
5	Material and Tool List	-	
6	Escalation form	-	
7	CRS (SMI / Unscheduled Maintenance)	1	

INSPECTION CARD (IC) LIST (Finding during maintenance)

No	Taskcard Ref	Subject	Status		Name/ Sign & Stamp
			Open	Close	
IC-001	741011	R/H IGNITION CABLE WORN OUT		✓	Wes Amos 
IC-002	742002	R/H IGNITION WORN OUT		✓	Wes Amos 
IC-003	0121 001	LH BACK PLATE BRAKE LINING WORN OUT		✓	FERRI-H 
IC-004	232000	SWITCH AUTOPILOT DISCONNECT BROKEN (PILOT SIDE)		✓	A23 
IC-005	324000	LH MAIN TIRE WORN OUT		✓	A23 
IC-006	322000	BOLT MPI NOSE GEAR NEED TO REPLACE		✓	FERRI-H 

<u>IC-007</u>	322000	NOSE GEAR SPRING YOKE BEARING BROKEN		✓	 FERRY.H	
<u>IC-008</u>						
<u>IC-009</u>						
<u>IC-010</u>						
<u>IC-011</u>						
<u>IC-012</u>						
<u>IC-013</u>						
<u>IC-014</u>						
<u>IC-015</u>						

Prepared by :
Technical Support



Hani

Checked by :
Chief Maintenance



Dodit

Verified by :
Chief Inspector



Yanuar

Approved by :
Technical Manager



Istiono



NON ROUTINE CARD
(Form: SCA/MTC/047)

1. JO/WO #	2. DATE	3. MTC TYPE	4. A/C REG/MSN
WO/040-SNG/II/2023	10- FEB- 2023	REPLACEMENT COMPONENT	PK-SNG
5. CARD #	6. ATA SPEC	7. TRADE	8. STA
#01	37		NARIBE
9. ZONE	10. PANEL		
CABIN			

11. DESCRIPTION

PERFORM VACUUM SYSTEM CENTRAL AIR FILTER REPLACEMENT
P/N: D9-18-1 / C294502-0201

REFERENCE	☒ AMM Ch. 37-10-00-960	☐ EMM Ch	☐ OTHER
RII (*)	☐ Y	☒ N	MHR :

12. RESULT

REPLACED WITH A NEW FILTER

Performed at A/C TT : 3213:29 A/C TC /LDG : 5233

MECH	ENG	INSP (*)
	Y.M	

FINDING	☐ Y	☐ N	ACT MHR :
INSPECTION CARD (IC) #			DATE/TIME (DD/MM/YY)
			18 02 23

13. PARTS REQUIRED

DESCRIPTION	PART NO	QTY	REMARK	
			STOCK	STATUS
FILTER ELEMENT	D9-18-1 / C294502-0201	1		NEW

14. TOOLS REQUIRED

DESCRIPTION	PART NO / MODEL	NEXT CALIBRATION DATE	STATUS
General Tool	-	9C	GOOD



NON ROUTINE CARD
(Form: SCA/MTC/047)

1. JO/WO #	2. DATE	3. MTC TYPE	4. A/C REG/MSN
WO/040-SNG/11/2023	18- Feb- 2023	REPLACEMENT COMPONENT	PK-SNG
5. CARD #	6. ATA SPEC	7. TRADE	8. STA
#02	37		NABIRE
9. ZONE	10. PANEL		
CABIN			

11. DESCRIPTION

PERFORM VACUUM RELIEF VALVE FILTER REPLACEMENT
P/N: B3-5-1 / C482001-0202

REFERENCE	☒ AMM Ch. 37-10-00-961	☐ EMM Ch	☐ OTHER
RII (*)	☐ Y	☒ N	MHR :

12. RESULT

REPLACED WITH A NEW FILTER

Performed at A/C TT : 3213:29 A/C TC /LDG : 5293

FINDING	☐ Y	☐ N	ACT MHR :	DATE/TIME (DD/MM/YY)
INSPECTION CARD (IC) #				10 02 23

13. PARTS REQUIRED

DESCRIPTION	PART NO	QTY	REMARK	
			STOCK	STATUS
FILTER ELEMENT	B3-5-1 / C482001-0202	1		new

14. TOOLS REQUIRED

DESCRIPTION	PART NO / MODEL	NEXT CALIBRATION DATE	STATUS
GENERAL TOOLS	-	%	Good

	INSPECTION CARD (Form: SCA/MTC/ 048)		TECHNICAL DEPARTMENT	
---	--	--	-------------------------	--

1. CARD#	2. JOWO#	3. ORIGINATOR	4. CARD REF	5. DATE
1C-001	W9040-SNS/11/2023	ADMIN	741011	17-FEB-2023
6. A/C REG/MSN	7. A/C TYPE	8. TRADE	12. VENDOR ORDER #	
PK-SNS	C208B			
9. ZONE	10. STA	11. MTC TYPE		
ENGINE	NRX	REPLACEMENT		

13. DESCRIPTION/DEFECT-IF FINDING OF CPCP INSPECTION, PLEASE COMPLETE SET. 20	14	15
	PPC/ENG	DATE
R/H IGNITION CABLE WORN OUT		

16. CORRECTIVE ACTION	17	18	19
	MECH	ENG. LIC	DATE
REPLACED R/H IGNITION CABLE WITH NEW ONE, OPS CHECK SATISFACTORY REFF AMM: 742002 Performed at A/C TT: 3213:29..... A/C TC/LDG: 5273			17 FEB 2023

20. CORROSION INFORMATION			
LOCATION	CAUSE OF DAMAGE		
	☐ Environment		
	☐ Internal Leakage		
CORROSION ☐ Isolated ☐ Widespread	☐ Chemical Spill		
CORROSION LVL ☐ 1 ☐ 2 ☐ 3	☐ LAV/Galley Spill		
PROPOSED ACTION ☐ Doublers	☐ Blocked Drain		
☐ Others	☐ Wet Insulation Blanket		
☐ Other			
21. If the defect is RII, Please Sign this card finally by RII Inspector		INSP	DATE
NOTICE OF INSPECTOR			

22. PARTS REQUIRED						
PART DESCRIPTION	PART NO	QTY	SERIAL NO		STATUS	
			ON	OFF	CLOSE	OPEN
IGNITION LEAD	CH53309-02	1	NSN	NSN	✓	
23. TOOLS REQUIRED						
DESCRIPTION	PART NO. / MODEL	NEXT CALIBRATION DATE	STATUS			

	INSPECTION CARD (Form: SCA/MTC/ 048)	TECHNICAL DEPARTMENT
---	--	---------------------------------

1. CARD #	2. JO/WO #	3. ORIGINATOR	4. CARD REF	5. DATE
IC-002	W0/040-SNG/11/2023	AMIN	742002	17-FEB-2023
6. A/C REG/MSN	7. A/C TYPE	8. TRADE	12. VENDOR ORDER #	
PE-SNG	C7083			
9. ZONE	10. STA	11. MTC TYPE		
ENGINE	NB3	REPLACEMENT		

13. DESCRIPTION/DEFECT-IF FINDING OF CPCP INSPECTION, PLEASE COMPLETE SET. 20	14 PPC/ENG	15 DATE
R/H IGNITION WORN OUT	JWS	17/FEB 2023

16. CORRECTIVE ACTION	17 MECH	18 ENG. LIC	19 DATE
REPLACED R/H IGNITION WITH NEW ONE. OPS CHECK SATISFYING, REF AMM: 742002 Performed at A/C TT: 3213:23 A/C TC/LDG: 5273			17/FEB 2022

20. CORROSION INFORMATION			
LOCATION	CAUSE OF DAMAGE		
	☐ Environment		
	☐ Internal Leakage		
CORROSION ☐ Isolated ☐ Widespread	☐ Chemical Spill		
CORROSION LVL ☐ 1 ☐ 2 ☐ 3	☐ LAV/Galley Spill		
PROPOSED ACTION ☐ Doublers	☐ Blocked Drain		
☐ Others	☐ Wet Insulation Blanket		
	☐ Other		
21. If the defect is RII, Please Sign this card finally by RII Inspector		INSP	DATE
NOTICE OF INSPECTOR			

22. PARTS REQUIRED						
PART DESCRIPTION	PART NO	QTY	SERIAL NO		STATUS	
			ON	OFF	CLOSE	OPEN
IGNITOR	CH34055	1	NSN	NSN	✓	

23. TOOLS REQUIRED			
DESCRIPTION	PART NO. / MODEL	NEXT CALIBRATION DATE	STATUS



INSPECTION CARD

(Form: SCA/MTC/ 048)

TECHNICAL
DEPARTMENT

1. CARD #	2. JO/WO #	3. ORIGINATOR	4. CARD REF	5. DATE
IC-003	WO/040-SNG/11/2023	-	DIM 001	17-FEB-2023
6. A/C REG/MSN	7. A/C TYPE	8. TRADE	12. VENDOR ORDER #	
PF-SNG	C208B EX	AIRFRAME		
9. ZONE	10. STA	11. MTC TYPE		
LANDING GEAR	NASIRE	REPLACEMENT		

13. DESCRIPTION/DEFECT-IF FINDING OF CPCP INSPECTION, PLEASE COMPLETE SET. 20	14	15
	PPC/ENG	DATE
LH BACK PLATE BRAKE LINING WORN OUT		17/02/23
	FEBRI. H	

16. CORRECTIVE ACTION	17	18	19
	MECH	ENG. LIC	DATE
REPLACED LH BACK PLATE BRAKE LINING WITH A NEW ONE SAW C208 AMM CHAP 32-40-00			17/02/23
Performed at A/C TT : 3215:29 A/C TC /LDG : 5275			

20. CORROSION INFORMATION			
LOCATION	CAUSE OF DAMAGE		
	☐ Environment		
	☐ Internal Leakage		
CORROSION ☐ Isolated ☐ Widespread	☐ Chemical Spill		
CORROSION LVL ☐ 1 ☐ 2 ☐ 3	☐ LAV/Galley Spill		
PROPOSED ACTION ☐ Doublers	☐ Blocked Drain		
☐ Others	☐ Wet Insulation Blanket		
	☐ Other		
21. If the defect is RII, Please Sign this card finally by RII Inspector		INSP	DATE
NOTICE OF INSPECTOR			

22. PARTS REQUIRED						
PART DESCRIPTION	PART NO	QTY	SERIAL NO		STATUS	
			ON	OFF	CLOSE	OPEN
LINING	066-15500	4EA	NSW	NSW	☒	
23. TOOLS REQUIRED						
DESCRIPTION	PART NO. / MODEL	NEXT CALIBRATION DATE	STATUS			
MICROMETER	MDC - 1 PX	APRIL 2023	SERVICEABLE			
TORQUE WRENCH	TA 0250	NOV 2023	SERVICEABLE			

		INSPECTION CARD (Form: SCA/MTC/ 048)		TECHNICAL DEPARTMENT	
---	--	--	--	-------------------------	--

1. CARD #	2. JO/WO #	3. ORIGINATOR	4. CARD REF	5. DATE	
IC-004	WO/040-SNG/11/2023	Ann Amara	22-000	20- Feb- 2023	
6. A/C REG/MSN	7. A/C TYPE	8. TRADE	12. VENDOR ORDER #		
PH-SNG	CROSB EX				
9. ZONE	10. STA	11. MTC TYPE			
	NADIRE	REPLACEMENT			

13. DESCRIPTION/DEFECT-IF FINDING OF CPCP INSPECTION, PLEASE COMPLETE SET. 20	14	15
	PPC/ENG	DATE
SWITCH AUTOPILOT DISCONNECT BROKEN (PILOT SIDE)		20-FEB-23

16. CORRECTIVE ACTION	17	18	19
	MECH	ENG. LIC	DATE
REPLACED SWITCH AUTOPILOT DISCONNECT WITH A NEW ONE IN CROSB AMM CHAP 22-12-00 Performed at A/C TT : 3213:20 A/C TC /LDG : 5293			20-FEB-23

20. CORROSION INFORMATION					
LOCATION	CAUSE OF DAMAGE				
	☐ Environment ☐ Internal Leakage ☐ Chemical Spill ☐ LAV/Galley Spill ☐ Blocked Drain ☐ Wet Insulation Blanket ☐ Other				
CORROSION ☐ Isolated ☐ Widespread					
CORROSION LVL ☐ 1 ☐ 2 ☐ 3					
PROPOSED ACTION ☐ Doublers ☐ Others					
21. If the defect is RII, Please Sign this card finally by RII Inspector				INSP	DATE
NOTICE OF INSPECTOR					

22. PARTS REQUIRED						
PART DESCRIPTION	PART NO	QTY	SERIAL NO		STATUS	
			ON	OFF	CLOSE	OPEN
SWITCH	031-00428-0000	1 EA	ASN	ASN	✓	

23. TOOLS REQUIRED			
DESCRIPTION	PART NO. / MODEL	NEXT CALIBRATION DATE	STATUS
GENERAL TOOL	ASN	O/C	GOOD



INSPECTION CARD

(Form: SCA/MTC/ 048)

TECHNICAL
DEPARTMENT

1. CARD #	2. JO/WO #	3. ORIGINATOR	4. CARD REF	5. DATE
IC-005	WO/040-SNG/11/2023	Ann Andika	324000	20-FEB-2023
6. A/C REG/MSN	7. A/C TYPE	8. TRADE	12. VENDOR ORDER #	
PF-SNG	C708B EX			
9. ZONE	10. STA	11. MTC TYPE		
LANDING GEAR	NABIRE	REPLACEMENT		

13. DESCRIPTION/DEFECT-IF FINDING OF CPCP INSPECTION, PLEASE COMPLETE SET. 20	14	15
	PPC/ENG	DATE
LH MAIN TIRE WORK OUT		20/02/23

16. CORRECTIVE ACTION	17	18	19
	MECH	ENG. LIC	DATE
REPLACED LH MAIN TIRE ASSY WITH A NEW 1AW C708B AMM CHAP 32-40-00			20/02/23
Performed at A/C TT : 2213:29 A/C TC /LDG : 5273			

20. CORROSION INFORMATION			
LOCATION	CAUSE OF DAMAGE		
	☐ Environment		
	☐ Internal Leakage		
CORROSION ☐ Isolated ☐ Widespread	☐ Chemical Spill		
CORROSION LVL ☐ 1 ☐ 2 ☐ 3	☐ LAV/Galley Spill		
PROPOSED ACTION ☐ Doublers	☐ Blocked Drain		
☐ Others	☐ Wet Insulation Blanket		
	☐ Other		
21. If the defect is RII, Please Sign this card finally by RII Inspector		INSP	DATE
NOTICE OF INSPECTOR			

22. PARTS REQUIRED						
PART DESCRIPTION	PART NO	QTY	SERIAL NO		STATUS	
			ON	OFF	CLOSE	OPEN
MAIN TIRE	070-446-1	1	1177 T00184	1175 T00160	✓	
INNER TUBE	GL-29150B	1			✓	

23. TOOLS REQUIRED			
DESCRIPTION	PART NO. / MODEL	NEXT CALIBRATION DATE	STATUS
TORQUE WRENCH	TA-0250	NOV 2023	SERVICEABLE



INSPECTION CARD

(Form: SCA/MTC/ 048)

TECHNICAL
DEPARTMENT

1. CARD #	2. JO/WO #	3. ORIGINATOR	4. CARD REF	5. DATE
1C-006	WO/040-ENG/11/2013	-	322000	17- Feb - 2023
6. A/C REG/MSN	7. A/C TYPE	8. TRADE	12. VENDOR ORDER #	
PK-ENG	C208B EX	AIRFRAME		
9. ZONE	10. STA	11. MTC TYPE		
	NABIRE	REPLACEMENT		

13. DESCRIPTION/DEFECT-IF FINDING OF CPCP INSPECTION, PLEASE COMPLETE SET. 20	14	15
	PPC/ENG	DATE
BOLT MPI NOSE GEAR NEED TO REPLACE	<i>[Signature]</i> FERRI.H	17/02/23

16. CORRECTIVE ACTION	17	18	19
	MECH	ENG. LIC	DATE
REPLACED BOLT MPI NOSE GEAR WITH A NEW 1AW C208B AMM CHAP 32-20-00		<i>[Signature]</i> 09	17/02/23
Performed at A/C TT : 3213:29 A/C TC /LDG : 5273			

20. CORROSION INFORMATION			
LOCATION	CAUSE OF DAMAGE		
	☐ Environment		
	☐ Internal Leakage		
CORROSION ☐ Isolated ☐ Widespread	☐ Chemical Spill		
CORROSION LVL ☐ 1 ☐ 2 ☐ 3	☐ LAV/Galley Spill		
PROPOSED ACTION ☐ Doublers	☐ Blocked Drain		
☐ Others	☐ Wet Insulation Blanket		
	☐ Other		
21. If the defect is RII, Please Sign this card finally by RII Inspector		INSP	DATE
NOTICE OF INSPECTOR			

22. PARTS REQUIRED						
PART DESCRIPTION	PART NO	QTY	SERIAL NO		STATUS	
			ON	OFF	CLOSE	OPEN
BOLT	S3461-88	2 EA	NSN	NSN	✓	
23. TOOLS REQUIRED						
DESCRIPTION	PART NO. / MODEL	NEXT CALIBRATION DATE	STATUS			
TORQUE WRENCH	TA-0250	NOV - 2023	SERVICEABLE			



INSPECTION CARD

(Form: SCA/MTC/ 048)

TECHNICAL
DEPARTMENT

1. CARD #	2. JO/WO #	3. ORIGINATOR	4. CARD REF	5. DATE
IC-007	WO/040-SNG/11/2023	-	332000	17 Feb - 2023
6. A/C REG/MSN	7. A/C TYPE	8. TRADE	12. VENDOR ORDER #	
PC-SNG	C208R EX	AIRFRAME		
9. ZONE	10. STA	11. MTC TYPE		
	MARSURE	REPLACEMENT		

13. DESCRIPTION/DEFECT-IF FINDING OF CPCP INSPECTION, PLEASE COMPLETE SET. 20	14 PPC/ENG	15 DATE
NOSE GEAR SPRING YOKE SPRING ² BEARING BROKEN	 FEB 17/23	17/02/23

16. CORRECTIVE ACTION	17 MECH	18 ENG. LIC	19 DATE
REPLACED NOSE GEAR SPRING YOKE BEARING WITH A NEW ONE 1AW C208 B AMM CHAP 32-20-00 Performed at A/C TT : 3213:29 A/C TC /LDG : 5273		 	17/02/23

20. CORROSION INFORMATION			
LOCATION	CAUSE OF DAMAGE		
	☐ Environment		
	☐ Internal Leakage		
CORROSION ☐ Isolated ☐ Widespread	☐ Chemical Spill		
CORROSION LVL ☐ 1 ☐ 2 ☐ 3	☐ LAV/Galley Spill		
PROPOSED ACTION ☐ Doublers	☐ Blocked Drain		
☐ Others	☐ Wet Insulation Blanket		
	☐ Other		
21. If the defect is RII, Please Sign this card finally by RII Inspector		INSP	DATE
NOTICE OF INSPECTOR			

22. PARTS REQUIRED						
PART DESCRIPTION	PART NO	QTY	SERIAL NO		STATUS	
			ON	OFF	CLOSE	OPEN
BEARING	MS24462-5	1 EA	NSN	NSN	✓	

23. TOOLS REQUIRED			
DESCRIPTION	PART NO. / MODEL	NEXT CALIBRATION DATE	STATUS
GENERAL TOOL	NPW	9/2	GOOD



SUMMARY INSPECTION ITEMS (Form: SCA/MTC/050)

WO Ref: WO/040-SNG/II/2023

NO.	TASK CARD NO.	DESCRIPTION	DATE	EST MHR	NAME	STAMP
1	APPENDIX D08	PT6A-ENGINE GROUND RUN	20/02/23		Azz	
2	APPENDIX C09	1600 HRS/24 MTHS INSPECTION	20/2023 FEB		FEBRI HERMAWAN	
3	APPENDIX C09	1600 HRS/60 MTHS INSPECTION	19/02/23		Azz	
4	APPENDIX C06	800 HRS/24 MTHS INSPECTION	19/02/23		Azz	
5	APPENDIX C07	800 HRS/12 MTHS INSPECTION	18/02/23		DENI	
6	APPENDIX C04	400 HRS/24 MTHS INSPECTION	18/2023 FEB		FEBRI HERMAWAN	
7	APPENDIX C05	400 HRS/12 MTHS INSPECTION	18/02/23		DENI	
8	APPENDIX C03	200 HRS/12 MTHS INSPECTION	18/02/23		DENI	
9	APPENDIX D12	PT6A-140 600 HRS ENGINE	20/02/23		Azz	
10	APPENDIX D11	PT6A-140 400 HRS ENGINE	20/02/23		Azz	
11	APPENDIX D10	PT6A-140 200 HRS/6 MTHS ENGINE	18/02/23		ARJJI	
12	APPENDIX D09	PT6A-140 200 HRS ENGINE	18/02/23		ARJJI	
13	APPENDIX D08	PT6A-140 100 HRS ENGINE	20/02/23		Azz	
14	NRC-01	VACUUM FILTER REPLACEMENT	18/02/23		Azz	
15	NRC-02	CENTRAL AIR FILTER REPLACEMENT	18/02/23		Azz	
16	SCA/MTC/023	EMERGENCY EQUIPMENT LIST	20/02/23		Azz	



MAINTENANCE PROGRAM CESSNA 208/208B

Appendix B08 – PT6A-140 Engine Run Performance Sheet

Reg. Mark : PK - SN6

WO/FML No. : WO/040-246/11/2023

PRE – INSPECTION	
Location	NABIRE
Date	16 Feb 2023
Cycle	-
Filed Barometric	1007
OAT	32 °C
Altitude	70 ft

POST – INSPECTION	
Location	NABIRE
Date	20 Feb 2023
Cycle	-
Filed Barometric	1007
OAT	37 °C
Altitude	60 ft

PRE – INSPECTION		
	Target	Actual
Tq	2397	2397
Np	1900	1880
ITT	841 °C	824 °C
Ng	102.7 %	100.3 %
Wf	578	542
Oil Press		92 °C
Oil Temp		68 °C
Start Temp		633 °C

POST – INSPECTION		
	Target	Actual
Tq	2397	2397
Np	1900	1870
ITT	843 °C	823 °C
Ng	102.6 %	100.5 %
Wf	560	537
Oil Press		90 °C
Oil Temp		78 °C
Start Temp		687 °C

Engine Run Up Checks							
<u>Inertial</u> ☒	<u>EPL</u> ☒	<u>OVG</u> ☒	<u>Stby Alt</u> ☒	<u>BOV</u> ☒	<u>Brake</u> ☒	<u>Random</u> ☒	
NOTE: 1. Brake system at Torque 2000 ft-lbs. 3. EPL check can't exceed 4% Ng per second. 5. Low idle at 55.5 - 57% 40Amps. 2. Inertial Separator at Torque 400 ft-lbs. 4. Standby Alt at 80% Ng. 6. High idle at 64 - 66% Ng 40Amps							

Engine Performance Target Table (Cessna C208B EX)

OAT (°C)	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41
Tq (ft.lbs)	2397	2397	2397	2397	2397	2397	2397	2397	2397	2397	2397	2397	2397	2397	2397
Np	1900	1900	1900	1900	1900	1900	1900	1900	1900	1900	1900	1900	1900	1900	1900
ITT (°C)	835	837	839	841	841	841	841	841	841	842	843	844	846	846	846
Ng (%)	102.7	102.7	102.7	102.7	102.7	102.7	102.7	102.6	102.6	102.6	102.6	102.6	102.6	102.6	102.5
WF (PPH)	578	578	578	578	578	578	578	570	565	565	560	560	555	548	548

Note:

1. Make sure that inertial separator in normal condition, no bleed air extracted from the engine and air condition OFF.
2. This table only applies to altitude 0-500 feet MSL. For higher altitude, refer to EMM 72-00-00.
3. Max fuel flow is 580 lb/hr fuel flow is not more than 15 lbs/hr higher than the value shown in table.
4. If parameters are outside the target performance table to EMM chapter 71-00-00.

REMARKS:

ENGINE PARAMETER WITHIN LIMIT

PERFORMED BY

Name	Sign & Stamp	Date	Location
M. Aziz A		20 Feb 2023	NABIRE



EMERGENCY EQUIPMENT LIST INSPECTION & MONITOR

**PT. SMART CAKRAWALA
AVIATION
DEPARTMENT TEKNIK
Form: SCA/MTC/023**

DATE : 20 - Feb - 2023

A/C REG : PK-SNG

A/C TYPE : C208B

CHECKER : Azul Andika **SIGN:**

No.	Description	P/N	S/N	Next Insp.	Remarks
1	Pilot Life Vest	P01202 - 201	19092030036	JAN - 2029	SERVICEABLE
2	Co-Pilot Life Vest	P01202 - 201	19092030051	JAN - 2029	SERVICEABLE
3	Pax Life Vest				
4	Pax Life Vest				
5	Pax Life Vest				
6	Pax Life Vest				
7	Pax Life Vest				
8	Pax Life Vest				
9	Pax Life Vest				
10	Pax Life Vest				
11	Pax Life Vest				
12	Pax Life Vest				
13	Firt Aid Kit	NPW	NSN	JUNE - 2023	SERVICEABLE
14	Crash Axe Installed	NPW	NSN	O/C	SERVICEABLE
15	Fire Extinguisher	C362	F60589352	SEP 2023	SERVICEABLE
16	Life Raft (If Installed)				
17	Survival Kit (If Installed)				
OTHERS					



Aircraft Registration: **PK-SNG**

WO# Nr.: WO/040-SNG/II/2023

Additional Work Sheet

Inspection 1600 Hours &

Additional Task

Part Used

Parts Used Sheet

[illegible]



Additional Work Sheet
Inspection 1600 Hours &
Additional Task
Parts Used Sheet

Special Tool Used

[illegible]