



PT. SMART CAKRAWALA AVIATION

WORK ORDER

Form: SCA/MTC/030

Subject : Out of Phase – Update Navigation Database	No.	WO/042-PK-SNP/V/2023
	Date	18 May 2023
	A/C Reg.	PK-SNP C208B-5495
Reference : MP C208B Issued 01	Prepared By	TS
	Checked By	CI
	Approved By	TM

To : Engineer In Charge

Description :

1. Perform Out of Phase – Update Navigation Database due at 18 May 2023
2. Make an entry in Maintenance Log.
3. Return the Completed Work Order and Form to PPC.

#If any finding, please close the routine card, and transferred to inspection card.

Additional Work :

-NIL-

Compliance Statement	Sign & Date Company Lic. No.:	Signature
Carried Out	 25 May 2023. (Engineer In Charge)	 (Technical Manager)

Appendix B - Form: SCA/MTC/030

AIRCRAFT CHECK WORK SUMMARY
(Form: SCA/MTC/051)

DATE OF ISSUED	JO/WO #	TYPE OF MAINTENANCE	DATE OF ACCOMPLISHED	
16 May 2023	WO/042-PK-SNP/VI/2023	Update Navigation Database	25 May 2023.	
A/C Type		Mfg. Serial Number	A/C Registration	
C208B		C208B-5495	PK-SNP	
AIRCRAFT DATA				
Subject	Pos #	Serial Number (SN)	TTSN/TCSN	
Engine	#1	PCE-VA0723	4771:14 / 7983.	
	#2	-		
Propeller/Rotor	#1	181158	4771:14 / 7983.	
	#2	-		
Landing Gear	NLG		4771:14 / 7983	
	LH MLG		4771:14 / 7983	
	RH MLG		4771:14 / 7983.	
PACKAGE COVERED				
No	Subject	Qty	Remark	
1	Non-Routine Card	-		
2	Inspection Card	1	✓	
3	Work Order	1	✓	
4	Summary Inspection List	1	✓	
5	Material and Tool List	-		
6	Escalation form	-		
7	CRS (SMI / Unscheduled Maintenance)	1	✓	
INSPECTION CARD (IC) LIST (Finding during maintenance)				
No	Taskcard Ref	Subject	Status	Name/ Sign & Stamp
			Open	Close
<u>IC-001</u>				
<u>IC-002</u>				
<u>IC-003</u>				
<u>IC-004</u>				
<u>IC-005</u>				
<u>IC-006</u>				

<u>IC-007</u>					
<u>IC-008</u>					
<u>IC-009</u>					
<u>IC-010</u>					
<u>IC-011</u>					
<u>IC-012</u>					
<u>IC-013</u>					
<u>IC-014</u>					
<u>IC-015</u>					

Prepared by :
Technical Support

Checked by :
Chief Maintenance

Verified by :
Chief Inspector

Approved by :
Technical Manager


.....
Dwi M


.....
Dodit


.....
Yanuar


.....
Istiono



SUMMARY INSPECTION ITEMS
(Form: SCA/MTC/050)

WO Ref: WO/042-PK-SNP/V/2023

NO.	TASK CARD NO.	DESCRIPTION	DATE	EST MHR	NAME	STAMP
1	APPENDIX C01	OOP34001 / UPDATED NAVIGATION DATABASE	25/05/2023	095/14.01	Angga P.	



PT. SMART CAKRAWALA AVIATION

CERTIFICATE RETURN TO SERVICE
SCHEDULED MAINTENANCE INSPECTION
(CRS-SMI)

A/C TYPE : CESSNA 208B TTSN : 4771:14
A/C REG : PK-SNP TCSN : 7983.
MSN : C208B-5495 DATE : 25 May 2023.

TYPE OF INSPECTION : OUT OF PHASE - UPDATE NAVIGATION DATABASE
DUE AT : 18 May 2023
REF : MP C208B Issued 01

EXCEPTION

- No Exception -

AUTHORIZED PERSON

I hereby certify that this aircraft has been maintained accordance with CASR and Maintenance Program.
Aircraft safe and airworthy for flight

NAME	CAT	AMEL/OTR NO	SIGN&STAMP	DATE
D. Arya Permana	AIRFRAME & POWER PLANT	9505/031		25 May 2023
	EIRA			

THE NEXT DUE TYPE OF INSPECTION : Update - Navigation Data Base.
DUE AT : 15 June 2023 .

Form: SCA/MTC/049

	INSPECTION CARD (Form: SCA/MTC/ 048)	TECHNICAL DEPARTMENT
---	--	---------------------------------

1. CARD #	2. JO/WO #	3. ORIGINATOR	4. CARD REF	5. DATE
6. A/C REG/MSN	7. A/C TYPE	8. TRADE	12. VENDOR ORDER #	
9. ZONE	10. STA	11. MTC TYPE		

13. DESCRIPTION/DEFECT-IF FINDING OF CPCP INSPECTION, PLEASE COMPLETE SET. 20	14 PPC/ENG	15 DATE

16. CORRECTIVE ACTION	17 MECH	18 ENG. LIC	19 DATE																								
Performed at A/C TT : A/C TC /LDG : 20. CORROSION INFORMATION <table style="width: 100%; border: none;"> <tr> <td style="width: 40%;">LOCATION</td> <td style="width: 20%;">CAUSE OF DAMAGE</td> <td style="width: 40%;"></td> </tr> <tr> <td></td> <td>☐ Environment</td> <td></td> </tr> <tr> <td></td> <td>☐ Internal Leakage</td> <td></td> </tr> <tr> <td>CORROSION ☐ Isolated ☐ Widespread</td> <td>☐ Chemical Spill</td> <td></td> </tr> <tr> <td>CORROSION LVL ☐ 1 ☐ 2 ☐ 3</td> <td>☐ LAV/Galley Spill</td> <td></td> </tr> <tr> <td>PROPOSED ACTION ☐ Doublers</td> <td>☐ Blocked Drain</td> <td></td> </tr> <tr> <td>☐ Others</td> <td>☐ Wet Insulation Blanket</td> <td></td> </tr> <tr> <td></td> <td>☐ Other</td> <td></td> </tr> </table>	LOCATION	CAUSE OF DAMAGE			☐ Environment			☐ Internal Leakage		CORROSION ☐ Isolated ☐ Widespread	☐ Chemical Spill		CORROSION LVL ☐ 1 ☐ 2 ☐ 3	☐ LAV/Galley Spill		PROPOSED ACTION ☐ Doublers	☐ Blocked Drain		☐ Others	☐ Wet Insulation Blanket			☐ Other				
LOCATION	CAUSE OF DAMAGE																										
	☐ Environment																										
	☐ Internal Leakage																										
CORROSION ☐ Isolated ☐ Widespread	☐ Chemical Spill																										
CORROSION LVL ☐ 1 ☐ 2 ☐ 3	☐ LAV/Galley Spill																										
PROPOSED ACTION ☐ Doublers	☐ Blocked Drain																										
☐ Others	☐ Wet Insulation Blanket																										
	☐ Other																										

21. If the defect is RII, Please Sign this card finally by RII Inspector	INSP	DATE
NOTICE OF INSPECTOR		


22. PARTS REQUIRED						
PART DESCRIPTION	PART NO	QTY	SERIAL NO		STATUS	
			ON	OFF	CLOSE	OPEN


23. TOOLS REQUIRED			
DESCRIPTION	PART NO. / MODEL	NEXT CALIBRATION DATE	STATUS

Appendix C01 – OOP34001 / Update Navigation Database

Reg. Mark : PK - SNP Date : 25 May 2023.
 MSN : C208B-5495 Station : TIM.
 TSN / CSN : 4771:14 / 7983. WO No. : WO/042-PK-SNP/V/2023

NO.	ZONE	TASK	SIGNATURE	
			SIGN	STAMP
01	211 212	Update Navigation Database. • G1000 Line Maintenance Manual, Doc. No. 190-00869-00, Rev. G. • G1000 NXi Supplemental Maintenance Manual, Doc. No. 190-02128-04, Rev. 3		
*** End of Appendix C01 Items ***				

PERSONNEL PARTICIPATING IN THIS INSPECTION			
NAME	POSITION	SIGNATURE	LICENSE NUMBER
<u>Aryu P.</u>	<u>Engineer</u>		<u>9505</u>
<u>Kristadi. H</u>	<u>Mechanic</u>	<u>Jus.</u>	

RETURN TO SERVICE			
The work recorded above has been carried out in accordance with the requirements of the Civil Aviation Safety Regulation for the time being in force and in that respect the aircraft is consider fit for Release to Service.			
Name	: <u>D. Aryu Permana.</u>	Stamp	: 
Signature	: 	Place/Date	: <u>TIM / 25 May 2023</u>