





PT. SMART CAKRAWALA AVIATION

WORK ORDER

Form: SCA/MTC/030

Subject : Out of Phase – Update Navigation Database	No.	WO/043-PK-SNV/V/2023
	Date	16 May 2023
	A/C Reg.	PK-SNV C208-5551
Reference : MP C208B Issued 01	Prepared By	TS
	Checked By	CI
	Approved By	TM
To : Engineer In Charge		
<p>Description :</p> <ol style="list-style-type: none">1. Perform Out of Phase – Update Navigation Database due at 18 May 20232. Make an entry in Maintenance Log.3. Return the Completed Work Order and Form to PPC. <p>#If any finding, please close the routine card, and transferred to inspection card.</p>		
<p>Additional Work :</p> <p>- NIL -</p>		
Compliance Statement UPDATE NAVIGATION DATABASE c/o	Sign & Date Company Lic. No.:  (Engineer In Charge) HENDRO	Signature  (Technical Manager)


Appendix B - Form: SCA/MTC/030

AIRCRAFT CHECK WORK SUMMARY
(Form: SCA/MTC/051)

DATE OF ISSUED	JO/WO #	TYPE OF MAINTENANCE	DATE OF ACCOMPLISHED		
16 May 2023	WO/041-PK-SNVV/2023	Update Navigation Database	25 MAY 2023		
A/C Type	Mfg. Serial Number	A/C Registration			
C208	C208-5551	PK-SNV			
AIRCRAFT DATA					
Subject	Pos #	Serial Number (SN)	TTSN/TCSN		
Engine	#1	PCE-VA0607	3599:05 / 5830		
	#2	-			
Propeller/Rotor	#1	181160	3599:05 / 3599:05		
	#2	-			
Landing Gear	NLG		5830 / 5830		
	LH MLG		5830 / 5830		
	RH MLG		5830 / 5830		
PACKAGE COVERED					
No	Subject	Qty	Remark		
1	Non-Routine Card	-			
2	Inspection Card	1	✓		
3	Work Order	1	✓		
4	Summary Inspection List	1	✓		
5	Material and Tool List	-			
6	Escalation form	-			
7	CRS (SMI / Unscheduled Maintenance)	1	✓		
INSPECTION CARD (IC) LIST (Finding during maintenance)					
No	Taskcard Ref	Subject	Status		Name/ Sign & Stamp
			Open	Close	
<u>IC-001</u>	—	—	—	—	—
<u>IC-002</u>					
<u>IC-003</u>					
<u>IC-004</u>					
<u>IC-005</u>					
<u>IC-006</u>					

<u>IC-007</u>					
<u>IC-008</u>					
<u>IC-009</u>					
<u>IC-010</u>					
<u>IC-011</u>					
<u>IC-012</u>					
<u>IC-013</u>					
<u>IC-014</u>					
<u>IC-015</u>					

Prepared by :
Technical Support



Dwi M

Checked by :
Chief Maintenance



Dodit

Verified by :
Chief Inspector



Yanuar

Approved by :
Technical Manager



Istiono



SUMMARY INSPECTION ITEMS
(Form: SCA/MTC/050)

WO Ref: WO/043-PK-SNV/V/2023

NO.	TASK CARD NO.	DESCRIPTION	DATE	EST MHR	NAME	STAMP
1	APPENDIX C01	OOP34001 / UPDATED NAVIGATION DATABASE	25 MAY 23	0.5 MHR	HENDRO	



PT. SMART CAKRAWALA AVIATION

CERTIFICATE RETURN TO SERVICE

SCHEDULED MAINTENANCE INSPECTION (CRS-SMI)

A/C TYPE : CESSNA 208
A/C REG : PK-SNV
MSN : C208-5551

TTSN : 3509:05
TCSN : 5830
DATE : 25 MAY 2023

TYPE OF INSPECTION : OUT OF PHASE - UPDATE NAVIGATION DATABASE
DUE AT : 18 May 2023
REF : MP C208 Issued 01

EXCEPTION

- No exception -


AUTHORIZED PERSON

I hereby certify that this aircraft has been maintained accordance with CASR and Maintenance Program.
Aircraft safe and airworthy for flight

NAME	CAT	AMEL/OTR NO	SIGN&STAMP	DATE
HENDRO	AIRFRAME & POWER PLANT	5583 / 28	Hendro [Stamp: 28]	25-MAY-23
	EIRA	—	—	

THE NEXT DUE TYPE OF INSPECTION : UP DATE NAVIGATION DATABASE
DUE AT : 15 JUNE 2023

Form: SCA/MTC/049

		INSPECTION CARD (Form: SCA/MTC/ 048)			TECHNICAL DEPARTMENT	
---	--	--	--	--	-------------------------	--

1. CARD #	2. JO/WO #	3. ORIGINATOR	4. CARD REF	5. DATE	
—	—	—	—	—	
6. A/C REG/MSN	7. A/C TYPE	8. TRADE	12. VENDOR ORDER #		
—	—	—	—		
9. ZONE	10. STA	11. MTC TYPE			
—	—	—			

13. DESCRIPTION/DEFECT-IF FINDING OF CPCP INSPECTION, PLEASE COMPLETE SET. 20	14	15
	PPC/ENG	DATE
—		

16. CORRECTIVE ACTION	17	18	19
	MECH	ENG. LIC	DATE
—			
Performed at A/C TT : A/C TC /LDG :			



20. CORROSION INFORMATION					
LOCATION	CAUSE OF DAMAGE				
	<input type="checkbox"/> Environment				
	<input type="checkbox"/> Internal Leakage				
CORROSION <input type="checkbox"/> Isolated <input type="checkbox"/> Widespread	<input type="checkbox"/> Chemical Spill				
CORROSION LVL <input type="checkbox"/> 1 <input type="checkbox"/> 2 <input type="checkbox"/> 3	<input type="checkbox"/> LAV/Galley Spill				
PROPOSED ACTION <input type="checkbox"/> Doublers	<input type="checkbox"/> Blocked Drain				
<input type="checkbox"/> Others	<input type="checkbox"/> Wet Insulation Blanket				
	<input type="checkbox"/> Other				
21. If the defect is RII, Please Sign this card finally by RII Inspector				INSP	DATE
NOTICE OF INSPECTOR					


22. PARTS REQUIRED						
PART DESCRIPTION	PART NO	QTY	SERIAL NO		STATUS	
			ON	OFF	CLOSE	OPEN

23. TOOLS REQUIRED			
DESCRIPTION	PART NO. / MODEL	NEXT CALIBRATION DATE	STATUS

Appendix C01 – OOP34001 / Update Navigation Database

Reg. Mark	: PK - SNV	Date	: 25 May 2023
MSN	: C208-5551	Station	: TAPAKAN
TSN / CSN	: 3509 : 05 / 5830	WO No.	: WO/043-PK-SNV/V/2023

NO.	ZONE	TASK	SIGNATURE	
			SIGN	STAMP
01	211	Update Navigation Database.		
	212	<ul style="list-style-type: none">• G1000 Line Maintenance Manual, Doc. No. 190-00869-00, Rev. G.• G1000 NXI Supplemental Maintenance Manual, Doc. No. 190-02128-04, Rev. 3		
*** End of Appendix C01 Items ***				

PERSONNEL PARTICIPATING IN THIS INSPECTION			
NAME	POSITION	SIGNATURE	LICENSE NUMBER
HENDRO	ENGINEER		6583

RETURN TO SERVICE

The work recorded above has been carried out in accordance with the requirements of the Civil Aviation Safety Regulation for the time being in force and in that respect the aircraft is consider fit for Release to Service.

Name	: 	Stamp	: 
Signature	: 	Place/Date	: TAPAKAN / 25 MAY 2023