



PT. SMART CAKRAWALA AVIATION

WORK ORDER

Form: SCA/MTC/030

Subject : Inspection Document 06 & Add Task Due at 2200 FH.	No.	WO/044-SNH/III/2022
	Date	01-Mar-2022
	A/C Reg.	PK-SNH C208B-5587
Reference : MP C208B Rev. 10	Prepared By	TS
	Checked By	CI
	Approved By	TM

To : Engineer In Charge

Description :

1. Perform Inspection Document 06 & Add Task Due at 2200 Hours.
2. Make an entry in Maintenance Log.
3. Return the Completed Work Order and Form to PPC.

#If any finding, please close the routine card, and transferred to inspection card.

Additional Work :

Compliance
Statement

CARRIED
OUT

Sign & Date
Company Lic. No.:

06-03-2022

(Engineer In Charge)



Signature

(Technical Manager)

AIRCRAFT CHECK WORK SUMMARY
(Form: SCA/MTC/051)

DATE OF ISSUED	JO/WO #	TYPE OF MAINTENANCE	DATE OF ACCOMPLISHED		
01-March-2022	WO/044-SNH/III/2022	Inspection Doc. 06 & Add Task	06-MAR-2022		
A/C Type		Mfg. Serial Number	A/C Registration		
C208B		C208B-5587	PK-SNH		
AIRCRAFT DATA					
Subject	Pos #	Serial Number (SN)	TTSN/TCSN		
Engine	#1	PCE-VA0662	2194:16 / 3228		
	#2	-			
Propeller/Rotor	#1	190837	2194:16 / 3228		
	#2	-			
Landing Gear	NLG				
	LH MLG				
	RH MLG				
PACKAGE COVERED					
No	Subject	Qty	Remark		
1	Non-Routine Card	-			
2	Inspection Card	1			
3	Work Order	1			
4	Summary Inspection List	1			
5	Material and Tool List	-			
6	Escalation form	-			
7	CRS (SMI / Unscheduled Maintenance)	1			
INSPECTION CARD (IC) LIST (Finding during maintenance)					
No	Taskcard Ref	Subject	Status		Name/ Sign & Stamp
			Open	Close	
<u>IC-001</u>					
<u>IC-002</u>					
<u>IC-003</u>					
<u>IC-004</u>					
<u>IC-005</u>					
<u>IC-006</u>					

<u>IC-007</u>					
<u>IC-008</u>					
<u>IC-009</u>					
<u>IC-010</u>					
<u>IC-011</u>					
<u>IC-012</u>					
<u>IC-013</u>					
<u>IC-014</u>					
<u>IC-015</u>					

Prepared by :
Technical Support

Checked by :
Chief Maintenance

Verified by :
Chief Inspector

Approved by :
Technical Manager

.....

.....

.....

.....



SUMMARY INSPECTION ITEMS (Form: SCA/MTC/050)

WO Ref: WO/044-SNH/III/2022

NO.	TASK CARD NO.	DESCRIPTION	DATE	EST MHR	NAME	STAMP
1	B03	PT6A-140 ENGINE GROUND RUN PERFORMANCE	06/03-22		NINDO	
2	CHAPTER 07	INSPECTION DOCUMENT 01	06/03-22		NINDO	
3	CHAPTER 08	INSPECTION DOCUMENT 02	06/03-22		NINDO	
4	CHAPTER 12	INSPECTION DOCUMENT 06	06/03-22		NINDO	
5	CHAPTER 51	ENGINE PT6A-140 100 HOUR INSPECTION/ MINOR INSPECTION	06/03-22		NINDO	
6	CHAPTER 52	ENGINE PT6A-140 200 HOUR INSPECTION	06/03-22		NINDO	
7	CHAPTER 53	ENGINE PT6A-140 200 HOUR / 6 MONTHS INSPECTION	06/03-22		NINDO	
8	SCA/MTC/023	EMERGENCY EQUIPMENT CHECK	06/03-22		NINDO	



PT. SMART CAKRAWALA AVIATION

CERTIFICATE RETURN TO SERVICE

SCHEDULED MAINTENANCE INSPECTION (CRS-SMI)

A/C TYPE	: CESSNA 208B	TTSN	: 2194:16
A/C REG	: PK-SNH	TCSN	: 3228
MSN	: C208B-5587	DATE	: 06-03-2022

TYPE OF INSPECTION	: INSPECTION DOCUMENT 06 & ADD TASK
DUE AT	: 2200 HOURS
REFF	: MP C208B REV. 10

EXCEPTION

NIL

AUTHORIZED PERSON

I hereby certify that this aircraft has been maintained accordance with CASR and Maintenance Program.
Aircraft safe and airworthy for flight

NAME	CAT	AMEL/OTR NO	SIGN&STAMP	DATE
ROHPININDO.N.S.P	AIRFRAME & POWER PLANT	9634 / SCA11		06/03-2022
	EIRA			

THE NEXT DUE TYPE OF INSPECTION	: 100 HRS INSP
DUE AT	: 2300:00

Form: SCA/MTC/049

		INSPECTION CARD (Form: SCA/MTC/ 048)			TECHNICAL DEPARTMENT	
1. CARD #	2. JO/WO #	3. ORIGINATOR	4. CARD REF	5. DATE		
001	WO/044-SMH/14/2022		32-40-00	06-03-2022		
6. A/C REG/MSN	7. A/C TYPE	8. TRADE	12. VENDOR ORDER #			
PK-SMH	C208B-EX					
9. ZONE	10. STA	11. MTC TYPE				
	DJJ					

13. DESCRIPTION/DEFECT-IF FINDING OF CPCP INSPECTION, PLEASE COMPLETE SET. 20	14	15
	PPC/ENG	DATE
R/H MAIN WHEEL TIRE FOUND SPOT. MAIN WHEEL TIRE NEED TO BE REPLACE		06/03-22

16. CORRECTIVE ACTION	17	18	19
	MECH	ENG. LIC	DATE
REPLACED R/H MAIN WHEEL TIRE WITH NEW MSY IAW C208B ANM CH 32-40-00 Performed at A/C TT : 2194.16 A/C TC /LDG : 3228	-		06/03-22

20. CORROSION INFORMATION			
LOCATION	CAUSE OF DAMAGE		
	☐ Environment ☐ Internal Leakage ☐ Chemical Spill ☐ LAV/Galley Spill ☐ Blocked Drain ☐ Wet Insulation Blanket ☐ Other		
CORROSION ☐ Isolated ☐ Widespread CORROSION LVL ☐ 1 ☐ 2 ☐ 3 PROPOSED ACTION ☐ Doublers ☐ Others			
21. If the defect is RII, Please Sign this card finally by RII Inspector		INSP	DATE
NOTICE OF INSPECTOR			

22. PARTS REQUIRED						
PART DESCRIPTION	PART NO	QTY	SERIAL NO		STATUS	
			ON	OFF	CLOSE	OPEN
MAIN WHEEL COTTER PIN	078-446-1	1 MSY	1197100167	1196700134	✓	—
	MS 24665-362	1 CA	MSN	MSN	✓	—

23. TOOLS REQUIRED			
DESCRIPTION	PART NO. / MODEL	NEXT CALIBRATION DATE	STATUS

Appendix B03 – PT6A-140 Engine Run Performance Sheet

Reg. Mark : PK - SNH

WO/FML No. : WO/044-SNH/11/2022

PRE – INSPECTION	
Location	
Date	
Cycle	
Filed Barometric	
OAT	
Altitude	

POST – INSPECTION	
Location	DJJ
Date	06-03-2022
Cycle	
Filed Barometric	1003
OAT	32°C
Altitude	280

PRE – INSPECTION		
	Target	Actual
Tq		
Np		
ITT	°C	°C
Ng	%	%
Wf		
Oil Press		°C
Oil Temp		°C
Start Temp		°C

POST- INSPECTION		
	Target	Actual
Tq	2397	2397
Np	1900	1890
ITT	841 °C	835 °C
Ng	102.7 %	100.2 %
Wf	578	543
Oil Press		96 °C
Oil Temp		58 °C
Start Temp		736 °C

Engine Run Up Checks							
Inertial	☒	EPL	☒	OVG	☒	Stby Alt	☒
BOV	☒	Brake	☒	Randomn	☒		

NOTE:

1. Brake system at Torque 2000 ft-lbs.
2. Inertial Separator at Torque 400 ft-lbs.
3. EPL check can't exceed 4% Ng per second.
4. Standby Alt at 80% Ng.
5. Low idle at 55.5 - 57% 40Amps.
6. High idle at 64 - 66% Ng 40Amps

Engine Performance Target Table (Cessna C208B EX)

OAT (°C)	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41
Tq (ft.lbs)	2397	2397	2397	2397	2397	2397	2397	2397	2397	2397	2397	2397	2397	2397	2397
Np	1900	1900	1900	1900	1900	1900	1900	1900	1900	1900	1900	1900	1900	1900	1900
ITT (°C)	835	837	839	841	841	841	841	841	841	842	843	844	846	846	846
Ng (%)	102.7	102.7	102.7	102.7	102.7	102.7	102.7	102.6	102.6	102.6	102.6	102.6	102.6	102.6	102.5
WF (PPH)	578	578	578	578	578	578	578	570	565	565	560	560	555	548	548

Note:

1. Make sure that inertial separator in normal condition, no bleed air extracted from the engine and air condition OFF.
2. This table only applies to altitude 0-500 feet MSL. For higher altitude, refer to EMM 72-00-00.
3. Max fuel flow is 580 lb/hr fuel flow is not more than 15 lbs/hr higher than the value shown in table.
4. If parameters are outside the target performance table to EMM chapter 71-00-00.

REMARKS:

- NIL -

PERFORMED BY			
Name	Sign & Stamp	Date	Location
ROHPININDO		06/03-2022	DJJ

Revision No. : 03

SCA/TEK/1-001



26 September 2019

MAINTENANCE PROGRAM **CESSNA C208/C208B**

Chapter 7 – Inspection Document 01

Reg. Mark : PK - SNH
MSN : 208B- 5587
TSN / CSN : 2194-16 / 3228

Date : 05-MAR-2022
Station : D13
WO No. : WO/044-SNH/111/2022

ITEM CODE NO.	ZONE	TASK	SIGNATURE	
			SIGN	STAMP
C122106	801 802 803 804 921 922 923 924	Key Lock Lubrication Task 12-21-07-640		
A251000	801 802	Smoke Goggle General Visual Inspection Task 25-10-00-210	N/A	
B262001	215 216 251 252	Portable Fire Extinguisher Functional Check (Weight Check) Task 26-20-00-720		
B272003	211 212 213 214 217 218 233 234 253 254 257 258 311 312 320 341	Rudder System Functional Check (Float Kit Installation) Task 27-20-00-721		
B313101	312	Flight Data Recorder System Functional Check Task 31-31-00-720		
A321001	721 722	Main Landing Gear Detailed Inspection Task 32-10-00-220		
A322002	701	Drag Link Forward Support Seal General Visual Inspection (Airplanes 20800553 and On and 208B5076 and on) Task 32-20-00-210		
A324001	721 722	Brakes Detailed Inspection Task 32-40-00-220		
A324005	721 722	Main Landing Gear Wheels and Tires Detailed Inspection Task 32-40-00-222		
A324009	710	Nose Landing Gear Wheel and Tire Detailed Inspection Task 32-40-00-224		
B350101	231 232 251 252 255 256 311 312 801 802	Oxygen System Operational Check Task 35-01-00-710		


ITEM CODE NO.	ZONE	TASK	SIGNATURE	
			SIGN	STAMP
A714101	130	Engine Wash Ring, Air Plenum, and Thermocouple (T1) Detailed Inspection Task 71-41-00-220		
*** End of Inspection Document 01 Items ***				

PERSONNEL PARTICIPATING IN THIS INSPECTION			
NAME	POSITION	SIGNATURE	LICENSE NUMBER
ROHPININDO	ENGINEER		9634
AP Nama P	Mechanic		

RETURN TO SERVICE

The work recorded above has been carried out in accordance with the requirements of the Civil Aviation Safety Regulation for the time being in force and in that respect the aircraft is consider fit for Release to Service.

Name : ROHPININDO.N.S.P Stamp : 

Signature :  Place/Date : D33 / 06-03-2022


MAINTENANCE PROGRAM **CESSNA C208/C208B**

Chapter 8 – Inspection Document 02

Reg. Mark : PK - SNH
MSN : 208B-5587
TSN / CSN : ~~208~~ 2194:16/3228

Date : 06-03-2022
Station : DJJ
WO No. : 00/044-SNH/III/2022

ITEM CODE NO.	ZONE	TASK	SIGNATURE	
			SIGN	STAMP
A710001	130	Engine Compartment Zonal Inspection Task 71-00-01-210		
*** End of Inspection Document 02 Items ***				

PERSONNEL PARTICIPATING IN THIS INSPECTION			
NAME	POSITION	SIGNATURE	LICENSE NUMBER
<u>RODRINUNDO.</u>	<u>ENGINEER</u>		<u>9634</u>
<u>Cep Nana P</u>	<u>Mechanic</u>		

RETURN TO SERVICE

The work recorded above has been carried out in accordance with the requirements of the Civil Aviation Safety Regulation for the time being in force and in that respect the aircraft is consider fit for Release to Service.



Name : RODRINUNDO, N.S.P Stamp : 
Signature :  Place/Date : DJJ / 06-03-2022

MAINTENANCE PROGRAM **CESSNA C208/C208B**

Chapter 12 – Inspection Document 06

Reg. Mark : PK - SNH
MSN : 208B-5587
TSN / CSN : 2194-16 / 3228

Date : 05-03-2022
Station : DJJ
WO No. : WO/044-SNH/III/2022

ITEM CODE NO.	ZONE	TASK	SIGNATURE	
			SIGN	STAMP
A110001	ALL	Interior and Exterior Placard and Decal Detailed Inspection Task 11-00-00-220		
D121001	121	Brake System Servicing Task 12-10-01-610		
D121003	710	Shimmy Damper Servicing Task 12-10-01-611	N/A	
C122101	700	Landing Gear Lubrication Task 12-21-03-640		
B236001	343 375 376 571 671	Static Discharge System Functional Check Task 23-60-00-720		
A255101	251 252 255 256 257 258	Cargo Nets Detailed Inspection Task 25-51-00-220	N/A	
C270001	215 216 226 373 374 503 525 603 625	Flight Controls Lubrication Task 27-00-00-640		
B273101	211 212 503	Stall Warning System Operational Check Task 27-31-00-710		
C275001	525 527 625 627	Flap Tracks and Rollers Lubrication Task 27-50-00-640		
B281001	575 675	Fuel Vent Line Float Valve Operational Check Task 28-10-03-710		
A281001	521 621	Fuel Filler Assembly Detailed Inspection Task 28-10-01-220		
B301003	122 AUX	Bleed Air Pressure Regulator Functional Check (without TKS and not incorporating CAB93-2) Task 30-10-00-720		
B322001	710	Shimmy Damper Functional Check Task 32-20-02-720		


ITEM CODE NO.	ZONE	TASK	SIGNATURE	
			SIGN	STAMP
B341101	AUX	Pitot Tube Heaters Operational Check Task 34-11-00-710		
A353001	256	Oxygen Mask Detailed Inspection Task 35-30-00-220		
B761003	AUX	Emergency Power Lever Annunciator Light (EPL) Operational Check Task 76-10-01-710		
*** End of Inspection Document 06 Items ***				

PERSONNEL PARTICIPATING IN THIS INSPECTION			
NAME	POSITION	SIGNATURE	LICENSE NUMBER
ROHPININDO	ENGINEER		9634
Cep Nana P	Mechanic		

RETURN TO SERVICE

The work recorded above has been carried out in accordance with the requirements of the Civil Aviation Safety Regulation for the time being in force and in that respect the aircraft is consider fit for Release to Service.

Name : ROHPININDO. N.S.P Stamp : 

Signature :  Place/Date : DJO / 06-03-2022






MAINTENANCE PROGRAM **CESSNA C208/C208B**

Chapter 51 – Engine PT6A-140 100 Hours/Minor Inspection

Reg. Mark : PK - SNH Date : 05-MAR-2022
 MSN : 208B-5587 Station : DJS
 TSN / CSN : 2194:16 / 3228 WO No. : WO/044-SNH/111/2022

ITEM CODE NO.	ZONE	TASK	SIGNATURE	
			SIGN	STAMP
F710001	130	Do a check of the FCU manual override system for static operation. For the engines installed with a manual override system only.		
F710003	130	Do a compressor performance recovery wash		
F720000	130	Do a visual inspection of the Control Linkages and wiring.		
F720001	130	Do a visual inspection of the engine exhaust duct welds.		
F720002	130	Do a visual inspection of the engine exhaust duct for cracks.		
F720003	130	Do a visual inspection of the gas generator case and the center fireseal.		
F720004	130	Do a visual inspection of the rear fireseal mounting ring.		
F722001	130	Do a visual inspection of the air inlet screen.		
F723000	130	Do a visual inspection with a mirror or a borescope inspection of the First-stage Compressor Rotor and the inlet case for corrosion		
F725005	130	Do a detailed inspection of the turbine exhaust duct.		
F731002	130	Do a check for the fuel pump installation and leaks.		
F731003	130	Do a check of the oil-to- fuel heater installation		
F731035	130	Do a visual Inspection of the Fuel - Oil Heat Exchanger Fuel Filter Element (CLEANING / REPLACEMENT) P/N OFF: <u>AN 6235-3A</u> P/N ON: <u>AN 6235-3A</u>		

Chapter 51 – Engine PT6A-140 100 Hours/Minor Inspection

ITEM CODE NO.	ZONE	TASK	SIGNATURE	
			SIGN	STAMP
F731006	130	Do a check of the drain valve for installation and leaks		
F731007	130	Do a check of the flow divider for installation and leaks.		
F731008	130	Do a visual inspection of the P3 filter and drain valve.		
F731015	130	Do a visual inspection of Fuel Pump outlet filter. (CLEANING / REPLACEMENT) P/N OFF: <u>AN6235-3A</u> P/N ON: <u>AN6235-3A</u>		
F731018	130	Clean or replace the P3 filter based on condition, service experience or environment. Note: If corrossions are found, replace filter.		
F732001	130	Do a check of the FCU for installation, linkages and pneumatic tubes.		
F792000	130	Inspect and clean oil filter for debris.		
*** End of Engine PT6A-140 100 Hours Inspection Items ***				

PERSONNEL PARTICIPATING IN THIS INSPECTION			
NAME	POSITION	SIGNATURE	LICENSE NUMBER
<u>REHPINWDO N.S.P</u>	<u>ENGINEER</u>		<u>9634</u>
<u>Cap Nana P</u>	<u>Mechanic</u>		

RETURN TO SERVICE

The work recorded above has been carried out in accordance with the requirements of the Civil Aviation Safety Regulation for the time being in force and in that respect the aircraft is consider fit for Release to Service.

Name : REHPINWDO Stamp : 
Signature :  Place/Date : DJJ/06-03-2022

MAINTENANCE PROGRAM CESSNA C208/C208B

Chapter 52 – Engine PT6A-140 200 Hours Inspection


Reg. Mark : PK - SNH Date : 06-03-2022
MSN : 208B-5587 Station : 033
TSN / CSN : 2194-16 / 3228 WO No. : 100/044-SNH/111/2022

ITEM CODE NO.	ZONE	TASK	SIGNATURE	
			SIGN	STAMP
F793001	130	Do a visual inspection of the chip detector for debris.		
*** End of Engine PT6A-140 200 Hours Inspection Items ***				

PERSONNEL PARTICIPATING IN THIS INSPECTION			
NAME	POSITION	SIGNATURE	LICENSE NUMBER
ROHPININDO	ENGINEER		9634
C&P Name P	Mechanic		

RETURN TO SERVICE

The work recorded above has been carried out in accordance with the requirements of the Civil Aviation Safety Regulation for the time being in force and in that respect the aircraft is consider fit for Release to Service.

Name : ROHPININDO .P.S.P Stamp : 
Signature :  Place/Date : 033 / 06-03-2022


MAINTENANCE PROGRAM CESSNA C208/C208B

Chapter 53 – Engine PT6A-140 200 Hours or 6 Months Inspection

Reg. Mark : PK - 50H Date : 06-03-2022
MSN : 2086-5587 Station : DJJ
TSN / CSN : 2194:16 / 3228 WO No. : W0/044-50H/111/2022

ITEM CODE NO.	ZONE	TASK	SIGNATURE	
			SIGN	STAMP
F793000	130	Do a visual inspection of the AGB internal scavenge oil pump inlet screen		

*** End of Engine PT6A- 140 200 Hours or 6 Months Inspection Items ***

PERSONNEL PARTICIPATING IN THIS INSPECTION			
NAME	POSITION	SIGNATURE	LICENSE NUMBER
<u>ROHPININDO</u>	<u>ENGINEER</u>		<u>9634</u>
<u>CRP Nama</u>	<u>Mechanic</u>		

RETURN TO SERVICE

The work recorded above has been carried out in accordance with the requirements of the Civil Aviation Safety Regulation for the time being in force and in that respect the aircraft is consider fit for Release to Service.

Name : ROHPININDO. N.S.P Stamp : 
Signature :  Place/Date : DJJ / 06-03-2022



Additional Work Sheet
Inspection Doc. 06 & Add Task

Inspection Doc. 06 & Add Task

Parts Used Sheet

1

[illegible]



PK-SNH



Additional Work Sheet
Inspection Doc. 06 & Add Task

Parts Used Sheet 2

[illegible]