



PT. SMART CAKRAWALA AVIATION

WORK ORDER

Form: SCA/MTC/030

Subject : Inspection Document 0A Due at 31 March 2022 FH.	No.	WO/045-SNH/III/2022
	Date	01-Mar-2022
	A/C Reg.	PK-SNH C208B-5587
Reference : MP C208B Rev. 10	Prepared By	TS
	Checked By	CI
	Approved By	TM
To : Engineer In Charge		
Description : 1. Perform Inspection Document 0A Due at 31 March 2022 FH. 2. Make an entry in Maintenance Log. 3. Return the Completed Work Order and Form to PPC. #If any finding, please close the routine card, and transferred to inspection card.		
Additional Work :		
Compliance Statement CARRIED OUT	Sign & Date Company Lic. No.: 06-03-2022  (Engineer In Charge)	Signature (Technical Manager)

AIRCRAFT CHECK WORK SUMMARY
(Form: SCA/MTC/051)

DATE OF ISSUED	JO/WO #	TYPE OF MAINTENANCE	DATE OF ACCOMPLISHED		
01-March-2022	WO/045-SNH/III/2022	Inspection Doc. 0A	06-03-2022		
A/C Type		Mfg. Serial Number	A/C Registration		
C208B		C208B-5587	PK-SNH		
AIRCRAFT DATA					
Subject	Pos #	Serial Number (SN)	TTSN/TCSN		
Engine	#1	PCE-VA0662	2194:16 / 3228		
	#2	-			
Propeller/Rotor	#1	190837	2194:16 / 3228		
	#2	-			
Landing Gear	NLG				
	LH MLG				
	RH MLG				
PACKAGE COVERED					
No	Subject	Qty	Remark		
1	Non-Routine Card	-			
2	Inspection Card	1			
3	Work Order	1			
4	Summary Inspection List	1			
5	Material and Tool List	-			
6	Escalation form	-			
7	CRS (SMI / Unscheduled Maintenance)	1			
INSPECTION CARD (IC) LIST (Finding during maintenance)					
No	Taskcard Ref	Subject	Status		Name/ Sign & Stamp
			Open	Close	
<u>IC-001</u>					
<u>IC-002</u>					
<u>IC-003</u>					
<u>IC-004</u>					
<u>IC-005</u>					
<u>IC-006</u>					

<u>IC-007</u>					
<u>IC-008</u>					
<u>IC-009</u>					
<u>IC-010</u>					
<u>IC-011</u>					
<u>IC-012</u>					
<u>IC-013</u>					
<u>IC-014</u>					
<u>IC-015</u>					

Prepared by :
Technical Support

Checked by :
Chief Maintenance

Verified by :
Chief Inspector

Approved by :
Technical Manager

.....

.....

.....

.....



SUMMARY INSPECTION ITEMS
(Form: SCA/MTC/050)

WO Ref: WO/045-SNH/III/2022

NO.	TASK CARD NO.	DESCRIPTION	DATE	EST MHR	NAME	STAMP
1	CHAPTER 06	INSPECTION DOCUMENT 0A	06/10/22		NINPO	

		INSPECTION CARD (Form: SCA/MTC/ 048)		TECHNICAL DEPARTMENT	
---	--	--	--	-------------------------	--

1. CARD #	2. JO/WO #	3. ORIGINATOR	4. CARD REF	5. DATE	
6. A/C REG/MSN	7. A/C TYPE	8. TRADE	12. VENDOR ORDER #		
9. ZONE	10. STA	11. MTC TYPE			

13. DESCRIPTION/DEFECT-IF FINDING OF CPCP INSPECTION, PLEASE COMPLETE SET. 20	14 PPC/ENG	15 DATE

16. CORRECTIVE ACTION	17 MECH	18 ENG. LIC	19 DATE
Performed at A/C TT : A/C TC /LDG :			

20. CORROSION INFORMATION					
LOCATION	CAUSE OF DAMAGE				
	☐ Environment				
	☐ Internal Leakage				
CORROSION ☐ Isolated ☐ Widespread	☐ Chemical Spill				
CORROSION LVL ☐ 1 ☐ 2 ☐ 3	☐ LAV/Galley Spill				
PROPOSED ACTION ☐ Doublers	☐ Blocked Drain				
☐ Others	☐ Wet Insulation Blanket				
	☐ Other				
21. If the defect is RII, Please Sign this card finally by RII Inspector				INSP	DATE
NOTICE OF INSPECTOR					

22. PARTS REQUIRED						
PART DESCRIPTION	PART NO	QTY	SERIAL NO		STATUS	
			ON	OFF	CLOSE	OPEN

23. TOOLS REQUIRED			
DESCRIPTION	PART NO. / MODEL	NEXT CALIBRATION DATE	STATUS






MAINTENANCE PROGRAM CESSNA C208/C208B

Chapter 6 – Inspection Document 0A

Reg. Mark	: PK - <u>SNH</u>	Date	: <u>06-03-2022</u>
MSN	: <u>208B-5587</u>	Station	: <u>DJ3</u>
TSN / CSN	: <u>2194-16 / 3228</u>	WO No.	: <u>W0/045-SNH/III/2022</u>

TASK NUMBER	TASK	SIGNATURE	
		SIGN	STAMP
05-20-00-280	Aircraft Records Check		
12-10-01-610	Hydraulic Brake System Servicing		
24-33-00-720	Concord Sealed Lead Acid Battery Functional Check (Capacity Check) EPV Voltage : _____ Volt Result : _____ %		
25-10-00-220	Crew Seats Detailed Inspection		
25-10-00-710	Inertia Reel Operational Check		
27-10-00-721	Aileron System Functional Check Aileron Wing Cable Tension 40 ± 5 lbs (178 ± 22 N) @ 21°C (70°F) Ref. 27-10-00 Figure 602 Result : <u>40</u> lbs Aileron Fuselage Cable Tension 20 ± 5 lbs (89 ± 22 N) @ 21°C (70°F) Ref. 27-10-00 Figure 603 Result : <u>20</u> lbs Turn the control wheel so that the stop bolt touches the right bellcrank. Left aileron up travel must be 25 ± 4 or 0 degrees. Result : <u>25</u> degrees Turn the control wheel so that the stop bolt touches the left bellcrank. Left aileron down travel must be 16 ± 1 or -0 degrees Result : <u>16</u> degrees		
27-50-00-220	Flap Actuator Mount Bracket Detailed Inspection		

TASK NUMBER	TASK	SIGNATURE	
		SIGN	STAMP
27-50-00-221	Flap Bell Crank Detailed Inspection		
27-50-00-720	Flap System Functional Check Make sure that cable tension is 35 $\pm$ 5 lbs (156 $\pm$ 22 N) @ 21°C (70°F) Ref. 27-50-00 Figure 602 Result: <u>35</u> lbs		
32-20-00-220	Nose Landing Gear Detailed Inspection		
32-40-00-220	Brakes Detailed Inspection Brake Disc Thickness (minimum 0.537 inch) LH: <u>0.550</u> inch / RH: <u>NEW</u> inch Brake linings Thickness (minimum 0.100 inch) Outboard LH: <u>0.125</u> inch. Outboard RH: <u>0.130</u> inch Inboard LH: <u>0.130</u> inch. Inboard RH: <u>0.128</u> inch		
32-40-00-222	Main Landing Gear Wheels and Tires Detailed Inspection Tire Pressure (56 $\pm$ 5 psi for APE STOL Installed & 45 $\pm$ 5 psi for non-APE STOL) Tire Pressure LH: <u>60</u> psi Tire Pressure RH: <u>60</u> psi		
32-40-00-224	Nose Landing Gear Wheel and Tire Detailed Inspection Tire Pressure (36 $\pm$ 6 psi) Tire Pressure : <u>40</u> psi		
32-10-00-220	Main Landing Gear Detailed Inspection Free Play Check (maximum 0.014 inch / 0.3556 mm) LH: <u>0.014</u> inch / RH: <u>0.014</u> inch		
53-10-00-214	Empennage and Horizontal Stabilizer Zonal Inspection		
53-10-00-210	External Fuselage Zonal Inspection		
53-10-00-211	Internal Cockpit Zonal Inspection		
53-10-00-212	Internal Cabin Zonal Inspection		

TASK NUMBER	TASK	SIGNATURE	
		SIGN	STAMP
53-10-00-213	Internal Tail Cone Zonal Inspection		
57-10-00-210	Wing Zonal Inspection		
61-11-00-720	McCauley Propeller Functional Check		
71-20-00-220	Engine Mounts and Firewall Detailed Inspection		
71-00-01-210	Engine Compartment Zonal Inspection		
76-10-00-720	Engine Controls Functional Check Low Idle Ng (52% - 55%) Result: <u>54</u> % High Idle Ng (64% - 66%) Result: <u>65</u> %		

PERSONNEL PARTICIPATING IN THIS INSPECTION			
NAME	POSITION	SIGNATURE	LICENSE NUMBER
DEWI SOPALI	ENGINEER		0632
ROHPININDO	ENGINEER		9634
Al Nana P	Mechanic		

RETURN TO SERVICE

The work recorded above has been carried out in accordance with the requirements of the Civil Aviation Safety Regulation for the time being in force and in that respect the aircraft is consider fit for Release to Service.

Name : ROHPININDO . W . S . P Stamp : 
 Signature :  Place/Date : 033/06-03-2022



Additional Work Sheet
Inspection Doc. 06 & Add Task

Inspection Doc. 06 & Add Task

Aircraft Registration: **PK-SNH**

WO# NR:
WO/045-SNH/III/2022

Parts Used Sheet 1[illegible]



2
Parts Used Sheet

[illegible]