



PT. SMART CAKRAWALA AVIATION

WORK ORDER

Form: SCA/MTC/030

Subject : Inspection Document 10 & Add Task due at 2400 Hours.	No.	WO/055-SNV/XI/2021
	Date	10-November-2021
	A/C Reg.	PK-SNV C208B-5551
Reference : MP C208B Rev. 10	Prepared By	TS
	Checked By	CI
	Approved By	TM

To : Engineer In Charge

Description :

1. Perform Inspection Document 10 & Add Task due at 2400 Hours.
2. Make an entry in Maintenance Log.
3. Return the Completed Work Order and Form to PPC.


#If any finding, please close the routine card, and transferred to inspection card.

Additional Work :

- nil -

Compliance
Statement

Sign & Date
Company Lic. No.:


9652
(Engineer In Charge)



Signature

(Technical Manager)

AIRCRAFT CHECK WORK SUMMARY
(Form: SCA/MTC/051)

DATE OF ISSUED	JOWO #	TYPE OF MAINTENANCE	DATE OF ACCOMPLISHED	
10-Nov-2021	WO/055-SNV/XI/2021	Inspection Doc. 10 & Add Task	26 NOVEMBER 2021	
A/C Type		Mfg. Serial Number	A/C Registration	
C208B		C208B-5551	PK-SNV	
AIRCRAFT DATA				
Subject	Pos #	Serial Number (SN)	TTSN/TCSN	
Engine	#1	PCE-VA0607	2401:12 / 4339	
	#2	-		
Propeller/Rotor	#1	181160	2401:12 / 4339	
	#2	-		
Landing Gear	NLG			
	LH MLG			
	RH MLG			
PACKAGE COVERED				
No	Subject	Qty	Remark	
1	Non-Routine Card	2	#001, #002	
2	Inspection Card	1		
3	Work Order	1		
4	Summary Inspection List	1		
5	Material and Tool List	-		
6	Escalation form	-		
7	CRS (SMI / Unscheduled Maintenance)	1		
INSPECTION CARD (IC) LIST (Finding during maintenance)				
No	Taskcard Ref	Subject	Status Open Close	Name/ Sign & Stamp
IC-001	02360001	STATIC WICK COVER BROKEN		✓  
IC-002				
IC-003				
IC-004				
IC-005				
IC-006				

INSPECTION CARD (IC) LIST (Finding during maintenance)

No	Taskcard Ref	Subject	Status		Name/ Sign & Stamp
			Open	Close	
<u>IC-007</u>					
<u>IC-008</u>					
<u>IC-009</u>					
<u>IC-010</u>					

Prepared by :
Technical Support

Checked by :
Chief Maintenance

Verified by :
Chief Inspector

Approved by :
Technical Manager

.....

.....

.....

.....



SUMMARY INSPECTION ITEMS

(Form: SCA/MTC/050)

WO Ref: WO/055-SNV/XI/2021

NO.	TASK CARD NO.	DESCRIPTION	DATE	EST MHR	NAME	STAMP
1	B03	PT6A-140 ENGINE GROUND RUN PERFORMANCE	26/11/21		Dennis Prama.	
2	CHAPTER 08	INSPECTION DOCUMENT 02	24-11-21		RIDZAL. G	
3	CHAPTER 12	INSPECTION DOCUMENT 06	24-11-21		Dennis Prama	
4	CHAPTER 13	INSPECTION DOCUMENT 07	25-11-21		RIDZAL. G	
5	CHAPTER 14	INSPECTION DOCUMENT 08	24-11-21		RIDZAL. G	
6	CHAPTER 15	INSPECTION DOCUMENT 09	25-11-21		RIDZAL. G	
7	CHAPTER 16	INSPECTION DOCUMENT 10	26/11/21		Dennis Prama.	
8	CHAPTER 51	ENGINE PT6A-140 100 HOUR INSPECTION/ MINOR INSPECTION	26-11-21		RIDZAL. G	
9	CHAPTER 52	ENGINE PT6A-140 200 HOUR INSPECTION	25-11-21		RIDZAL. G	
10	CHAPTER 53	ENGINE PT6A-140 200 HOUR / 6 MONTHS INSPECTION	25/11/21		Dennis Prama	
11	CHAPTER 54	ENGINE PT6A-140 400 HOUR INSPECTION	25/11/21		Dennis Prama	
12	CHAPTER 55	ENGINE PT6A-140 600 HOUR INSPECTION	25/11/21		Dennis Prama	
15	NRC-001	VACUUM SYSTEM CENTRAL AIR FILTER REPLACEMENT PART NUMBER: AAD9-18-1	23/11/21		Dennis Prama	
16	NRC-002	VACUUM SYSTEM CENTRAL AIR FILTER REPLACEMENT PART NUMBER: B3-5-1	23/11/21		Dennis Prama	

17	SCA/MTC/023	EMERGENCY EQUIPMENT CHECK	25-11-21		RIDJAL.E	
----	-------------	---------------------------	----------	--	----------	---



INSPECTION CARD

(Form: SCA/MTC/ 048)

TECHNICAL
DEPARTMENT

1. CARD #	2. JOWO #	3. ORIGINATOR	4. CARD REF	5. DATE
IC - 001	W0/055-SNV/x1/2024			22 Nov 2024
6. A/C REG/MSN	7. A/C TYPE	8. TRADE	12. VENDOR ORDER #	
PK-SNV	C208B EX			
9. ZONE	10. STA	11. MTC TYPE		
TAIL				

13. DESCRIPTION/DEFECT-IF FINDING OF CPCP INSPECTION, PLEASE COMPLETE SET. 20	14	15
	PPC/ENG	DATE
STATIC WICK COVER BROKEN AT TAIL ZONE		21/Nov/2024

16. CORRECTIVE ACTION	17	18	19
	MECH	ENG, LIC	DATE
REPLACED WITH NEW PART		 #0967	22/Nov/2024
Performed at A/C TT : 2401:12 A/C TC /LDG : 4339			

20. CORROSION INFORMATION		CAUSE OF DAMAGE			
LOCATION					
CORROSION ☐ Isolated ☐ Widespread	☐ Environment				
CORROSION LVL ☐ 1 ☐ 2 ☐ 3	☐ Internal Leakage				
PROPOSED ACTION ☐ Doublers	☐ Chemical Spill				
☐ Others	☐ LAV/Galley Spill				
	☐ Blocked Drain				
	☐ Wet Insulation Blanket				
	☐ Other				

21. If the defect is RII, Please Sign this card finally by RII Inspector		INSP	DATE
NOTICE OF INSPECTOR			

22. PARTS REQUIRED						
PART DESCRIPTION	PART NO	QTY	SERIAL NO		STATUS	
			ON	OFF	CLOSE	OPEN
BUICK COVER	C592001-0206	1ea	-	-	✓	

23. TOOLS REQUIRED			
DESCRIPTION	PART NO. / MODEL	NEXT CALIBRATION DATE	STATUS
GENERAL TOOLS	-	O/C	Good

NON ROUTINE CARD (Form: SCA/MTC/047)

1. JO/WO #	2. DATE	3. MTC TYPE	4. A/C REG/MSN
WO/055-SNV/XI/2021	10-Nov-2021	REPLACEMENT	PK-SNV/208B-5551
5. CARD #	6. ATA SPEC	7. TRADE	8. STA
#001	37		
9. ZONE	10. PANEL		
COCKPIT			

11. DESCRIPTION			
PERFORM REPLACE VACUUM SYSTEM CENTRAL AIR FILTER DISCARD PN: AAD9-18-1			
REFERENCE	☒ AMM Ch. 37-10-00-960	☐ EMM Ch	☐ OTHER
RII (*)	☐ Y	☒ N	MHR:

12. RESULT		MECH	ENG	INSP (*)
PERFORMED REPLACE VACUUM SYSTEM CENTRAL FILTER				
Performed at A/C TT : 2101:12 A/C TC/LDG : 4330				
FINDING	☐ Y	☒ N	ACT MHR:	DATE/TIME (DD/MM/YY)
INSPECTION CARD (IC) #			23	NOV 2021

13. PARTS REQUIRED				
DESCRIPTION	PART NO	QTY	REMARK	
			STOCK	STATUS
VACUUM CENTRAL FILTER	AAD9-18-1	1	✓	✓

14. TOOLS REQUIRED			
DESCRIPTION	PART NO / MODEL	NEXT CALIBRATION DATE	STATUS
GENERAL TOOLS	-	b/c	Good

NON ROUTINE CARD (Form: SCA/MTC/047)

1. JO/WO #	2. DATE	3. MTC TYPE	4. A/C REG/MSN
WO/055-SNV/XI/2021	10-Nov-2021	REPLACEMENT	PK-SNV/208B-5551
5. CARD #	6. ATA SPEC	7. TRADE	8. STA
#002	37		
9. ZONE	10. PANEL		

11. DESCRIPTION			
PERFORM REPLACE VACUUM RELIEF VALVE FILTER DISCARD PN: B3-5-1			
REFERENCE	☒ AMM Ch. 37-10-00-961	☐ EMM Ch	☐ OTHER
RII (*)	☐ Y	☒ N	MHR :

12. RESULT		MECH	ENG	INSP (*)
PERFORMED REPLACE VACUUM RELIEF VALVE FILTER		<i>And</i>	<i>26</i>	
Performed at A/C TT : 2A01:12 A/C TC /LDG : A339				
FINDING	☐ Y	☒ N	ACT MHR :	DATE/TIME (DD/MM/YY)
INSPECTION CARD (IC) #		23	NOV	2021

13. PARTS REQUIRED				
DESCRIPTION	PART NO	QTY	REMARK	
			STOCK	STATUS
VACUUM RELIEF VALVE FILTER	B3-5-1	1ea	☒	☒

14. TOOLS REQUIRED			
DESCRIPTION	PART NO / MODEL	NEXT CALIBRATION DATE	STATUS
GENERAL TOOLS	-	10/10	Good.



MAINTENANCE PROGRAM CESSNA C208/C208B

Appendix B03 – PT6A-140 Engine Run Performance Sheet

Reg. Mark : PK - SNU

WO/FML No. : WO/055-SNU/X1/2021

PRE – INSPECTION	
Location	<u>NABIRE</u>
Date	<u>20 NOV 2021</u>
Cycle	
Filed Barometric	<u>1009</u>
OAT	<u>32°C</u>
Altitude	<u>40 FT.</u>

POST – INSPECTION	
Location	<u>NABIRE</u>
Date	<u>26 NOV 2021</u>
Cycle	
Filed Barometric	<u>1009</u>
OAT	<u>31°C</u>
Altitude	<u>40 FT</u>

PRE – INSPECTION		
	Target	Actual
Tq	<u>2397</u>	<u>2397</u>
Np	<u>1900</u>	<u>1900</u>
ITT	<u>841 °C</u>	<u>831 °C</u>
Ng	<u>102.7 %</u>	<u>101.2 %</u>
Wf	<u>578</u>	<u>540</u>
Oil Press		<u>89 °C</u>
Oil Temp		<u>69 °C</u>
Start Temp		<u>715 °C</u>

POST – INSPECTION		
	Target	Actual
Tq	<u>2397</u>	<u>2397</u>
Np	<u>1900</u>	<u>1900</u>
ITT	<u>841 °C</u>	<u>836 °C</u>
Ng	<u>102.7 %</u>	<u>100.9 %</u>
Wf	<u>578</u>	<u>537</u>
Oil Press		<u>88 °C</u>
Oil Temp		<u>72 °C</u>
Start Temp		<u>705 °C</u>

Engine Run Up Checks	
Inertial ☒	EPL ☒
OVG ☒	Stby Alt ☒
BOV ☒	Brake ☒
Random ☒	

NOTE:

1. Brake system at Torque 2000 ft-lbs.
2. Inertial Separator at Torque 400 ft-lbs.
3. EPL check can't exceed 4% Ng per second.
4. Standby Alt at 80% Ng.
5. Low idle at 55.5 - 57% 40Amps.
6. High idle at 64 - 66% Ng 40Amps

Engine Performance Target Table (Cessna C208B EX)

OAT (°C)	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41
Tq (ft.lbs)	2397	2397	2397	2397	2397	2397	2397	2397	2397	2397	2397	2397	2397	2397	2397
Np	1900	1900	1900	1900	1900	1900	1900	1900	1900	1900	1900	1900	1900	1900	1900
ITT (°C)	835	837	839	841	841	841	841	841	841	842	843	844	846	846	846
Ng (%)	102.7	102.7	102.7	102.7	102.7	102.7	102.7	102.6	102.6	102.6	102.6	102.6	102.6	102.6	102.5
WF (PPH)	578	578	578	578	578	578	578	570	565	565	560	560	555	548	548

Note:

1. Make sure that inertial separator in normal condition, no bleed air extracted from the engine and air condition OFF.
2. This table only applies to altitude 0-500 feet MSL. For higher altitude, refer to EMM 72-00-00.
3. Max fuel flow is 580 lb/hr fuel flow is not more than 15 lbs/hr higher than the value shown in table.
4. If parameters are outside the target performance table to EMM chapter 71-00-00.

REMARKS:

~~ITT~~ ITT IS APPROACHING LIMITS. (AMBER)

PERFORMED BY

Name	Sign & Stamp	Date	Location
<u>Daniel Pruna</u>		<u>26 NOV 2021</u>	<u>NABIRE</u>



MAINTENANCE PROGRAM CESSNA C208/C208B

Chapter 8 – Inspection Document 02

Reg. Mark : PK-SNV
 MSN : C208B-5551
~~WO/055-SNV~~
 TSN / CSN : 2401:17/4339

Date : 24 NOV 2021
 Station : NABIRE
 WO No. : WO/055-SNV/X1/2021

ITEM CODE NO.	ZONE	TASK	SIGNATURE	
			SIGN	STAMP
A710001	130	Engine Compartment Zonal Inspection Task 71-00-01-210		
*** End of Inspection Document 02 Items ***				

PERSONNEL PARTICIPATING IN THIS INSPECTION			
NAME	POSITION	SIGNATURE	LICENSE NUMBER
<u>RIDZAL, G</u>	<u>ENGINEER</u>		<u>9694</u>

RETURN TO SERVICE

The work recorded above has been carried out in accordance with the requirements of the Civil Aviation Safety Regulation for the time being in force and in that respect the aircraft is consider fit for Release to Service.

Name : RIDZAL GHAZALI Stamp :


Signature : Place/Date : NBX, 24 NOV 2021

MAINTENANCE PROGRAM CESSNA C208/C208B

Chapter 12 – Inspection Document 06

Reg. Mark : PK-SNV
MSN : C208B 5551
TSN / CSN : 240112/4339

Date : 24 Nov 2021
Station : NARSIRE
WO No. : WO/095-SNV/11/2021

ITEM CODE NO.	ZONE	TASK	SIGNATURE	
			SIGN	STAMP
A110001	ALL	Interior and Exterior Placard and Decal Detailed Inspection Task 11-00-00-220		
D121001	121	Brake System Servicing Task 12-10-01-610		
D121003	710	Shimmy Damper Servicing Task 12-10-01-611	N/A	N/A
C122101	700	Landing Gear Lubrication Task 12-21-03-640		
B236001	343 375 376 571 671	Static Discharge System Functional Check Task 23-60-00-720		
A255101	251 252 255 256 257 258	Cargo Nets Detailed Inspection Task 25-51-00-220	N/A	N/A
C270001	215 216 226 373 374 503 525 603 625	Flight Controls Lubrication Task 27-00-00-640		
B273101	211 212 503	Stall Warning System Operational Check Task 27-31-00-710		
C275001	525 527 625 627	Flap Tracks and Rollers Lubrication Task 27-50-00-640		
B281001	575 675	Fuel Vent Line Float Valve Operational Check Task 28-10-03-710		
A281001	521 621	Fuel Filler Assembly Detailed Inspection Task 28-10-01-220		
B301003	122 AUX	Bleed Air Pressure Regulator Functional Check (without TKS and not incorporating CAB93-2) Task 30-10-00-720		
B322001	710	Shimmy Damper Functional Check Task 32-20-02-720		



MAINTENANCE PROGRAM **CESSNA C208/C208B**

Chapter 12 – Inspection Document 06

ITEM CODE NO.	ZONE	TASK	SIGNATURE	
			SIGN	STAMP
B341101	AUX	Pitot Tube Heaters Operational Check Task 34-11-00-710		
A353001	256	Oxygen Mask Detailed Inspection Task 35-30-00-220		
B761003	AUX	Emergency Power Lever Annunciator Light (EPL) Operational Check Task 76-10-01-710		
*** End of Inspection Document 06 Items ***				

PERSONNEL PARTICIPATING IN THIS INSPECTION			
NAME	POSITION	SIGNATURE	LICENSE NUMBER
RIDZAL G	ENGINEER		9694
DENIRO PIZUARA	ENGINEER		9657-

RETURN TO SERVICE

The work recorded above has been carried out in accordance with the requirements of the Civil Aviation Safety Regulation for the time being in force and in that respect the aircraft is consider fit for Release to Service.

Name : Denny Pramu Stamp :

Signature : Place/Date : MBX / 24 NOV 2024



MAINTENANCE PROGRAM

CESSNA C208/C208B

Chapter 13 – Inspection Document 07

Reg. Mark : PK-GNV
 MSN : C208B-5551
 TSN / CSN : 2401-12/4339


Date : 25 NOV 2021
 Station : NABIRE
 WO No. : WO/055-GNV/X1/2021

ITEM CODE NO.	ZONE	TASK	SIGNATURE	
			SIGN	STAMP
A243601	121	Standby Alternator Detailed Inspection Task 24-36-00-220		
B251001	221 232	Inertia Reel Operational Check Task 25-10-00-710		
B255201	901 902 903 904 905 906	Cargo Pod Drains Operational Check Task 25-52-00-710		
A261001	121 122	Engine Fire Detection System General Visual Inspection Task 26-10-00-210		
C271001	211 212 217 218 233 234 253 254 251 252 551 571 651 671	Aileron Trim System Lubrication Task 27-10-02-640		
B271005	551 571 651 671	Aileron Trim Tab (Free Play) Functional Check Task 27-10-02-720		
B273003	371 372 375 376	Elevator Trim Tab (Free Play) Functional Check Task 27-30-02-720		
D282101	130	Firewall Mounted Fuel Filter Servicing Task 28-21-00-610		
B282103	213 214 220	Firewall Fuel Shutoff Valve Control Operational Check Task 28-21-00-711		
C282301	231 232 511 611	Wing Shutoff Valve Linkage Lubrication Task 28-23-00-640		
B284101	ENG	Fuel Reservoir Warning System Operational Check Task 28-41-00-710		
B301001	122 AUX	Bleed Air Pressure Regulator Functional Check (Airplanes with de-ice boots installed) Task 30-10-00-720	N/A	N/A.
A353003	256	Portable Oxygen Cylinder Detailed Inspection Task 35-30-00-221		

MAINTENANCE PROGRAM CESSNA C208/C208B

Chapter 13 – Inspection Document 07

ITEM CODE NO.	ZONE	TASK	SIGNATURE	
			SIGN	STAMP
B611101	110	McCauley Propeller Functional Check Task 61-11-00-720		
A712001	130	Engine Mounts and Firewall Detailed Inspection Task 71-20-00-220		
A716001	130	Inertial Air Separator Detailed Inspection Task 71-60-00-220		
B761001	130 211 212 ENG	Engine Controls Functional Check Task 76-10-00-72		
A801001	130	Starter-Generator (Part Number 23081 Series only) Detailed Inspection Task 80-10-00-220	N/A	N/A
*** End of Inspection Document 07 Items ***				

PERSONNEL PARTICIPATING IN THIS INSPECTION			
NAME	POSITION	SIGNATURE	LICENSE NUMBER
RIDZAL GHAZALI	ENGINEER		9694
	ENGINEER		9687
Pirajan Tosi Hamsyah	MECHANIC		

RETURN TO SERVICE

The work recorded above has been carried out in accordance with the requirements of the Civil Aviation Safety Regulation for the time being in force and in that respect the aircraft is consider fit for Release to Service.

Name : RIDZAL GHAZALI Stamp : 



Signature :  Place/Date : NEX, 29 NOV 2021

MAINTENANCE PROGRAM CESSNA C208/C208B

Chapter 14 – Inspection Document 08

Reg. Mark : PK-SNV Date : 24 NOV 2021
MSN : C208B-5551 Station : NATSIRE
TSN / CSN : 2401:12/4339 WO No. : WD/055-SNV/X1/2021

ITEM CODE NO.	ZONE	TASK	SIGNATURE	
			SIGN	STAMP
B215001	121 122	Compressor Drive Belt Functional Check Task 21-50-00-720		
A322001	710	Nose Landing Gear Detailed Inspection Task 32-20-00-220		
*** End of Inspection Document 08 Items ***				

PERSONNEL PARTICIPATING IN THIS INSPECTION			
NAME	POSITION	SIGNATURE	LICENSE NUMBER
RIDZAL GHAZALI	ENGINEER		9694
Deur Pranom	ENGINEER		9657
Furman TOR H.	MECHANIC		
PETER AGAPIL	MECHANIC		

RETURN TO SERVICE

The work recorded above has been carried out in accordance with the requirements of the Civil Aviation Safety Regulation for the time being in force and in that respect the aircraft is consider fit for Release to Service.


Name : RIDZAL GHAZALI Stamp : 
Signature :  Place/Date : NBSX, 24 NOV 2021

MAINTENANCE PROGRAM CESSNA C208/C208B

Chapter 15 – Inspection Document 09

Reg. Mark : PK - SNV
MSN : C208B-5591
TSN / CSN : 240112 / 4339

Date : 25 NOV 2021
Station : NABIRE
WO No. : W0/099-SNV/X1/2021

ITEM CODE NO.	ZONE	TASK	SIGNATURE	
			SIGN	STAMP
B212401	211 212	Avionics Cooling Fan Operational Check Task 21-24-00-710		
B221201	226 232	Garmin Autopilot (GFC 700) Functional Check Task 22-12-00-720		
B221203	226 232	Garmin Autopilot (GFC 700) Slip Clutch Override Operational Check Task 22-12-00-710		
C273030	213 214	Elevator Bellcrank Lubrication Task 12-21-02-640		
A275001	231 232	Flap Actuator Mount Bracket Detailed Inspection Task 27-50-00-220		
A275003	251 252 511 611 525 625	Flap Bellcrank Detailed Inspection Task 27-50-00-221		
*** End of Inspection Document 09 Items ***				

PERSONNEL PARTICIPATING IN THIS INSPECTION			
NAME	POSITION	SIGNATURE	LICENSE NUMBER
<u>RIDZAL GHAZALI</u>	<u>ENGINEER</u>		<u>9694</u>
<u>Danur Prama</u>	<u>Engineer</u>		<u>9657</u>
<u>Firman TOR H.</u>	<u>MECHANIC</u>		<u>-</u>
<u>PITIR ASHAR</u>	<u>MECHANIC</u>		<u>-</u>

RETURN TO SERVICE

The work recorded above has been carried out in accordance with the requirements of the Civil Aviation Safety Regulation for the time being in force and in that respect the aircraft is consider fit for Release to Service.


Name : RIDZAL GHAZALI Stamp : 
Signature :  Place/Date : NABX, 25 NOV 2021

MAINTENANCE PROGRAM CESSNA C208/C208B

Chapter 16 – Inspection Document 10


Reg. Mark : PK - 8N3
MSN : C208B 5581
TSN / CSN : 2901:12 / 4339


Date : 28 NOV 2021
Station : NABUPE
WO No. : WO(088-8N3) / 01 / 2021

ITEM CODE NO.	ZONE	TASK	SIGNATURE	
			SIGN	STAMP
C221201	226 232	Autopilot Servos Lubrication Task 22-12-00-640		
A245001	121 122	Power Distribution Boxes Detailed Inspection Task 24-50-00-220		
A251001	231 232	Crew Seats Detailed Inspection Task 25-10-00-220		
A251003	231 232	Passenger Seats Detailed Inspection Task 25-21-00-220		
B271001	211 212 217 218 233 234 253 254 251 252 503 525 603 625	Spoiler System Functional Check Task 27-10-00-720		
C271003 RII	551 571 651 671	Aileron Trim Tab Actuator (2660044-1) Lubrication Task 27-10-02-641 <u>AILERON TRIM ACTUATOR 2661615-13</u>		
		RII Sign: <u>N/A</u> RII Stamp: <u>N/A</u>		
C273001 RII	371 372 375 376	Elevator Trim Tab Actuator (2660017-1) Lubrication Task 27-30-02-640 <u>ELEVATOR TRIM ACTUATOR 2661215-9</u>		
		RII Sign: <u>N/A</u> RII Stamp: <u>N/A</u>		
B284103	AUX	Fuel Quantity and Low Fuel Warning Systems Functional Check Task 28-41-00-720		
B313103	312	Flight Data Recorder Underwater Locator Beacon Functional Check Task 31-31-00-721		
B324001	ENG	Brakes Operational Check Task 32-40-00-710		

MAINTENANCE PROGRAM CESSNA C208/C208B

Chapter 16 – Inspection Document 10

ITEM CODE NO.	ZONE	TASK	SIGNATURE	
			SIGN	STAMP
B332001	AUX	Passenger/Cargo Compartment Lighting Operational Check Task 33-20-00-710		
A520001	801 802	Crew Doors Detailed Inspection Task 52-00-00-220		
A520003	255 256 257 258 803 804	Passenger/Cargo Doors and Door Frames Detailed Inspection Task 52-00-00-221		
A781001	130	Primary and Secondary Exhaust Duct General Visual Inspection Task 78-10-00-211		
*** End of Inspection Document 10 Items ***				

PERSONNEL PARTICIPATING IN THIS INSPECTION			
NAME	POSITION	SIGNATURE	LICENSE NUMBER
RIOTAL GHAZALI	ENGINEER		9694
Danur Pramu	Engineer		9687
firmman rosi Handan	MECHANIC		
PITEL AGARA	MECHANIC		

RETURN TO SERVICE

The work recorded above has been carried out in accordance with the requirements of the Civil Aviation Safety Regulation for the time being in force and in that respect the aircraft is consider fit for Release to Service.

Name : Danur Pramu Stamp : 

Signature :  Place/Date : MABIRE / 26 - NOV - 2021

MAINTENANCE PROGRAM CESSNA C208/C208B

Chapter 51 – Engine PT6A-140 100 Hours/Minor Inspection

Reg. Mark : PK - 8NU

Date : 26 NOV 2021

MSN : C208B 8881

Station : NBX

TSN / CSN : 2401812 / A339


WO No. : wo/oss-8nu/x1/2021

ITEM CODE NO.	ZONE	TASK	SIGNATURE	
			SIGN	STAMP
F710001	130	Do a check of the FCU manual override system for static operation. For the engines installed with a manual override system only.		
F710003	130	Do a compressor performance recovery wash		
F720000	130	Do a visual inspection of the Control Linkages and wiring.		
F720001	130	Do a visual inspection of the engine exhaust duct welds.		
F720002	130	Do a visual inspection of the engine exhaust duct for cracks.		
F720003	130	Do a visual inspection of the gas generator case and the center fireseal.		
F720004	130	Do a visual inspection of the rear fireseal mounting ring.		
F722001	130	Do a visual inspection of the air inlet screen.		
F723000	130	Do a visual inspection with a mirror or a borescope inspection of the First-stage Compressor Rotor and the inlet case for corrosion		
F725005	130	Do a detailed inspection of the turbine exhaust duct.		
F731002	130	Do a check for the fuel pump installation and leaks.		
F731003	130	Do a check of the oil-to- fuel heater installation		
F731035	130	Do a visual Inspection of the Fuel - Oil Heat Exchanger Fuel Filter Element (CLEANING / REPLACEMENT) P/N OFF: <u>AN 6235-3A</u> P/N ON: <u>NA 6235-3A</u>		

MAINTENANCE PROGRAM CESSNA C208/C208B

Chapter 51 – Engine PT6A-140 100 Hours/Minor Inspection

ITEM CODE NO.	ZONE	TASK	SIGNATURE	
			SIGN	STAMP
F731006	130	Do a check of the drain valve for installation and leaks		
F731007	130	Do a check of the flow divider for installation and leaks.		
F731008	130	Do a visual inspection of the P3 filter and drain valve.		
F731015	130	Do a visual inspection of Fuel Pump outlet filter. (CLEANING / REPLACEMENT) P/N OFF: <u>AN6235-3A</u> P/N ON: <u>AN6235-3A</u>		
F731018	130	Clean or replace the P3 filter based on condition, service experience or environment. Note: If corrosions are found, replace filter.		
F732001	130	Do a check of the FCU for installation, linkages and pneumatic tubes.		
F792000	130	Inspect and clean oil filter for debris.		
*** End of Engine PT6A-140 100 Hours Inspection Items ***				

PERSONNEL PARTICIPATING IN THIS INSPECTION			
NAME	POSITION	SIGNATURE	LICENSE NUMBER
RIZAL - G	ENGINEER		9694
Demar Præmua	Engineer		9687
pinjam rori H	MECHANIC		-
PITER AGAPA	MECHANIC		-

RETURN TO SERVICE

The work recorded above has been carried out in accordance with the requirements of the Civil Aviation Safety Regulation for the time being in force and in that respect the aircraft is consider fit for Release to Service.


Name : RIZAL - G Stamp : 
Signature :  Place/Date : MBX, 26 NOV 2021

MAINTENANCE PROGRAM CESSNA C208/C208B

Chapter 52 – Engine PT6A-140 200 Hours Inspection

Reg. Mark : PK - 8W Date : 25 NOV 2021
MSN : C208B 8851 Station : NABIRE
TSN / CSN : 2401:12 / 4339 WO No. : WO/055-8W/XI/2021

ITEM CODE NO.	ZONE	TASK	SIGNATURE	
			SIGN	STAMP
F793001	130	Do a visual inspection of the chip detector for debris.		
*** End of Engine PT6A-140 200 Hours Inspection Items ***				

PERSONNEL PARTICIPATING IN THIS INSPECTION			
NAME	POSITION	SIGNATURE	LICENSE NUMBER
RIZDAL GHAZALI	ENGINEER		9694
Dennis Praman	Engineer		9687.
Purman Toi H	MECHANIC		
PITAZ. AGARA	MECHANIC		

RETURN TO SERVICE

The work recorded above has been carried out in accordance with the requirements of the Civil Aviation Safety Regulation for the time being in force and in that respect the aircraft is consider fit for Release to Service.

Name : RIZDAL. G Stamp : 
Signature :  Place/Date : MBX, 25-11-2021

MAINTENANCE PROGRAM CESSNA C208/C208B

Chapter 53 – Engine PT6A-140 200 Hours or 6 Months Inspection

Reg. Mark	: PK - <u>GNU</u>	Date	: <u>25-11-2021</u>
MSN	: <u>C208B-5851</u>	Station	: <u>NABIRE</u>
TSN / CSN	: <u>2401:12 / 4339</u>	WO No.	: <u>W0/085-3NU/X1/2021</u>

ITEM CODE NO.	ZONE	TASK	SIGNATURE	
			SIGN	STAMP
F793000	130	Do a visual inspection of the AGB internal scavenge oil pump inlet screen		
*** End of Engine PT6A- 140 200 Hours or 6 Months Inspection Items ***				

PERSONNEL PARTICIPATING IN THIS INSPECTION			
NAME	POSITION	SIGNATURE	LICENSE NUMBER
<u>PIZZAL GHAZALI</u>	<u>ENGINEER</u>		<u>9694</u>
<u>Daniel Praven</u>	<u>Engineer</u>		<u>9687</u>
<u>Angen Tohi H.</u>	<u>MECHANIC</u>		-

RETURN TO SERVICE

The work recorded above has been carried out in accordance with the requirements of the Civil Aviation Safety Regulation for the time being in force and in that respect the aircraft is consider fit for Release to Service.

Name	: <u>PIZZAL, G</u>	Stamp	: 
Signature	: 	Place/Date	: <u>NABIR, 25-11-2021</u>



MAINTENANCE PROGRAM **CESSNA C208/C208B**

Chapter 54 – Engine PT6A-140 400 Hours Inspection

Reg. Mark : PK- SNV Date : 23 NOV 21
 MSN : C208B-5640 Station : MABIRE
 TSN/CSN : 2401:12 / 4339 WO No. : WO/055-SNV/X1/2021

ITEM CODE NO.	ZONE	TASK	SIGNATURE	
			SIGN	STAMP
F724000	130	Do borescope inspection of hot section components.		
F731004	130	Do a leak test and a functional test of the fuel manifold adapter and nozzle assemblies. Note: Engines ON fuel nozzle in-situ cleaning program (Ref. Task 71-00-00- 160-808). Test fuel nozzles and refurbish as necessary.		
F741001	130	Do a visual inspection of the ignition exciter.		
F741011	130	Do a visual inspection of the ignition cables.		
F742001	130	Do a functional check of the ignition cable.		
F742002	130	Do a visual inspection of the spark igniter/glow plugs. Note: Examine initially at 200 Hours.		
*** End of Engine PT6A-140 400 Hours Inspection Items ***				

PERSONNEL PARTICIPATING IN THIS INSPECTION			
NAME	POSITION	SIGNATURE	LICENSE NUMBER
AGUS SULAIMAN	ENG		6444.
Dewar Prawing	ENGINEER		9657.

RETURN TO SERVICE

The work recorded above has been carried out in accordance with the requirements of the Civil Aviation Safety Regulation for the time being in force and in that respect the aircraft is consider fit for Release to Service.

Name : AGUS SULAIMAN Stamp :
 Signature : Place/Date : MAB / 23 NOV 21






MAINTENANCE PROGRAM CESSNA C208/C208B

Chapter 55 – Engine PT6A-140 600 Hours Inspection

Reg. Mark : PK-SNV
MSN : C20805551
TSN / CSN : 2401:12 / 4339

Date : 24 NOVEMBER 2021
Station : NABIRE
WO No. : WO/055-SNV/XI/2021

ITEM CODE NO.	ZONE	TASK	SIGNATURE	
			SIGN	STAMP
F731005		Do a visual inspection of the fuel pump inlet screen.		
F753001		Do a visual inspection of the compressor bleed valve.		
F793002		Do a functional check of the chip detector.		
*** End of Engine PT6A-140 600 Hours Inspection Items ***				

PERSONNEL PARTICIPATING IN THIS INSPECTION			
NAME	POSITION	SIGNATURE	LICENSE NUMBER
Daur Pramu	ENGINEER		9687
Firman Ton H	MECHANIC		-
PETER AGARA	MECHANIC		-

RETURN TO SERVICE

The work recorded above has been carried out in accordance with the requirements of the Civil Aviation Safety Regulation for the time being in force and in that respect the aircraft is consider fit for Release to Service.

Name : Daur Pramu

Stamp : 

Signature : 

Place/Date : NABIRE / 25-NOV-2021



PT. SMART CAKRAWALA AVIATION

CERTIFICATE RETURN TO SERVICE SCHEDULED MAINTENANCE INSPECTION (CRS-SMI)

A/C TYPE	: CESSNA 208B	TTSN	: 2401 : 12.
A/C REG	: PK-SNV	TCSN	: 4339
MSN	: C208B-5551	DATE	: 26 NOV 2021

TYPE OF INSPECTION	: INSPECTION DOC. 10 & ADD TASK
DUE AT	: 2400 HOURS
REF	: MP 208/208B REV. 10

EXCEPTION

- NO EXCEPTION -

AUTHORIZED PERSON

I hereby certify that this aircraft has been maintained accordance with CASR and Maintenance Program.
Aircraft safe and airworthy for flight

NAME	CAT	AMEL/OTR NO	SIGN&STAMP	DATE
<i>Danar Prana</i>	AIRFRAME & POWER PLANT	<i>9687 / 026</i>	<i>[Signature]</i> 	<i>26 / NOV / 2021</i>
	EIRA			

THE NEXT DUE TYPE OF INSPECTION	: 100 Hours Inspection.
DUE AT	: 2500 hours

Form: SCA/MTC/049



EMERGENCY EQUIPMENT LIST INSPECTION & MONITOR

PT. SMART CAKRAWALA
AVIATION
DEPARTMENT TEKNIK
Form: SCA/MTC/023

DATE : 22 NOVEMBER 2021	A/C REG : PK-SNV
A/C TYPE : C 208B	CHECKER : PITER.A SIGN: <i>[Signature]</i>

No.	Description	P/N	S/N	Next Insp.	Remarks
1	Pilot Life Vest	P01202-201	19080030099	02 AUG. 2023	Good
2	Co-Pilot Life Vest	P01202-201	19080030019	02 AUG. 2023	Good
3	Pax Life Vest				
4	Pax Life Vest				
5	Pax Life Vest				
6	Pax Life Vest				
7	Pax Life Vest				
8	Pax Life Vest				
9	Pax Life Vest				
10	Pax Life Vest				
11	Pax Life Vest				
12	Pax Life Vest				
13	First Aid Kit	FL220-FAKFAA	0919-1381	02 JAN. 2022	Good
14	Crash Axe Installed	-	-	-	Good
15	Fire Extinguisher	C 352	F-60589867	30 OCT. 2022	Good
16	Life Raft (If Installed)				
17	Survival Kit (If Installed)	FL 220	5714	Nov. 2022	Good
OTHERS					



WO/055-SNV/XI/2021

Parts Used Sheet

WO# Nr:

PK-SNV

Aircraft Registration:

Part Used

[illegible]



Parts Used Sheet