





PT. SMART CAKRAWALA AVIATION

## WORK ORDER

Form: SCA/MTC/030

Subject :	No.	WO/061-SNV/XII/2021
Inspection Documen 20 (ELT Functional Check) due at January 2022	Date	28-Dec-2021
	A/C Reg.	PK-SNV C208B-5551
Reference : MP C208B REV. 10	Prepared By	TS
	Checked By	CI
	Approved By	TM
To : Engineer In Charge		
<b>Description :</b>  <ol style="list-style-type: none"><li>1. Perform Inspection Documen 20 (ELT Functional Check) due at January 2022</li><li>2. Make an entry in Maintenance Log.</li><li>3. Return the Completed Work Order and Form to PPC.</li></ol> <p>#If any finding, please close the routine card, and transferred to inspection card.</p>		
<b>Additional Work :</b>  - NIL -		
Compliance Statement  CARRIED OUT	Sign & Date Company Lic. No.:   (Engineer In Charge)	Signature   (Technical Manager)

**AIRCRAFT CHECK WORK SUMMARY**  
(Form: SCA/MTC/051)

DATE OF ISSUED	JO/WO #	TYPE OF MAINTENANCE	DATE OF ACCOMPLISHED		
28-Dec-2021	WO/061-SNV/XII/2021	Inspection Doc. 20 (ELT Functional Check)	01 JAN 2022		
A/C Type		Mfg. Serial Number	A/C Registration		
C208B		C208B-5551	PK-SNV		
AIRCRAFT DATA					
Subject	Pos #	Serial Number (SN)	TTSN/TCSN		
Engine	#1	PCE-VA0607	2491:53 / 4500		
	#2	-			
Propeller/Rotor	#1	181160	2491:53 / -		
	#2	-			
Landing Gear	NLG				
	LH MLG				
	RH MLG				
PACKAGE COVERED					
No	Subject	Qty	Remark		
1	Non-Routine Card	-			
2	Inspection Card	1			
3	Work Order	1			
4	Summary Inspection List	1			
5	Material and Tool List	-			
6	Escalation form	-			
7	CRS (SMI / Unscheduled Maintenance)	1			
INSPECTION CARD (IC) LIST (Finding during maintenance)					
No	Taskcard Ref	Subject	Status		Name/ Sign & Stamp
			Open	Close	
<u>IC-001</u>					
<u>IC-002</u>					
<u>IC-003</u>					
<u>IC-004</u>					
<u>IC-005</u>					
<u>IC-006</u>					

INSPECTION CARD (IC) LIST (Finding during maintenance)					
No	Taskcard Ref	Subject	Status		Name/ Sign & Stamp
			Open	Close	
<u>IC-007</u>					
<u>IC-008</u>					
<u>IC-009</u>					
<u>IC-010</u>					

Prepared by :  
Technical Support

Checked by :  
Chief Maintenance

Verified by :  
Chief Inspector

Approved by :  
Technical Manager

.....

.....

.....

.....



**SUMMARY INSPECTION ITEMS**  
(Form: SCA/MTC/050)

WO Ref: WO/061-SNV/XII/2021

NO.	TASK CARD NO.	DESCRIPTION	DATE	EST MHR	NAME	STAMP
1	CHAPTER 26	INSPECTION DOCUMENT 20 (ELT Functional Check)				





PT. SMART CAKRAWALA AVIATION

**CERTIFICATE RETURN TO SERVICE**  
SCHEDULED MAINTENANCE INSPECTION  
(CRS-SMI)

A/C TYPE : CESSNA 208B TTSN : 2491:53  
A/C REG : PK-SNV TCSN : 4500  
MSN : C208B-5551 DATE : 01 JAN 2022


TYPE OF INSPECTION : INSPECTION DOCUMENT 20 (ELT Functional Check)  
DUE AT : 31 January 2022  
REF : MP C208B REV. 10

EXCEPTION

NO EXCEPTION


**AUTHORIZED PERSON**

I hereby certify that this aircraft has been maintained accordance with CASR and Maintenance Program.  
Aircraft safe and airworthy for flight

NAME	CAT	AMEL/OTR NO	SIGN&STAMP	DATE
DENI SOTBALI	AIRFRAME & POWER PLANT	9632 SCA 20		01/01/2022
	EIRA			

THE NEXT DUE TYPE OF INSPECTION : INSPECTION DOCUMENT 20 ELT FUNCTIONAL CHECK 7  
DUE AT : JANUARY 2023

Form: SCA/MTC/049

		<b>INSPECTION CARD</b> (Form: SCA/MTC/ 048)			TECHNICAL DEPARTMENT	
---	--	--	--	--	-------------------------	--

1. CARD #	2. JO/WO #	3. ORIGINATOR	4. CARD REF	5. DATE	
6. A/C REG/MSN	7. A/C TYPE	8. TRADE	12. VENDOR ORDER #		
9. ZONE	10. STA	11. MTC TYPE			

13. DESCRIPTION/DEFECT-IF FINDING OF CPCP INSPECTION, PLEASE COMPLETE SET. 20	14 PPC/ENG	15 DATE

16. CORRECTIVE ACTION	17 MECH	18 ENG. LIC	19 DATE
Performed at A/C TT : ..... A/C TC /LDG : .....			

20. CORROSION INFORMATION					
LOCATION	CAUSE OF DAMAGE				
	<input type="checkbox"/> Environment				
	<input type="checkbox"/> Internal Leakage				
CORROSION <input type="checkbox"/> Isolated <input type="checkbox"/> Widespread	<input type="checkbox"/> Chemical Spill				
CORROSION LVL <input type="checkbox"/> 1 <input type="checkbox"/> 2 <input type="checkbox"/> 3	<input type="checkbox"/> LAV/Galley Spill				
PROPOSED ACTION <input type="checkbox"/> Doublers	<input type="checkbox"/> Blocked Drain				
<input type="checkbox"/> Others	<input type="checkbox"/> Wet Insulation Blanket				
.....	<input type="checkbox"/> Other				
21. If the defect is RII, Please Sign this card finally by RII Inspector				INSP	DATE
NOTICE OF INSPECTOR					

22. PARTS REQUIRED						
PART DESCRIPTION	PART NO	QTY	SERIAL NO		STATUS	
			ON	OFF	CLOSE	OPEN



23. TOOLS REQUIRED			
DESCRIPTION	PART NO. / MODEL	NEXT CALIBRATION DATE	STATUS

# MAINTENANCE PROGRAM CESSNA C208/C208B

## Chapter 26 – Inspection Document 20

Reg. Mark	: PK - SNV	Date	: 01 JANUARY 2022
MSN	: 208B - 5551	Station	: TIMIKA
TSN / CSN	: 2491:53 / 4500	WO No.	: WO / 061 - SNV / XII / 2021

ITEM CODE NO.	ZONE	TASK	SIGNATURE	
			SIGN	STAMP
B256005	220 311 312 340	ARTEX C406-N Emergency Locator Transmitter (ELT) Functional Check Task 25-60-00-722		
*** End of Inspection Document 20 Items ***				

PERSONNEL PARTICIPATING IN THIS INSPECTION			
NAME	POSITION	SIGNATURE	LICENSE NUMBER
DEVI SOBACI	ENGINEER		9632
YOHAN.S. DEPARI	MECHANIC		

### RETURN TO SERVICE

The work recorded above has been carried out in accordance with the requirements of the Civil Aviation Safety Regulation for the time being in force and in that respect the aircraft is consider fit for Release to Service.

Name	:	_____	Stamp	:	_____
Signature	:	_____	Place/Date	:	TIMIKA / 01-JAN - 2022




WO# Nr: WO/061-SNV/XII/2021

## Parts Used Sheet

[illegible]





## Parts Used Sheet

[illegible]

# AIRCRAFT FLIGHT MAINTENANCE LOG



elt - 2022-01-01 15:39:05

=====  
Result  
=====

Full Message

E0D32 5BF31 A4D78 99DAB 4FE0F F0F61

Hex ID

C1A64 B7E63 49AF1

Message Format

Long

Protocol Flag

User

Country Code

525 - Indonesia

Aircraft Address

PK-SNV

ELT Number

1st ELT

Radio-Locating

121.5 MHz

Position Data Source

External

Latitude Encoded

127° 0' 0" (Default)

Longitude Encoded

255° 0' 0" (Default)

Power

25.73 dBm

Frequency

406.0278 MHz