



PT. SMART CAKRAWALA AVIATION

**WORK ORDER**

Form: SCA/MTC/030

Subject : Inspection Document MG & Add Task Due at 5000 FH.	No.	WO/083-SNS/X/2021
	Date	02-Oct-2021
	A/C Reg.	PK-SNS C208B-2341
Reference : MP C208B Rev. 10	Prepared By	TS
	Checked By	CI
	Approved By	TM

To : Engineer In Charge

**Description :**

1. Perform Inspection Document MG & Add Task Due at 5000 FH.
2. Make an entry in Maintenance Log.
3. Return the Completed Work Order and Form to PPC.

#If any finding, please close the routine card, and transferred to inspection card.

**Additional Work :**

— NIL —

Compliance Statement <b>SATISFIED</b>	Sign & Date Company Lic. No.:  24/ OCT 2021 KRISTIYONO (Engineer In Charge)	Signature (Technical Manager)
--	--	----------------------------------



PT. SMART CAKRAWALA AVIATION

**CERTIFICATE RETURN TO SERVICE**  
SCHEDULED MAINTENANCE INSPECTION  
(CRS-SMI)

A/C TYPE	: CESSNA 208B	TTSN	: 5065 : 10
A/C REG	: PK-SNS	TCSN	: 2454
MSN	: C208B-2341	DATE	: 24 OCT 2021

TYPE OF INSPECTION	: INSPECTION DOC. MG & ADD TASK
DUE AT	: 5000 HOURS
REFF	: MP C208B REV. 9

EXCEPTION

— NIL —

**AUTHORIZED PERSON**

I hereby certify that this aircraft has been maintained accordance with CASR and Maintenance Program.  
Aircraft safe and airworthy for flight

NAME	CAT	AMEL/OTR NO	SIGN&STAMP	DATE
KRISTI YONO	AIRFRAME & POWER PLANT	7243 / SCA 08		24 / OCT 2021
	EIRA			

THE NEXT DUE TYPE OF INSPECTION : 100 HRS

DUE AT : 5079 : 00 HOURS

Form: SCA/MTC/049

**AIRCRAFT CHECK WORK SUMMARY**

(Form: SCA/MTC/051)

DATE OF ISSUED	JO/WO #	TYPE OF MAINTENANCE	DATE OF ACCOMPLISHED
02-Oct-2021	WO/083-SNS/X/2021	Inspection Doc. MG & Add Task	24 OCTOBER 2021

A/C Type C208B	Mfg. Serial Number C08B-2341	A/C Registration PK-SNS
-------------------	---------------------------------	----------------------------

**AIRCRAFT DATA**

Subject	Pos #	Serial Number (SN)	TTSN/TCSN
Engine	#1	PCE-PC1288	2136806 / 2758
	#2	-	
Propeller/Rotor	#1	111120	1207 : 47
	#2	-	
Landing Gear	NLG		5065 : 10 / 2454
	LH MLG		5065 : 10 / 2454
	RH MLG		5065 : 10 / 2454

**PACKAGE COVERED**

No	Subject	Qty	Remark
1	Non-Routine Card	-	
2	Inspection Card	1	
3	Work Order	1	
4	Summary Inspection List	1	
5	Material and Tool List	-	
6	Escalation form	-	
7	CRS (SMI / Unscheduled Maintenance)	1	

**INSPECTION CARD (IC) LIST (Finding during maintenance)**

No	Taskcard Ref	Subject	Status		Name/ Sign & Stamp
			Open	Close	
IC-001					
IC-002					
IC-003					
IC-004					
IC-005					
IC-006					

<u>IC-007</u>					
<u>IC-008</u>					
<u>IC-009</u>					
<u>IC-010</u>					
<u>IC-011</u>					
<u>IC-012</u>					
<u>IC-013</u>					
<u>IC-014</u>					
<u>IC-015</u>					

Prepared by :  
Technical Support

Checked by :  
Chief Maintenance

Verified by :  
Chief Inspector

Approved by :  
Technical Manager



**SUMMARY INSPECTION ITEMS**  
(Form: SCA/MTC/050)

WO Ref: WO/083-SNS/X/2021

NO.	TASK CARD NO.	DESCRIPTION	DATE	EST MHR	NAME	STAMP
1	CHAPTER 20	INSPECTION DOCUMENT 14	24 / OCT 2021		KRISTIYONO	
2	CHAPTER 36	INSPECTION DOCUMENT ME	24 / OCT 2021		KRISTIYONO	
3	CHAPTER 38	INSPECTION DOCUMENT MG	24 / OCT 2021		KRISTIYONO	



**INSPECTION CARD**  
(Form: SCA/MTC/ 048)

TECHNICAL  
DEPARTMENT

1. CARD #	2. JO/WO #	3. ORIGINATOR	4. CARD REF	5. DATE
6. A/C REG/MSN	7. A/C TYPE	8. TRADE	12. VENDOR ORDER #	
9. ZONE	10. STA	11. MTC TYPE		

13. DESCRIPTION/DEFECT-IF FINDING OF CPCP INSPECTION, PLEASE COMPLETE SET. 20	14 PPC/ENG	15 DATE

16. CORRECTIVE ACTION	17 MECH	18 ENG. LIC	19 DATE

Performed at A/C TT : ..... A/C TC /LDG : .....

20. CORROSION INFORMATION					
LOCATION	CAUSE OF DAMAGE				
	<input type="checkbox"/> Environment	<input type="checkbox"/> Internal Leakage	<input type="checkbox"/> Chemical Spill	<input type="checkbox"/> LAV/Galley Spill	
CORROSION <input type="checkbox"/> Isolated <input type="checkbox"/> Widespread	<input type="checkbox"/> Doublers	<input type="checkbox"/> Blocked Drain	<input type="checkbox"/> Wet Insulation Blanket		
CORROSION LVL <input type="checkbox"/> 1 <input type="checkbox"/> 2 <input type="checkbox"/> 3	<input type="checkbox"/> Others	<input type="checkbox"/> Other			
PROPOSED ACTION					
.....					
21. If the defect is RII, Please Sign this card finally by RII Inspector				INSP	DATE
NOTICE OF INSPECTOR					

22. PARTS REQUIRED						
PART DESCRIPTION	PART NO	QTY	SERIAL NO		STATUS	
			ON	OFF	CLOSE	OPEN

23. TOOLS REQUIRED			
DESCRIPTION	PART NO. / MODEL	NEXT CALIBRATION DATE	STATUS



## MAINTENANCE PROGRAM CESSNA C208/C208B

### Chapter 20 – Inspection Document 14

Reg. Mark	: <u>PK-SNS</u>	Date	: <u>24 OCTOBER 2021</u>
MSN	: <u>2088-2341</u>	Station	: <u>PNK</u>
TSN / CSN	: <u>5065:10/2454</u>	WO No.	: <u>W0/083-SNS/X/2021</u>

ITEM CODE NO.	ZONE	TASK	SIGNATURE	
			SIGN	STAMP
A532015	253 254	Fuselage Skin Doubler at Main Landing Gear Cutout Detailed Inspection (SID 53-20-14) Task 53-10-00-225		
*** End of Inspection Document 14 Items ***				

PERSONNEL PRTICIPATING IN THIS INSPECTION			
NAME	POSITION	SIGNATURE	LICENSE NUMBER
IBRAHIM			C.06.
KRISTIYONO	ENGINEER		7243

### RETURN TO SERVICE

The work recorded above has been carried out in accordance with the requirements of the Civil Aviation Safety Regulation for the time being in force and in that respect the aircraft is consider fit for Release to Service.

Name	: <u>KRISTIYONO</u>	Stamp	:
Signature	:	Place/Date	: <u>PNK /24 OCTOBER 2021</u>



# MAINTENANCE PROGRAM CESSNA C208/C208B

## Chapter 36 – Inspection Document ME

Reg. Mark	: <u>PK-SNS</u>	Date	: <u>24 OCTOBER 2021</u>
MSN	: <u>208B-2341</u>	Station	: <u>PNK</u>
TSN / CSN	: <u>5065:10/2454</u>	WO No.	: <u>WO/083-SNS/X/2021</u>

ITEM CODE NO.	ZONE	TASK	SIGNATURE	
			SIGN	STAMP
A570009	531 631	Wing Strut Fittings Special Detailed Inspection (Severe Inspection Compliance) (SID 57-60-01) <u>Task 57-10-01-251</u>		
*** End of Inspection Document ME Items ***				

PERSONNEL PRTICIPATING IN THIS INSPECTION			
NAME	POSITION	SIGNATURE	LICENSE NUMBER
KRISTIYONO	ENGINEER		7243
IBRAHIM			C.06.

### RETURN TO SERVICE

The work recorded above has been carried out in accordance with the requirements of the Civil Aviation Safety Regulation for the time being in force and in that respect the aircraft is consider fit for Release to Service.

Name	: <u>KRISTIYONO</u>	Stamp	:
Signature	:	Place/Date	: <u>PNK / 24 OCT 2021</u>



# MAINTENANCE PROGRAM CESSNA C208/C208B

## Chapter 38 – Inspection Document MG

Reg. Mark	: <u>PK-SNS</u>	Date	: <u>24 OCTOBER 2021</u>
MSN	: <u>208B-2341</u>	Station	: <u>PNK</u>
TSN / CSN	: <u>5065:10/2454</u>	WO No.	: <u>WO/083-SNS/X/2021</u>

ITEM CODE NO.	ZONE	TASK	SIGNATURE	
			SIGN	STAMP
A531006	251 252 253 254	Fuselage to Strut Attach Fitting Lugs (Nominal Standard Bolt Size) (Severe Inspection Compliance) Special Detailed Inspection (SID 53-20-07) Task 53-20-07-251		
*** End of Inspection Document MG Items ***				

PERSONNEL PRTICIPATING IN THIS INSPECTION			
NAME	POSITION	SIGNATURE	LICENSE NUMBER
KRISTIYONO	ENGINEER		7243
IBRAHIM			C.06

### RETURN TO SERVICE

The work recorded above has been carried out in accordance with the requirements of the Civil Aviation Safety Regulation for the time being in force and in that respect the aircraft is consider fit for Release to Service.

Name	: <u>KRISTIYONO</u>	Stamp	:
Signature	:	Place/Date	: <u>PNK / 24 OCT 2021</u>



## **Additional Work Sheet**

### **Inspection Doc. MG & Add Task**

PK-SNS

WO# Nr.: WO/083-SNS/X/2021

1

### Special Tools

No.	Description	Due Date	Engineer
1	NDT TOOLS / COPY CURRENT INSTRUMENT	27 JULY 2022	QUESTION
2			
3			
4			
5			
6			
7			
8			
9			
10			
11			
12			
13			
14			
15			
16			
17			
18			
19			
20			
21			
22			
23			
24			
25			
26			
27			
28			
29			
30			
31			
32			
33			
34			
35			
36			
37			
38			
39			
40			
41			
42			
43			
44			
45			
46			
47			
48			
49			
50			
51			
52			
53			
54			
55			
56			
57			
58			
59			
60			
61			
62			
63			
64			
65			
66			
67			
68			
69			
70			
71			
72			
73			
74			
75			
76			
77			
78			
79			
80			
81			
82			
83			
84			
85			
86			
87			
88			
89			
90			
91			
92			
93			
94			
95			
96			
97			
98			
99			
100			
101			
102			
103			
104			
105			
106			
107			
108			
109			
110			
111			
112			
113			
114			
115			
116			
117			
118			
119			
120			
121			
122			
123			
124			
125			
126			
127			
128			
129			
130			
131			
132			
133			
134			
135			
136			
137			
138			
139			
140			
141			
142			
143			
144			
145			
146			
147			
148			
149			
150			
151			
152			
153			
154			
155			
156			
157			
158			
159			
160			
161			
162			
163			
164			
165			
166			
167			
168			
169			
170			
171			
172			
173			
174			
175			
176			
177			
178			
179			
180			
181			
182			
183			
184			
185			
186			
187			
188			
189			
190			
191			
192			
193			
194			
195			
196			
197			
198			
199			
200			
201			
202			
203			
204			
205			
206			
207			
208			
209			
210			
211			
212			
213			
214			
215			
216			
217			
218			
219			
220			
221			
222			
223			
224			
225			
226			
227			
228			
229			
230			
231			
232			
233			
234			
235			
236			
237			
238			
239			
240			
241			
242			
243			
244			
245			
246			
247			
248			
249			
250			
251			
252			
253			
254			
255			
256			
257			
258			
259			
260			
261			
262			
263			
264			
265			
266			
267			
268			
269			
270			
271			
272			
273			
274			
275			
276			
277			
278			
279			
280			
281			
282			
283			
284			
285			
286			
287			
288			
289			
290			
291			
292			
293			
294			
295			
296			
297			
298			
299			
300			
301			
302			
303			
304			
305			
306			
307			
308			
309			
310			
311			
312			
313			
314			
315			
316			
317			
318			
319			
320			
321			
322			
323			
324			
325			
326			
327			
328			
329			
330			
331			
332			
333			
334			
335			
336			
337			
338			
339			
340			
341			
342			
343			
344			
345			
346			
347			
348			
349			
350			
351			
352			
353			
354			
355			
356			
357			
358			
359			
360			
361			
362			
363			
364			
365			
366			
367			
368			
369			
370			
371			
372			
373			
374			
375			
376			
377			
378			
379			
380			
381			
382			
383			
384			
385			
386			
387			
388			
389			
390			
391			
392			
393			
394			
395			
396			
397			
398			
399			
400			
401			
402			
403			
404			
405			
406			
407			
408			
409			
410			
411			
412			
413			
414			
415			
416			
417			
418			
419			
420			
421			
422			
423			
424			
425			
426			
427			
428			
429			
430			
431			
432			
433			
434			
435			
436			
437			
438			
439			
440			
441			
442			
443			
444			
445			
446			
447			
448			
449			
450			
451			
452			
453			
454			
455			
456			
457			
458			
459			
460			
461			
462			
463			
464			
465			
466			
467			
468			
469			
470			
471			
472			
473			
474			
475			
476			
477			
478			
479			
480			
481			
482			
483			
484			
485			
486			
487			
488			
489			
490			
491			
492			
493			
494			
495			
496			
497			
498			
499			
500			
501			
502			
503			
504			
505			
506			
507			
508			



Aircraft Registration: **PK-SNS**

WO# Nr: WO/083-SNS/X/2021



## **Additional Work Sheet**

### **Inspection Doc. MG & Add Task**

2  
Parts Used Sheet

Part Used					
Date	Part Nr.	Serial Nr.	Description	Quantity	Engineer
24 Oct 2021	MS 24665-360	-	COTTER PIN	4-20	KUS TIRKUO