

Reg. Mark : PK-SNX



Date : 16/10/2023

MSN : 53467

Station : MJU

TSN /CSN : 961:51/2330

WO No. : WO/096-PK-SNX/X/2023

ITEM CODE NO	ZONE	TASK	SIGNATURE	
			ENGINEER SIGN & STAMP	RII SIGN & STAMP
62/21/00 /000/000 /145	62-21	Spherical bearing 57910700 (704A33633211) LB4-1231-1 (704A33633208) Check of the elastomer part. GVI AMM05-40-00,6-7	 IRWAN	N/A
62/21/00 /000/000 /185	62-21	Frequency adapter 365A31-1019-25 (-) E-4165F01 (704A33640088) E-4165F11 (704A33640100) Check of the elastomer part. Must not be mixed together. GVI AMM05-40-00,6-7	 IRWAN	N/A

PERSONNEL PARTICIPATION IN THIS INSPECTION			
NAME	POSITION	SIGNATURE	LICENSE NUMBER

RETURN TO SERVICE

The work recorded above has been carried out in accordance with the requirements of the Civil Aviation Safety Regulation for the time being in force and in that respect the aircraft in the consider fit for Release to Service.

Name : IRWAN

Place/Date : MJU, 16/10/2023

Sign & Stamp :  IRWAN

Reg. Mark : PK-SNX








Date : _____





MSN : 53467

Station : _____

TSN /CSN : _____

WO No. : WO/096-PK-SNX/X/2023

ITEM CODE NO	ZONE	TASK	SIGNATURE	
			ENGINEER SIGN & STAMP	RII SIGN & STAMP
N/A	N/A	Record the corrective maintenance operations performed in the engine log book, if any.		N/A
N/A	N/A	Make sure that the automatic cycle counting is correct. EMM 05-10-02-200-801		N/A
N/A	N/A	In the engine log book, record the total number of C1 and C2 cycles consumed as counted by the EECU. EMM 05-10-02-200-801		N/A
N/A	N/A	Visually examine the engine and the engine floor for leakage.		N/A
N/A	N/A	Visually examine the engine attachments and fire protections for signs of impact or deterioration. Refer to Helicopter Manual Note: Fire protections of shut off valve and HMU		N/A
N/A	N/A	Record the values from the creep damage counter in the engine logbook. EMM 05-15-00-200-801		N/A
N/A	N/A	Record in the engine logbook the accumulation of flying hours. EMM 05-10-02-200-801		N/A

ITEM CODE NO	ZONE	TASK	SIGNATURE	
			ENGINEER SIGN & STAMP	RII SIGN & STAMP
N/A	N/A	Check that the HP gas generator rotates freely (no abnormal noises) and visually check that the engine is in good condition. Note: Manually or during a dry crank cycle		N/A
N/A	N/A	Manually check that the power turbine rotates freely (no abnormal noises). EMM 05-10-02-200-801		N/A
N/A	N/A	Inspection of oil level in tank and top up if required. Refer to Helicopter Manual Note: Within 15 minutes following engine shut-down.		N/A
N/A	N/A	Make sure that there are no foreign objects: examine near the air intakes and the exhaust zone. Install the blanks.		N/A

PERSONNEL PARTICIPATION IN THIS INSPECTION

NAME	POSITION	SIGNATURE	LICENSE NUMBER

RETURN TO SERVICE

The work recorded above has been carried out in accordance with the requirements of the Civil Aviation Safety Regulation for the time being in force and in that respect the aircraft in the consider fit for Release to Service.

Name : _____ Place/Date : , _____

Sign & Stamp : _____

Reg. Mark : PK-SNX


Date : 16/10/2023

MSN : 53467

Station : MJU

TSN /CSN : 961:51/2330

WO No. : WO/096-PK-SNX/X/2023

ITEM CODE NO	ZONE	TASK	SIGNATURE	
			ENGINEER SIGN & STAMP	RII SIGN & STAMP
62/11/00 /000/000 /065	62-11	Main rotor blade Sand-laden and/or dust-laden atmosphere Check for erosion. In the event of intensive operation in heavily sand-laden areas, all the necessary measures should be taken to ensure optimum operation of the aircraft. GVI AMM 62-11-00, 6-1		N/A

PERSONNEL PARTICIPATION IN THIS INSPECTION			
NAME	POSITION	SIGNATURE	LICENSE NUMBER

RETURN TO SERVICE

The work recorded above has been carried out in accordance with the requirements of the Civil Aviation Safety Regulation for the time being in force and in that respect the aircraft in the consider fit for Release to Service.

Name : IRWAN

Place/Date : MJU, 16/10/2023

Sign & Stamp :  _____

Reg. Mark : PK-SNX




Date : 16/10/2023

MSN : 53467

Station : MJU

TSN /CSN : 961:51/2330

WO No. : WO/096-PK-SNX/X/2023

ITEM CODE NO	ZONE	TASK	SIGNATURE	
			ENGINEER SIGN & STAMP	RII SIGN & STAMP
05/21/00 /000/000 /020	05-21	P-check VC AMM 05-40-00, 6-7	 IRWAN	N/A
05/21/00 /000/000 /030	05-21	P-check - Optional equipments Note: Maintenance operations can be carried out by an aircrew member. VC AMM 05-40-00, 6-8	 IRWAN	N/A
53/00/00 /000/000 /050	53-00	Structure Salt-laden atmosphere Rinsing and Drying. CLN AMM 12-20-00, 3-3	 IRWAN	N/A

PERSONNEL PARTICIPATION IN THIS INSPECTION			
NAME	POSITION	SIGNATURE	LICENSE NUMBER

RETURN TO SERVICE

The work recorded above has been carried out in accordance with the requirements of the Civil Aviation Safety Regulation for the time being in force and in that respect the aircraft in the consider fit for Release to Service.

Name : IRWAN

Place/Date : MJU, 16/10/2023

Sign & Stamp : 
IRWAN