





PT. SMART CAKRAWALA AVIATION

WORK ORDER

Form: SCA/MTC/030

Subject : Perform Hoses Assy Replacement Due on 31 March 2022.	No.	WO/096-SNS/II/2022
	Date	25-Feb-2022
	A/C Reg.	PK-SNS C208B-2341
Reference : MP C208B Rev. 10	Prepared By	TS
	Checked By	CI
	Approved By	TM
To : Engineer In Charge		
Description : 1. Perform Hoses Assy Replacement Due on 31 March 2022. 2. Make an entry in Maintenance Log. 3. Return the Completed Work Order and Form to PPC. #If any finding, please close the routine card, and transferred to inspection card.		
Additional Work : — NIL —		
Compliance Statement <i>CARRIED OUT</i>	Sign & Date Company Lic. No.:  (Engineer In Charge) 31 MARCH 2022	Signature  (Technical Manager)

AIRCRAFT CHECK WORK SUMMARY
(Form: SCA/MTC/051)

DATE OF ISSUED	JO/WO #	TYPE OF MAINTENANCE	DATE OF ACCOMPLISHED	
25-Feb-2022	WO/096-SNS/II/2022	Hoses Assy Replacement	31 MARCH 2022	
A/C Type				
C208B	Mfg. Serial Number		A/C Registration	
	C08B-2341		PK-SNS	
AIRCRAFT DATA				
Subject	Pos #	Serial Number (SN)	TTSN/TCSN	
Engine	#1	PCE-PC1937	5535:53/6047	
	#2	-		
Propeller/Rotor	#1	170666	1676:25/6047	
	#2	-		
Landing Gear	NLG		5535:53/6047	
	LH MLG		5535:53/6047	
	RH MLG		5535:53/6047	
PACKAGE COVERED				
No	Subject	Qty	Remark	
1	Non-Routine Card	2		
2	Inspection Card	1		
3	Work Order	1		
4	Summary Inspection List	1		
5	Material and Tool List	-		
6	Escalation form	-		
7	CRS (SMI / Unscheduled Maintenance)	1		
INSPECTION CARD (IC) LIST (Finding during maintenance)				
No	Taskcard Ref	Subject	Status Open Close	Name/ Sign & Stamp
	IC-001			
	IC-002			
	IC-003			

Prepared by :
Technical Support

Checked by :
Chief Maintenance

Verified by :
Chief Inspector

Approved by :
Technical Manager



SUMMARY INSPECTION ITEMS
(Form: SCA/MTC/050)

WO Ref: WO/096-SNS/II/2022

NO.	TASK CARD NO.	DESCRIPTION	DATE	EST MHR	NAME	STAMP
1	NRC 001	FUEL TO ENGINE HOSE - AE3663726H0520 PN : S2808-8B0520 SN : NSN	31/03/22		DENI SOPACI	
2	NRC 002	MOTIVE FLOW HOSE - AE3663724G0330 PN : S2808-6-0330 SN : NSN	31/03/22		DENI SOPACI	



PT. SMART CAKRAWALA AVIATION

CERTIFICATE RETURN TO SERVICE

SCHEDULED MAINTENANCE INSPECTION

(CRS-SMI)

A/C TYPE : CESSNA 208B TTSN : 5535:53
A/C REG : PK-SNS TCSN : 6047
MSN : C208B-2341 DATE : 31 MARCH 22

TYPE OF INSPECTION : PERFORMED HOSES ASSY REPLACEMENT
DUE AT : MAR 2022
REFF : MP C208B REV. 10
EXCEPTION

NO EXCEPTION

AUTHORIZED PERSON

I hereby certify that this aircraft has been maintained accordance with CASR and Maintenance Program.
Aircraft safe and airworthy for flight

NAME	CAT	AMEL/OTR NO	SIGN&STAMP	DATE
DENI SOBALI	AIRFRAME & POWER PLANT	8632 SCA 20		31 / MARCH 22
	EIRA			

THE NEXT DUE TYPE OF INSPECTION : 31 MARCH 2032 CACENDER INST.
DUE AT : HOURS 10 YEARS CACENDER INST

Form: SCA/MTC/049



22. PARTS REQUIRED						
PART DESCRIPTION	PART NO	QTY	SERIAL NO		STATUS	
			ON	OFF	CLOSE	OPEN

23. TOOLS REQUIRED			
DESCRIPTION	PART NO. / MODEL	NEXT CALIBRATION DATE	STATUS



NON ROUTINE CARD
(Form: SCA/MTC/047)

1. JO/WO #	2. DATE	3. MTC TYPE	4. A/C REG/MSN
WO/096-SNS/II/2022	25-Feb-2022	REPLACEMENT	PK-SNS/208B-2341
5. CARD #	6. ATA SPEC	7. TRADE	8. STA
#001	28		
9. ZONE	10. PANEL		

11. DESCRIPTION PERFORM REPLACE HOSES ASSY			
PN OFF : S2808-8B0520 PN ON : <u>S2808-8B0520</u>			
SN OFF : SNS SN ON : <u>-</u>			
REFERENCE	<input checked="" type="checkbox"/> AMM Ch. 28-21-00	<input type="checkbox"/> EMM Ch	<input type="checkbox"/> OTHER
RII (*)	<input type="checkbox"/> Y	<input checked="" type="checkbox"/> N	MHR :

12. RESULT		MECH	ENG	INSP (*)
<u>PERFORMED REPLACE HOSE ASSY</u> <u>WITH NEW PBF TO CH 28-21-00.</u> Performed at A/C TT : <u>5535:53</u> A/C TC /LDG : <u>6047</u>			<u>DENT</u> <u>503mi</u>	
FINDING	<input type="checkbox"/> Y <input type="checkbox"/> N	ACT MHR :		DATE/TIME (DD/MM/YY)
INSPECTION CARD (IC) #		<u>31</u>	<u>03</u>	<u>2022</u>

13. PARTS REQUIRED				
DESCRIPTION	PART NO	QTY	REMARK	
			STOCK	STATUS
<u>HOSE ASSY</u>	<u>S2808-8B0520</u>	<u>1</u>		

14. TOOLS REQUIRED			
DESCRIPTION	PART NO / MODEL	NEXT CALIBRATION DATE	STATUS
<u>GENERAL TOOLS</u>	<u>-</u>	<u>-</u>	<u>Good</u>



NON ROUTINE CARD
(Form: SCA/MTC/047)



1. JOWO #	2. DATE	3. MTC TYPE	4. A/C REG/MSN
WO/096-SNS/II/2022	25-Feb-2022	REPLACEMENT	PK-SNS/208B-2341
5. CARD #	6. ATA SPEC	7. TRADE	8. STA
#002	28		
9. ZONE	10. PANEL		

11. DESCRIPTION PERFORM REPLACE HOSES ASSY			
PN OFF : S2808-6-0330		PN ON : <u>S2808-6-0330</u>	
SN OFF : SNS		SN ON : <u>-</u>	
REFERENCE	<input checked="" type="checkbox"/> AMM Ch. 28-21-00	<input type="checkbox"/> EMM Ch	<input type="checkbox"/> OTHER
RII (*)	<input type="checkbox"/> Y	<input checked="" type="checkbox"/> N	MHR :

12. RESULT		MECH	ENG	INSP (*)
<p>PERFORMED REPLACED HOSE ASSY WITH NEW. PERFORMED LEAK TEST FOUND SATISFY REF TO 28-21-00 1 VIEW REV.37</p> <p>Performed at A/C TT : <u>535:53</u> A/C TC /LDG : <u>6047</u></p>			<p>DEAT</p> <p>803AL</p>	
FINDING	<input type="checkbox"/> Y <input type="checkbox"/> N	ACT MHR :		DATE/TIME (DD/MM/YY)
INSPECTION CARD (IC) #		3/	03	2022

13. PARTS REQUIRED				
DESCRIPTION	PART NO	QTY	REMARK	
			STOCK	STATUS
HOSES ASSY	S 2808-6-0330	1		



14. TOOLS REQUIRED			
DESCRIPTION	PART NO / MODEL	NEXT CALIBRATION DATE	STATUS
GENERAL TOOL	-	-	(GOOD)




Parts Used Sheet

1

[illegible][illegible]



Parts Used Sheet 2

[illegible]

No	DISCREPANCIES (write NIL or A/C OK if No Defect)	No	CORRECTIVE ACTION	Sign, Stamp & Date			
1.	PERFORM HOSES ASSY REPLACEMENT DUE ON 31 MARCH 2022 REF TO WO 1096-SNS /11/2022	1.	PERFORMED REPLACED HOSER ASSY. REF TO MP C208B REV-10 DETAIL JOB REF TO: WO 1096-SNS /11/2022.	 31 MARCH 22			
			URGENT DUE AT: 31 MARCH 2032 DUE BY CALENDER				
No	COMPONENT CHANGE (Description)	POS	P/N On:	P/N Off:	S/N On:	S/N Off:	LIC NO. & SIGN
	WO 1096-SNS /11/2022		-	-	-	'	