






PT. SMART CAKRAWALA AVIATION

WORK ORDER

Form: SCA/MTC/030

Subject : Out of Phase – Update Navigation Database	No.	WO/103-SNS/VI/2022
	Date	13 June 2022
	A/C Reg.	PK-SNS C208B-2341
Reference : MP C208B REV. 10	Prepared By	TS
	Checked By	CI
	Approved By	TM
To : Engineer In Charge		
Description : <ol style="list-style-type: none">1. Perform Out of Phase – Update Navigation Database2. Make an entry in Maintenance Log.3. Return the Completed Work Order and Form to PPC. <p>#If any finding, please close the routine card, and transferred to inspection card.</p>		
Additional Work : -NIL-		
Compliance Statement UPDATE NAVIGATION DATABASE c/o	Sign & Date 16 June 2022 Company Lic. No.: SCA 28  HERDORO (Engineer In Charge) 	Signature  (Technical Manager)

Appendix B - Form: SCA/MTC/030

AIRCRAFT CHECK WORK SUMMARY
(Form: SCA/MTC/051)

DATE OF ISSUED	JO/WO #	TYPE OF MAINTENANCE	DATE OF ACCOMPLISHED		
13 June 2022	WO/103-SNS/VI/2022	Update Navigation Database	16 JUNE 2022		
A/C Type		Mfg. Serial Number	A/C Registration		
C208B		C208B-2341	PK-SNS		
AIRCRAFT DATA					
Subject	Pos #	Serial Number (SN)	TTSN/TCSN		
Engine	#1	PCE-PC1288	5678:07 / 6222 +P		
	#2	-	2444:36 / 3532		
Propeller/Rotor	#1	111120	1798:31 / 1798:31		
	#2	-			
Landing Gear	NLG		6222 / 6222		
	LH MLG		6222 / 6222		
	RH MLG		6222 / 6222		
PACKAGE COVERED					
No	Subject	Qty	Remark		
1	Non-Routine Card	-			
2	Inspection Card	1	✓		
3	Work Order	1	✓		
4	Summary Inspection List	1	✓		
5	Material and Tool List	-			
6	Escalation form	-			
7	CRS (SMI / Unscheduled Maintenance)	1	✓		
INSPECTION CARD (IC) LIST (Finding during maintenance)					
No	Taskcard Ref	Subject	Status		Name/ Sign & Stamp
			Open	Close	
<u>IC-001</u>					
<u>IC-002</u>					
<u>IC-003</u>					
<u>IC-004</u>					
<u>IC-005</u>					
<u>IC-006</u>					


<u>IC-007</u>				
<u>IC-008</u>				
<u>IC-009</u>				
<u>IC-010</u>				
<u>IC-011</u>				
<u>IC-012</u>				
<u>IC-013</u>				
<u>IC-014</u>				
<u>IC-015</u>				

Prepared by :
Technical Support


Checked by :
Chief Maintenance

Verified by :
Chief Inspector


Approved by :
Technical Manager




Dwi M



Dodit



Yanuar



Istiono



SUMMARY INSPECTION ITEMS
(Form: SCA/MTC/050)

WO Ref: WO/103-SNS/VI/2022

NO.	TASK CARD NO.	DESCRIPTION	DATE	EST MHR	NAME	STAMP
1	APPENDIX C01	OOP34001 / UPDATED NAVIGATION DATABASE	16 JUN 22	0.5 MHR	HENRHO	



PT. SMART CAKRAWALA AVIATION

CERTIFICATE RETURN TO SERVICE
 SCHEDULED MAINTENANCE INSPECTION
 (CRS-SMI)

A/C TYPE	: CESSNA 208B	TTSN	: 5679:57
A/C REG	: PK-SNS	TCSN	: 6222
MSN	: C208B-2341	DATE	: 16 JUNE 2022

TYPE OF INSPECTION : OUT OF PHASE – UPDATE NAVIGATION DATABASE
 DUE AT : 16 June 2022
 REFF : MP C208B REV. 10

EXCEPTION

- NO EXCEPTION -

AUTHORIZED PERSON

I hereby certify that this aircraft has been maintained accordance with CASR and Maintenance Program.
 Aircraft safe and airworthy for flight

NAME	CAT	AMEL/OTR NO	SIGN&STAMP	DATE
HENDRO	AIRFRAME & POWER PLANT	5583/28		16 JUN 22
<hr/>	EIRA	<hr/>	<hr/>	

THE NEXT DUE TYPE OF INSPECTION : UPDATE NAVIGATION DATA BASE
 DUE AT : 14 JULY 2022

Form: SCA/MTC/049



INSPECTION CARD

(Form: SCA/MTC/ 048)

TECHNICAL
DEPARTMENT

1. CARD #	2. JO/WO #	3. ORIGINATOR	4. CARD REF	5. DATE
	WO/103-SNS/VI/2022			
6. A/C REG/MSN	7. A/C TYPE	8. TRADE	12. VENDOR ORDER #	
PK-SNS / 2341	C208B			
9. ZONE	10. STA	11. MTC TYPE		

13. DESCRIPTION/DEFECT-IF FINDING OF CPCP INSPECTION, PLEASE COMPLETE SET. 20	14	15
	PPC/ENG	DATE

16. CORRECTIVE ACTION	17	18	19
	MECH	ENG. LIC	DATE
<p>Performed at A/C TT : A/C TC /LDG :</p>			



20. CORROSION INFORMATION			
LOCATION	CAUSE OF DAMAGE		
	<input type="checkbox"/> Environment		
	<input type="checkbox"/> Internal Leakage		
CORROSION <input type="checkbox"/> Isolated <input type="checkbox"/> Widespread	<input type="checkbox"/> Chemical Spill		
CORROSION LVL <input type="checkbox"/> 1 <input type="checkbox"/> 2 <input type="checkbox"/> 3	<input type="checkbox"/> LAV/Galley Spill		
PROPOSED ACTION <input type="checkbox"/> Doublers	<input type="checkbox"/> Blocked Drain		
<input type="checkbox"/> Others	<input type="checkbox"/> Wet Insulation Blanket		
.....	<input type="checkbox"/> Other		
21. If the defect is RII, Please Sign this card finally by RII Inspector			INSP
NOTICE OF INSPECTOR			DATE


22. PARTS REQUIRED						
PART DESCRIPTION	PART NO	QTY	SERIAL NO		STATUS	
			ON	OFF	CLOSE	OPEN

23. TOOLS REQUIRED			
DESCRIPTION	PART NO. / MODEL	NEXT CALIBRATION DATE	STATUS

Appendix C01 – OOP34001 / Update Navigation Database


Reg. Mark	: PK - SNS	Date	: 16 JUNE 2022
MSN	: 208B-2341	Station	: MEPAUKE
TSN / CSN	: 5679.57/6222	WO No.	: WO/103-SNS/VI/2022


NO.	ZONE	TASK	SIGNATURE	
			SIGN	STAMP
01	211 212	Update Navigation Database. • G1000 Line Maintenance Manual, Doc. No. 190-00869-00, Rev. G. • G1000 NXi Supplemental Maintenance Manual, Doc. No. 190-02128-04, Rev. 3		
*** End of Appendix C01 Items ***				

PERSONNEL PARTICIPATING IN THIS INSPECTION			
NAME	POSITION	SIGNATURE	LICENSE NUMBER
HENDRO	ENGINEER		5583

RETURN TO SERVICE

The work recorded above has been carried out in accordance with the requirements of the Civil Aviation Safety Regulation for the time being in force and in that respect the aircraft is consider fit for Release to Service.

Name : HENDRO Stamp : 

Signature :  Place/Date : MKG / 16 JUNE 2022