



PT. SMART CAKRAWALA AVIATION

WORK ORDER

Form: SCA/MTC/030

Subject : Inspection Doc. 12 - 1600TFH&Add. Task	No.	WO/031-SNV/XII/2022
	Date	7 Dec 2022
	A/C Reg.	PK-SNV C208B-5551
Reference : MP C208B Rev. 12	Prepared By	TS
	Checked By	CI
	Approved By	TM

To : Engineer In Charge

Description :

1. Perform Inspection Doc. 12 - 1600TFH&Add.Task
2. Make an entry in Maintenance Log.
3. Return the Completed Work Order and Form to PPC.

#If any finding, please close the routine card, and transferred to inspection card.

Additional Work :

Compliance
Statement

Carried out

Sign & Date
Company Lic. No.:

[Signature] # 3011





(Engineer In Charge)

Signature

[Signature]

(Technical Manager)

AIRCRAFT CHECK WORK SUMMARY
(Form: SCA/MTC/051)

DATE OF ISSUED	JO/WO #	TYPE OF MAINTENANCE	DATE OF ACCOMPLISHED		
7 Dec 2022	WO/031-SNV/XII/2022	Insp.1600TFH&Add.Task	16 JANUARY 2022.		
A/C Type		Mfg. Serial Number	A/C Registration		
C208B		C208B-5551	PK-SNV		
AIRCRAFT DATA					
Subject	Pos #	Serial Number (SN)	TTSN/TCSN		
Engine	#1	PCE-VA0607	3190:10 / 5287		
	#2	-			
Propeller/Rotor	#1	181160	3190:10 / 5287		
	#2	-			
Landing Gear	NLG		3190:10 / 5287		
	LH MLG				
	RH MLG				
PACKAGE COVERED					
No	Subject	Qty	Remark		
1	Non-Routine Card	2			
2	Inspection Card	1			
3	Work Order	1			
4	Summary Inspection List	1			
5	Material and Tool List	-			
6	Escalation form	-			
7	CRS (SMI / Unscheduled Maintenance)	1			
INSPECTION CARD (IC) LIST (Finding during maintenance)					
No	Taskcard Ref	Subject	Status		Name/ Sign & Stamp
			Open	Close	
IC-001	D121001	LH & RH SIDE BRAKE DISC OUT OF LIMIT	-	✓	 ROHPININDO
IC-002	D121001	BRAKE LINING RH SIDE AT BACK PLATE NEED TO BE REPLACE	-	✓	 ROHPININDO
IC-003	D121001	FOUND LEAKING AT BRAKE LH SIDE POSITION NO #3 & #4	-	✓	 ROHPININDO
IC-004	F7A2001	RH SIDE CABLE LEAD IGNITER NEED TO BE REPLACE	-	✓	 Daur Proun
IC-005					
IC-006					

<u>IC-007</u>					
<u>IC-008</u>					
<u>IC-009</u>					
<u>IC-010</u>					
<u>IC-011</u>					
<u>IC-012</u>					
<u>IC-013</u>					
<u>IC-014</u>					
<u>IC-015</u>					

Prepared by :
Technical Support



.....
Hani

Checked by :
Chief Maintenance



.....
Dodit

Verified by :
Chief Inspector



.....
Yanuar

Approved by :
Technical Manager



.....
Istiono



SUMMARY INSPECTION ITEMS (Form: SCA/MTC/050)

WO Ref: WO/031-SNV/XII/2022

NO.	TASK CARD NO.	DESCRIPTION	DATE	EST MHR	NAME	STAMP
1	B03	PT6A-140 ENGINE GROUND RUN PERFORMANCE	16/01/2023		Denur Pramu	(26)
2	CHAPTER 12	INSPECTION DOCUMENT 06	10/01/2023		POHPININDO	(11)
3	CHAPTER 13	INSPECTION DOCUMENT 07	12/01/2023		POHPININDO	(11)
4	CHAPTER 14	INSPECTION DOCUMENT 08	13/01/2023		POHPININDO	(11)
5	CHAPTER 15	INSPECTION DOCUMENT 09	15/01/2023		Denur Pramu	(26)
6	CHAPTER 16	INSPECTION DOCUMENT 10	15/01/2023		Denur Pramu	(26)
7	CHAPTER 17	INSPECTION DOCUMENT 11	18/01/2023		Denur Pramu	(26)
8	CHAPTER 18	INSPECTION DOCUMENT 12	18/01/2023		Denur Pramu	(26)
7	CHAPTER 7	INSPECTION DOCUMENT 01	15/01/2023		Denur Pramu	(26)
8	CHAPTER 51	ENGINE PT6A-140 100 HOUR INSPECTION/ MINOR INSPECTION	15/01/2023		Denur Pramu	(26)
9	CHAPTER 52	ENGINE PT6A-140 200 HOUR INSPECTION	18/01/2023		Denur Pramu	(26)
10	CHAPTER 53	ENGINE PT6A-140 200 HOUR / 6 MONTHS INSPECTION	16/01/2023		Denur Pramu	(26)
11	CHAPTER 54	ENGINE PT6A-140 400 HOUR INSPECTION	16/01/2023		Denur Pramu	(26)
12	CHAPTER 55	ENGINE PT6A-140 600 HOUR INSPECTION	16/01/2023		Denur Pramu	(26)
13	SCA/MTC/023	EMERGENCY EQUIPMENT CHECK	18/01/2023		Denur Pramu	(26)

		INSPECTION CARD (Form: SCA/MTC/ 048)		TECHNICAL DEPARTMENT		
1. CARD #		2. JOWO #		5. DATE		
1C-001		W01031-SNV/X11/2022		10 JAN 2022		
6. A/C REG/MSN		7. A/C TYPE		12. VENDOR ORDER #		
PK-SNV		C208B-EX				
9. ZONE		10. STA				
LANDING GEAR		KOPANG				
		8. TRADE		11. MTC TYPE		
		REPLACEMENT				
13. DESCRIPTION/DEFECT-IF FINDING OF CPCP INSPECTION, PLEASE COMPLETE SET. 20				14		
				PPC/ENG		
LH & RH SIDE BRAKE DISC OUT OF LIMIT NEED TO BE REPLACE				15		
				DATE		
16. CORRECTIVE ACTION				17		
				MECH		
REPLACED WITH NEW BRAKE DISC REFF TO AIRM CH. 32-40-00. Performed at A/C TT: 3189.26 A/C TC/LDG: 5285				18		
				ENG. LIC		
20. CORROSION INFORMATION				19		
				DATE		
LOCATION		CAUSE OF DAMAGE				
		☐ Environment				
		☐ Internal Leakage				
CORROSION ☐ Isolated ☐ Widespread		☐ Chemical Spill				
CORROSION LVL ☐ 1 ☐ 2 ☐ 3		☐ LAV/Galley Spill				
PROPOSED ACTION ☐ Doublers		☐ Blocked Drain				
☐ Others		☐ Wet Insulation Blanket				
		☐ Other				
21. If the defect is RII, Please Sign this card finally by RII Inspector				INSP		
NOTICE OF INSPECTOR				DATE		
22. PARTS REQUIRED						
PART DESCRIPTION	PART NO	QTY	SERIAL NO		STATUS	
			ON	OFF	CLOSE	OPEN
BRAKE DISC	164-22201	2 EA	-	-	☒	-
23. TOOLS REQUIRED						
DESCRIPTION	PART NO. / MODEL	NEXT CALIBRATION DATE		STATUS		
GENERAL TOOLS	NPM	B/C		Good		

	INSPECTION CARD (Form: SCA/MTC/048)	TECHNICAL DEPARTMENT
---	---	-------------------------

1. CARD #	2. JOWO #	3. ORIGINATOR	4. CARD REF	5. DATE
1C-002	W01031-SNU/X11/2023		0121021	10 JAN 2023
6. A/C REG/MSN	7. A/C TYPE	8. TRADE	12. VENDOR ORDER #	
PR-SNU	C2080EX	AIDFARM		
9. ZONE	10. STA	11. MTC TYPE		
LANDING GEAR	REPANCH	REPLACEMENT		

13. DESCRIPTION/DEFECT-IF FINDING OF CPCP INSPECTION, PLEASE COMPLETE SET. 20	14 PPC/ENG	15 DATE
BRAKE LINING LH SIDE AT BACK PLATE NEED TO BE REPLACE	 	10/01/2023

16. CORRECTIVE ACTION	17 MECH	18 ENG. LIC	19 DATE
REPLACED WITH NEW PARTS REFF ATOM C.A. 32-40-0 Performed at A/C TT: 3189: 26 A/C TC/LDG: 5285	done  		11/01/2023

20. CORROSION INFORMATION			
LOCATION	CAUSE OF DAMAGE		
	☐ Environment		
	☐ Internal Leakage		
CORROSION ☐ Isolated ☐ Widespread	☐ Chemical Spill		
CORROSION LVL ☐ 1 ☐ 2 ☐ 3	☐ LAV/Galley Spill		
PROPOSED ACTION ☐ Doublers	☐ Blocked Drain		
☐ Others	☐ Wet Insulation Blanket		
	☐ Other		
21. If the defect is RII, Please Sign this card finally by RII Inspector		INSP	DATE
NOTICE OF INSPECTOR			

22. PARTS REQUIRED						
PART DESCRIPTION	PART NO	QTY	SERIAL NO		STATUS	
			ON	OFF	CLOSE	OPEN
BRAKE LINING	066-15300	4ea	-	-	✓	-

23. TOOLS REQUIRED			
DESCRIPTION	PART NO. / MODEL	NEXT CALIBRATION DATE	STATUS
GENERAL TOOLS	REFM	O/C	Good

	INSPECTION CARD (Form: SCA/MTC/ 048)		TECHNICAL DEPARTMENT	

1. CARD #	2. JO/WO #	3. ORIGINATOR	4. CARD REF	5. DATE
1C-003	WO/031-SNV/XV/2023		0121001	11 JAN 2023
6. A/C REG/MSN	7. A/C TYPE	8. TRADE	12. VENDOR ORDER #	
PR-SNV		APPRAD		
9. ZONE	10. STA	11. MTC TYPE		
LANDING GEAR	REPAIR	REPLACEMENT		

13. DESCRIPTION/DEFECT-IF FINDING OF CPCP INSPECTION, PLEASE COMPLETE SET. 20	14	15
	PPC/ENG	DATE
FOUND LEAKING ON BRAKE PISTON NO #3 & #4		11/01/2023

16. CORRECTIVE ACTION	17	18	19
	MECH	ENG. LIC	DATE
REPLACED BRAKE PISTON ORING with NEW PART REFF ATAM CH. 32-40-00 Performed at A/C TT: 3189:26 A/C TC/LDG: 5285			11/01/2023

20. CORROSION INFORMATION			
LOCATION	CAUSE OF DAMAGE		
	☐ Environment ☐ Internal Leakage ☐ Chemical Spill ☐ LAV/Galley Spill ☐ Blocked Drain ☐ Wet Insulation Blanket ☐ Other		
CORROSION ☐ Isolated ☐ Widespread CORROSION LVL ☐ 1 ☐ 2 ☐ 3 PROPOSED ACTION ☐ Doublers ☐ Others			
21. If the defect is RII, Please Sign this card finally by RII Inspector			INSP
NOTICE OF INSPECTOR			DATE

22. PARTS REQUIRED						
PART DESCRIPTION	PART NO	QTY	SERIAL NO		STATUS	
			ON	OFF	CLOSE	OPEN
ORING	MS20795	2ea	-	-	✓	-
23. TOOLS REQUIRED						
DESCRIPTION	PART NO. / MODEL	NEXT CALIBRATION DATE	STATUS			
GENERAL TOOLS	APR	etc	Good			

		INSPECTION CARD (Form: SCA/MTC/ 048)		TECHNICAL DEPARTMENT	
---	--	--	--	-------------------------	--

1. CARD #	2. JO/WO #	3. ORIGINATOR	4. CARD REF	5. DATE	
IC-004	W01031-SNU/X11/2023		F742001	15 JAN 2021.	
6. A/C REG/MSN	7. A/C TYPE	8. TRADE	12. VENDOR ORDER #		
PIE-SNU	C708B EX	ENGINE			
9. ZONE	10. STA	11. MTC TYPE			
ENGINE	EOE	REPLACEMENT			

13. DESCRIPTION/DEFECT-IF FINDING OF CPCP INSPECTION, PLEASE COMPLETE SET. 20	14	15
	PPC/ENG	DATE
RH SIDE CABLE LEAD IGNITER NEED TO BE REPLACED	 tiger	15/01/2023

16. CORRECTIVE ACTION	17	18	19
	MECH	ENG. LIC	DATE
REPLACED WITH NEW CABLE LEAD REF FROM CH. 74-20 Performed at A/C TT : 3180 : 10 A/C TC /LDG : 5287 .	 aut	 tiger	15/01/2023

20. CORROSION INFORMATION			
LOCATION	CAUSE OF DAMAGE		
	☐ Environment ☐ Internal Leakage ☐ Chemical Spill ☐ LAV/Galley Spill ☐ Blocked Drain ☐ Wet Insulation Blanket ☐ Other		
CORROSION ☐ Isolated ☐ Widespread CORROSION LVL ☐ 1 ☐ 2 ☐ 3 PROPOSED ACTION ☐ Doublers ☐ Others			
21. If the defect is RII, Please Sign this card finally by RII Inspector		INSP	DATE
NOTICE OF INSPECTOR			

22. PARTS REQUIRED						
PART DESCRIPTION	PART NO	QTY	SERIAL NO		STATUS	
			ON	OFF	CLOSE	OPEN
CABLE LEAD.	CH 5399-02	1ea	-	-	☒	☐

23. TOOLS REQUIRED			
DESCRIPTION	PART NO. / MODEL	NEXT CALIBRATION DATE	STATUS
GENERAL TOOLS	NPM	O/C	Good



NON ROUTINE CARD
(Form: SCA/MTC/047)

1. JO/WO #	2. DATE	3. MTC TYPE	4. A/C REG/MSN
WO/031-SNV/XII/2022	10 JAN 2023	REPLACEMENT	PK-SNV/208B-5551
5. CARD #	6. ATA SPEC	7. TRADE	8. STA
#002	37		Repair 4
9. ZONE	10. PANEL		
CABIN.			

11. DESCRIPTION

PERFORM REPLACE VACUUM RELIEF VALVE FILTER DISCARD
PN: B3-5-1

REFERENCE	☒ AMM Ch. 37-10-00-961	☐ EMM Ch	☐ OTHER
RII (*)	☐ Y	☒ N	MHR :

12. RESULT		MECH	ENG	INSP (*)
REPLACED WITH NEW FILTER REF ATAM BH-37-10-00 Performed at A/C TT : 2189:26 A/C TC/LDG : 5285		duct 		
FINDING	☐ Y ☐ N	ACT MHR :	DATE/TIME (DD/MM/YY)	
INSPECTION CARD (IC) #		10	01	2023

13. PARTS REQUIRED

DESCRIPTION	PART NO	QTY	REMARK	
			STOCK	STATUS
FILTER	B3-5-1	1ea	✓	✓

14. TOOLS REQUIRED

DESCRIPTION	PART NO / MODEL	NEXT CALIBRATION DATE	STATUS
GENERAL TOOLS	H.P.M	O/C	Good



NON ROUTINE CARD
(Form: SCA/MTC/047)

1. JO/WO #	2. DATE	3. MTC TYPE	4. A/C REG/MSN
WO/031-SNV/XI/2022	10 JAN 2023	REPLACEMENT	PK-SNV/208B-5551
5. CARD #	6. ATA SPEC	7. TRADE	8. STA
#001	37		PCPMM
9. ZONE	10. PANEL		
CABIN			

11. DESCRIPTION			
PERFORM REPLACE VACUUM SYSTEM CENTRAL AIR FILTER DISCARD PN: AAD9-18-1			
REFERENCE	☒ AMM Ch. 37-10-00-960	☐ EMM Ch	☐ OTHER
RII (*)	☐ Y	☒ N	MHR :

12. RESULT		MECH	ENG	INSP (*)
REPAIRED WITH NEW FILTER. REF AMM CH. 37-10-00 Performed at A/C TT : 3189 : 26 A/C TC /LDG : 3185		act		
FINDING	☐ Y ☐ N	ACT MHR :		DATE/TIME (DD/MM/YY)
INSPECTION CARD (IC) #		10	01	2023

13. PARTS REQUIRED				
DESCRIPTION	PART NO	QTY	REMARK	
			STOCK	STATUS
FILTER	AAD9-18-1	1	✓	✓

14. TOOLS REQUIRED			
DESCRIPTION	PART NO / MODEL	NEXT CALIBRATION DATE	STATUS
GENERAL TOOL	NPN	O/C	Good.



NON ROUTINE CARD
(Form: SCA/MTC/047)

1. JO/WO #	2. DATE	3. MTC TYPE	4. A/C REG/MSN
WO/031-SNV/XII/2022	15 JAN 2023	LUBRICATION	PK-SNV/208B-5551
5. CARD #	6. ATA SPEC	7. TRADE	8. STA
#003	27		beperan
9. ZONE	10. PANEL		
TAIL SECTION			

11. DESCRIPTION

PERFORM ELEVATOR TRIM TAB ACTUATOR LUBRICATION

REFERENCE	☒ AMM Ch. 27-30-02	☐ EMM Ch	☐ OTHER
RII (*)	☒ Y	☐ N	MHR :

12. RESULT

PERFORMED ELEVATOR TRIM TAB ACTUATOR LUBRICATION
REF AMM CH. 27-30-02.

Performed at A/C TT : 3190:10 A/C TC /LDG : 5287.

FINDING	☐ Y	☐ N	ACT MHR :	MECH	ENG	INSP (*)
INSPECTION CARD (IC) #				15	01	2023

13. PARTS REQUIRED

DESCRIPTION	PART NO	QTY	REMARK	
			STOCK	STATUS
POLYKOTE MED LUM 33	-	1 EA.	✓	✓

14. TOOLS REQUIRED

DESCRIPTION	PART NO / MODEL	NEXT CALIBRATION DATE	STATUS
GENERIC TOOL	NPM	O/C	Good



MAINTENANCE PROGRAM CESSNA C208/C208B

Appendix B03 – PT6A-140 Engine Run Performance Sheet

Reg. Mark : PK - SNV

WO/FML No. : WO/031-SNV/Xil/2022

PRE – INSPECTION	
Location	KUPANG
Date	10 JAN 2023
Cycle	-
Filed Barometric	1007
OAT	36°C
Altitude	150 FT

POST – INSPECTION	
Location	KUPANG
Date	15 JAN 2023
Cycle	-
Filed Barometric	1008
OAT	30°C
Altitude	380 FT

PRE – INSPECTION		
	Target	Actual
Tq	2397	2397
Np	1800	1900
ITT	842 °C	838 °C
Ng	102.6 %	101.8 %
Wf	565	556
Oil Press		89 PSI
Oil Temp		73 °C
Start Temp		677 °C

POST – INSPECTION		
	Target	Actual
Tq	2397	2397
Np	1900	1900
ITT	841 °C	845 °C
Ng	102.7 %	101.9 %
Wf	578	544
Oil Press		88 PSI
Oil Temp		75 °C
Start Temp		723 °C

Engine Run Up Checks							
Inertial	☒	EPL	☒	OVG	☒	Stby Alt	☒
BOV	☒	Brake	☒	Randomn	☒		
NOTE: 1. Brake system at Torque 2000 ft-lbs. 3. EPL check can't exceed 4% Ng per second. 5. Low idle at 55.5 - 57% 40Amps. 2. Inertial Separator at Torque 400 ft-lbs. 4. Standby Alt at 80% Ng. 6. High idle at 64 - 66% Ng 40Amps							

Engine Performance Target Table (Cessna C208B EX)

OAT (°C)	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41
Tq (ft.lbs)	2397	2397	2397	2397	2397	2397	2397	2397	2397	2397	2397	2397	2397	2397	2397
Np	1900	1900	1900	1900	1900	1900	1900	1900	1900	1900	1900	1900	1900	1900	1900
ITT (°C)	835	837	839	841	841	841	841	841	841	842	843	844	846	846	846
Ng (%)	102.7	102.7	102.7	102.7	102.7	102.7	102.7	102.6	102.6	102.6	102.6	102.6	102.6	102.6	102.5
WF (PPH)	578	578	578	578	578	578	578	570	565	565	560	560	555	548	548

Note:

1. Make sure that inertial separator in normal condition, no bleed air extracted from the engine and air condition OFF.
2. This table only applies to altitude 0-500 feet MSL. For higher altitude, refer to EMM 72-00-00.
3. Max fuel flow is 580 lb/hr fuel flow is not more than 15 lbs/hr higher than the value shown in table.
4. If parameters are outside the target performance table to EMM chapter 71-00-00.

REMARKS:

Handwritten remarks: HUS-18 EVO-1

PERFORMED BY			
Name	Sign & Stamp	Date	Location
Deur Purnon		18/01/2023	KOE



DOCUMENT FORM BORESCOPE INSPECTION FORM

Page | - 1 -

Engine Borescope Inspection

Job No: WO/031-SNV/XII/2022

Engine Serial Number
PCE-VA0607Date
15 JAN 2023Base / Location
KOEAircraft Registration
PK-SNVAircraft Total Time
3190:10Aircraft Total Cycle
5287Reason For Borescope
1600 HOURS INSPECTION**Note:**

Record any discrepancies found during inspection, and/or take photographic evidence.

If None, then write No Findings. If you find defects, please quote EMM (Engine Maintenance Manual) Reference and Limitations.

Item	Work Description	SIGN	STAMP
1	Remove fuel manifold adapter as necessary (Ref. 73-10-04).		
2	Perform inspection of the First Stage Compressor. <u>Defects:</u> ERROSION ON THE LEADING EDGE, WITHIN LIMITATION <u>If defects found, quote MM Limitation and References :</u> PT6A-140, EMM 72-30-00, PARA 1 F (Acceptable Damage Limit)		

Photo of First Stage Compressor 1st QuadrantPhoto of First Stage Compressor 2nd Quadrant

Photo of First Stage Compressor 3rd Quadrant

Photo of First Stage Compressor 4th Quadrant


3

Perform inspection of Combustion Chamber Liner Assembly.

Defects:
FOUND SATISFACTORY, NO DEFECT
If defects found, quote MM Limitation and References :

SIGN

STAMP



Photo of Combustion Chamber 1st Quadrant

Photo of Combustion Chamber 2nd Quadrant


Photo of Combustion Chamber 3rd Quadrant

Photo of Combustion Chamber 4th Quadrant


4

Perform Inspection of CT-Stator assembly.

Defects:
FOUND BURNING OF COATING / PARENT MATERIAL ON THREE AREA SMALL EXIT DUCT
If defects found, quote MM Limitation and References :
PT6A-140, EMM 72-40-10, PARA 7D (Acceptable Damage Limit)

SIGN

STAMP




Photo of CT Stator 1st Quadrant

Photo of CT Stator 2nd Quadrant


Photo of CT Stator 3rd Quadrant

Photo of CT Stator 4th Quadrant


5

Perform inspection of CT blades and shroud segments.

Defects:
FOUND SATISFACTORY, NO DEFECT FOUND
If defects found, quote MM Limitation and References :

SIGN

STAMP



Photo of Leading Edge CT-Blades 1st Quadrant

Photo of Leading Edge CT-Blades 2nd


Photo of Leading Edge CT-Blades 3rd Quadrant

Photo of Leading Edge CT-Blades 4th Quadrant


6

Perform inspection trailing edge of CT blades.

Defects:
FOUND INTIAL COATING DETORATION (SULFIDATION)

If defects found, quote MM Limitation and References :

PT6A-140, EMM 72-50-02, PARA 3D (Acceptable Damage Limit)

SIGN

STAMP



Photo of Trailing Edge CT-Blades 1st Q

Photo of Trailing Edge CT-Blades 2nd Q


Photo of Trailing Edge CT-Blades 3rd Q

Photo of Trailing Edge CT-Blades 4th Q


7

Perform inspection of PT-Blades and PT-Vanes Ring

Defects:
FOUND SATISFACTORY, NO DEFECT FOUND
If defects found, quote MM Limitation and References :

SIGN

STAMP



Photo of PT-Blades/Vanes 1st Q

Photo of PT-Blades/Vanes 2nd Q




DOCUMENT FORM BORESCOPE INSPECTION FORM

Page | - 7 -

Photo of PT-Blades/Vanes 3rd Q



Photo of PT-Blades/Vanes 4th Q





		SIGN	STAMP
8	Install fuel manifold adapter(s) (Ref. 73-10-04).		
9	Perform fuel leak check post fuel nozzle installation		

BORESCOPE PERFORMED BY

Name: Rohpinindo N.S Purba



Signature



Additional Work Sheet
Insp.Doc.12-1600Hrs&Add.Insp.

Parts Used Sheet

[illegible]



Additional Work Sheet
Insp.Doc.12-1600 Hrs&Add.Task

Parts Used Sheet

[illegible]