



PT. SMART CAKRAWALA AVIATION

WORK ORDER

Form: SCA/MTC/030

Subject : Inspection 200Hrs A/F	No.	WO/059-SNV/X/2023
	Date	12 Oct 023
	A/C Reg.	PK-SNV C208B-5551
Reference : MP C208B Issued 01	Prepared By	TS
	Checked By	CI
	Approved By	TM

To : Engineer In Charge

Description :

1. Perform Inspection 200Hrs A/F
2. Make an entry in Maintenance Log.
3. Return the Completed Work Order and Form to PPC.

#If any finding, please close the routine card, and transferred to inspection card.

Additional Work :

Compliance Statement CARRIED OUT	Sign & Date 14-10-2023 Company Lic. No.: SCA 26  # 9657 (Engineer In Charge)	Signature  (Technical Manager)
---	---	--

AIRCRAFT CHECK WORK SUMMARY
(Form: SCA/MTC/051)

DATE OF ISSUED	JOWO #	TYPE OF MAINTENANCE	DATE OF ACCOMPLISHED		
12 Oct 2023	WO/059-SNV/X/2023	Inspection 200Hrs A/F,	14-10-2023		
A/C Type		Mfg. Serial Number	A/C Registration		
C208B		C208B-5551	PK-SNV		
AIRCRAFT DATA					
Subject	Pos #	Serial Number (SN)	TTSN/TCSN		
Engine	#1	PCE-VA0567	U199:10/6710		
	#2	-			
Propeller/Rotor	#1	181160	595:29		
	#2	-			
Landing Gear	NLG		4199:10/6710		
	LH MLG		4199:10/6710.		
	RH MLG		4199:10/6710.		
PACKAGE COVERED					
No	Subject	Qty	Remark		
1	Non-Routine Card	-			
2	Inspection Card	13	CLOSED		
3	Work Order	1			
4	Summary Inspection List	1			
5	Material and Tool List	-			
6	Escalation form	-			
7	CRS (SMI / Unscheduled Maintenance)	1			
INSPECTION CARD (IC) LIST (Finding during maintenance)					
No	Taskcard Ref	Subject	Status	Name/ Sign & Stamp	
			Open	Close	
IC-001	32-40-00	R/H MAIN WHEEL REPLACEMENT		✓	
IC-002	32-40-00	R/H MAIN WHEEL BEARING CONE REPLACEMENT		✓	
IC-003	32-40-00	L/H BRAKE LINING REPLACEMENT		✓	
IC-004					
IC-005					
IC-006					

IC-007

IC-008

IC-009

IC-010

IC-011

IC-012

IC-013

IC-014

IC-015

Prepared by :
Technical Support



.....
Hani

Checked by :
Chief Maintenance



.....
Dodit

Verified by :
Chief Inspector



.....
Yanuar

Approved by :
Technical Manager



.....
Istiono

		INSPECTION CARD (Form: SCA/MTC/ 048)			TECHNICAL DEPARTMENT	
---	--	--	--	--	-------------------------	--

1. CARD #	2. JO/WO #	3. ORIGINATOR	4. CARD REF	5. DATE	
001	W01059-SNV/X/2023			14-10-2023	
6. A/C REG/MSN	7. A/C TYPE	8. TRADE	12. VENDOR ORDER #		
PK-SNV	C208B				
9. ZONE	10. STA	11. MTC TYPE			
	NBX				

13. DESCRIPTION/DEFECT-IF FINDING OF CPCP INSPECTION, PLEASE COMPLETE SET. 20	14	15
	PPC/ENG	DATE
R/H MAIN WHEEL TIRE FOUND WORN OUT OF LIMIT.		14/10-2023

16. CORRECTIVE ACTION	17	18	19
	MECH	ENG. LIC	DATE
REPLACED R/H MAIN WHEEL ASSY WITH NEW TIRE AND BRAKE DISC. IAW C208B AMM CH 32-40-00 Performed at A/C TT : 4199:10 A/C TC/LDG : 6710			14/10-2023

20. CORROSION INFORMATION			
LOCATION	CAUSE OF DAMAGE		
	☐ Environment		
	☐ Internal Leakage		
CORROSION ☐ Isolated ☐ Widespread	☐ Chemical Spill		
CORROSION LVL ☐ 1 ☐ 2 ☐ 3	☐ LAV/Galley Spill		
PROPOSED ACTION ☐ Doublers	☐ Blocked Drain		
☐ Others	☐ Wet Insulation Blanket		
	☐ Other		
21. If the defect is RII, Please Sign this card finally by RII Inspector		INSP	DATE
NOTICE OF INSPECTOR			

22. PARTS REQUIRED						
PART DESCRIPTION	PART NO	QTY	SERIAL NO		STATUS	
			ON	OFF	CLOSE	OPEN
MAIN WHEEL ASSY	110T01-3	1 ASSY	31390471	90792627	✓	

23. TOOLS REQUIRED			
DESCRIPTION	PART NO. / MODEL	NEXT CALIBRATION DATE	STATUS
TORQUE WRENCH	TA-0250	NOV-2023	SERVICEABLE

	INSPECTION CARD (Form: SCA/MTC/ 048)	TECHNICAL DEPARTMENT
--	--	---------------------------------

1. CARD# 002	2. JOWO# W4/059-SNV/X/2023	3. ORIGINATOR	4. CARD REF	5. DATE 14-10-2023
6. A/C REG/MSN PK-SNV	7. A/C TYPE C208B	8. TRADE	12. VENDOR ORDER #	
9. ZONE	10. STA NB X	11. MTC TYPE		

13. DESCRIPTION/DEFECT-IF FINDING OF CPCP INSPECTION, PLEASE COMPLETE SET. 20	14 PPC/ENG	15 DATE
R/H MAIN WHEEL BEARING CONE FOUND WORN		14/10-2023

16. CORRECTIVE ACTION	17 MECH	18 ENG. LIC	19 DATE
REPLACED R/H MAIN WHEEL BEARING CONE WITH NEW. IAW C208B AMM CH 32-40-00 Performed at A/C TT : 4199:10 A/C TC /LDG : 6710			14/10-2023

20. CORROSION INFORMATION					
LOCATION	CAUSE OF DAMAGE				
	☐ Environment				
	☐ Internal Leakage				
CORROSION ☐ Isolated ☐ Widespread	☐ Chemical Spill				
CORROSION LVL ☐ 1 ☐ 2 ☐ 3	☐ LAV/Galley Spill				
PROPOSED ACTION ☐ Doublers	☐ Blocked Drain				
☐ Others	☐ Wet Insulation Blanket				
	☐ Other				
21. If the defect is RII, Please Sign this card finally by RII Inspector				INSP	DATE
NOTICE OF INSPECTOR					

22. PARTS REQUIRED						
PART DESCRIPTION	PART NO	QTY	SERIAL NO		STATUS	
			ON	OFF	CLOSE	OPEN
BEARING CONE	214-61300	2EA	NSW	NSW	☒	
23. TOOLS REQUIRED						
DESCRIPTION	PART NO. / MODEL	NEXT CALIBRATION DATE		STATUS		



INSPECTION CARD

(Form: SCA/MTC/ 048)

TECHNICAL
DEPARTMENT

1. CARD# 003	2. JOWO# W0/059-SNV/X/2023	3. ORIGINATOR	4. CARD REF	5. DATE 14-10-2023
6. A/C REG/MSN PK-SNV	7. A/C TYPE C208B	8. TRADE	12. VENDOR ORDER#	
9. ZONE	10. STA NBX	11. MTC TYPE		

13. DESCRIPTION/DEFECT-IF FINDING OF CPCP INSPECTION, PLEASE COMPLETE SET. 20 1/4 BRAKE PLATE AND PRESSURE PLATE LINING FOUND WORN OUT OF LIMIT	14 PPC/ENG	15 DATE
		14/10-2023

16. CORRECTIVE ACTION REPLACED 8 EA BRAKE LINING ANNA CH. 32-90-00 Performed at A/C TT : 4199:10 A/C TC/LDG : 6716	17 MECH	18 ENG. LIC	19 DATE
			14/10-2023

20. CORROSION INFORMATION			
LOCATION	CAUSE OF DAMAGE		
	☐ Environment		
	☐ Internal Leakage		
	☐ Chemical Spill		
CORROSION ☐ Isolated ☐ Widespread	☐ LAV/Galley Spill		
CORROSION LVL ☐ 1 ☐ 2 ☐ 3	☐ Blocked Drain		
PROPOSED ACTION ☐ Doublers	☐ Wet Insulation Blanket		
☐ Others	☐ Other		
21. If the defect is RII, Please Sign this card finally by RII Inspector		INSP	DATE
NOTICE OF INSPECTOR			

22. PARTS REQUIRED						
PART DESCRIPTION	PART NO	QTY	SERIAL NO		STATUS	
			ON	OFF	CLOSE	OPEN
BRAKE LINING	066-03300	8EA	NSN	NSN	✓	

23. TOOLS REQUIRED			
DESCRIPTION	PART NO. / MODEL	NEXT CALIBRATION DATE	STATUS
TORQUE WRENCH	TA-0280	NOV-2023	SERVICEABLE



PT. SMART CAKRAWALA AVIATION

CERTIFICATE RETURN TO SERVICE

SCHEDULED MAINTENANCE INSPECTION

(CRS-SMI)

A/C TYPE	: CESSNA 208B	TTSN	: 4199:10
A/C REG	: PK-SNV	TCSN	: 6710
MSN	: C208B-5551	DATE	: 19-10-2023

TYPE OF INSPECTION : INSPECTION 200HRS A/F
 DUE AT : 4000 HOURS
 REFF : MP 208/208B ISSUED 01

EXCEPTION

- ENGINE GROUND RUN INCLUDE ENGINE REPLACEMENT WORK ORDER
 - EMERGENCY EQUIPMENT LIST INCLUDE ENGINE REPLACEMENT WORK ORDER
- W00/058-SNV/X/2023

AUTHORIZED PERSON

I hereby certify that this aircraft has been maintained accordance with CASR and Maintenance Program.
 Aircraft safe and airworthy for flight

NAME	CAT	AMEL/OTR NO	SIGN&STAMP	DATE
DENIAR F.P. SONTANI	AIRFRAME & POWER PLANT	9657/SCA 26		19/10-2023
	EIRA			

THE NEXT DUE TYPE OF INSPECTION : 100 HRS INSP

DUE AT : 4 300 : 00

Form: SCA/MTC/049



SUMMARY INSPECTION ITEMS (Form: SCA/MTC/050)

WO Ref: WO/059-SNV/X/2023


NO.	TASK CARD NO.	DESCRIPTION	DATE	EST MHR	NAME	STAMP
1	APPENDIX D08	PT6A-140 ENGINE GROUND RUN	N/A DUE TO ENGINE REPLACEMENT		DENIAR	
2	APPENDIX C03	200 HRS/12 MTHS INSPECTION	14/10-2023		DENIAR	
3	SCA/MTC/023	EMERGENCY EQUIPMENT LIST	INCLUDE ENGINE REPLACEMENT WO		DENIAR	



Special Tool Used _____
Sheet

WO# Nf: WO/059-SNV/X/2023
PART USED
~~Special Tool Used~~

[illegible]



Parts Used Sheet

WO# Nr.: WO/059-SNV/X/2023
Part Used **SPECIAL TOOLS**

[illegible]