



PT. SMART CAKRAWALA AVIATION

WORK ORDER

Form: SCA/MTC/030

Subject : Perform Cargo Pod Removal.	No.	WO/061A-SNS/VIII/2023
	Date	12 Aug 2023
	A/C Reg.	PK-SNS C208B-2341
Reference : MP C208B Issued 01	Prepared By	TS
	Checked By	CI
	Approved By	TM
To : Engineer In Charge		

Description :

1. Perform Cargo Pod Removal
2. Make an entry in Maintenance Log.
3. Return the Completed Work Order and Form to PPC.

#If any finding, please close the routine card, and transferred to inspection card.

Additional Work :

- NIL -

Compliance Statement <i>CARRIED OUT</i>	Sign & Date Company Lic. No.: <i>DENI SABATI</i> (Engineer In Charge)	Signature <i>[Signature]</i> (Technical Manager)
---	--	--

Appendix B - Form: SCA/MTC/030

AIRCRAFT CHECK WORK SUMMARY
(Form: SCA/MTC/051)


DATE OF ISSUED	JO/WO #	TYPE OF MAINTENANCE	DATE OF ACCOMPLISHED	
12 Aug 2023	WO/061A-SNS/VIII/2023	CARGO POD REMOVAL	12 AUGUST 2023	
A/C Type		Mfg. Serial Number	A/C Registration	
C208B		C208B-2341	PK-SNS	
AIRCRAFT DATA				
Subject	Pos #	Serial Number (SN)	TTSN/TCSN	
Engine	#1	PCE-PC306	550:32/734	
	#2	-		
Propeller/Rotor	#1	081043	1125:12	
	#2	-		
Landing Gear	NLG		7078:58/8117	
	LH MLG		7078:58/8117	
	RH MLG		7078:58/8117	
PACKAGE COVERED				
No	Subject	Qty	Remark	
1	Non-Routine Card	1		
2	Inspection Card	1		
3	Work Order	1		
4	Summary Inspection List	1		
5	Material and Tool List	-		
6	Escalation form	-		
7	CRS (SMI / Unscheduled Maintenance)	-		
INSPECTION CARD (IC) LIST (Finding during maintenance)				
No	Taskcard Ref	Subject	Status	Name/ Sign & Stamp
			Open	Close
IC-001				
IC-002				
IC-003				

Prepared by :
Technical Support


Checked by :
Chief Maintenance


Verified by :
Chief Inspector

Approved by :
Technical Manager


.....


.....


.....


.....



SUMMARY INSPECTION ITEMS
(Form: SCA/MTC/050)

WO Ref: WO/061A-SNS/VIII/2023

NO.	TASK CARD NO.	DESCRIPTION	DATE	EST MHR	NAME	STAMP
1	25-52-00	CARGO POD REMOVAL	12/ 08-23		DENI SOBALI	

		INSPECTION CARD (Form: SCA/MTC/ 048)			TECHNICAL DEPARTMENT	
---	--	--	--	--	-------------------------	--

1. CARD #	2. JO/WO #	3. ORIGINATOR	4. CARD REF	5. DATE	
6. A/C REG/MSN	7. A/C TYPE	8. TRADE	12. VENDOR ORDER #		
9. ZONE	10. STA	11. MTC TYPE			

13. DESCRIPTION/DEFECT-IF FINDING OF CPCP INSPECTION, PLEASE COMPLETE SET. 20	14 PPC/ENG	15 DATE

16. CORRECTIVE ACTION	17 MECH	18 ENG. LIC	19 DATE
Performed at A/C TT : A/C TC /LDG :			

20. CORROSION INFORMATION					
LOCATION	CAUSE OF DAMAGE				
	☐ Environment				
	☐ Internal Leakage				
CORROSION ☐ Isolated ☐ Widespread	☐ Chemical Spill				
CORROSION LVL ☐ 1 ☐ 2 ☐ 3	☐ LAV/Galley Spill				
PROPOSED ACTION ☐ Doublers	☐ Blocked Drain				
☐ Others	☐ Wet Insulation Blanket				
	☐ Other				
21. If the defect is RII, Please Sign this card finally by RII Inspector				INSP	DATE
NOTICE OF INSPECTOR					

22. PARTS REQUIRED						
PART DESCRIPTION	PART NO	QTY	SERIAL NO		STATUS	
			ON	OFF	CLOSE	OPEN

23. TOOLS REQUIRED			
DESCRIPTION	PART NO. / MODEL	NEXT CALIBRATION DATE	STATUS



NON ROUTINE CARD
(Form: SCA/MTC/047)

1. JO/WO #	2. DATE	3. MTC TYPE	4. A/C REG/MSN
WO/061A-SNS/VIII/2023	12-08-2023	REMOVAL	PK-SNS
5. CARD #	6. ATA SPEC	7. TRADE	8. STA
001	25	AIRFRAME	NABIRE
9. ZONE	10. PANEL	-	
CARGO POD			

11. DESCRIPTION

PERFORM CARGO POD REMOVAL

REFERENCE	☒ AMM Ch. 25-52-00	☐	☐ OTHER
RII (*)	☐ Y	☒ N	MHR :

12. RESULT		MECH	ENG	INSP (*)
PERFORMED CARGO POD REMOVAL REF TO : CHAPTER 25-52-00 Performed at A/C TT : 7078:58 A/C TC /LDG : 8117		PETER AGAPA		
FINDING	☐ Y ☒ N	ACT MHR :		DATE/TIME (DD/MM/YY)
INSPECTION CARD (IC) #		12	08	2023

13. PARTS REQUIRED

DESCRIPTION	PART NO	QTY	REMARK	
			STOCK	STATUS

14. TOOLS REQUIRED

DESCRIPTION	PART NO / MODEL	NEXT CALIBRATION DATE	STATUS
GENERAL TOOL	-	-	GOOD