



PT. SMART CAKRAWALA AVIATION

WORK ORDER

Form: SCA/MTC/030

Subject : Perform Cargo Pod Installation	No.	WO/061B-SNS/VIII/2023
	Date	23 Aug 2023
	A/C Reg.	PK-SNS C208B-2341
Reference : MP C208B Issued 01	Prepared By	TS
	Checked By	CI
	Approved By	TM

To : Engineer In Charge

Description :

1. Perform Cargo Pod Installation
2. Make an entry in Maintenance Log.
3. Return the Completed Work Order and Form to PPC.

#If any finding, please close the routine card, and transferred to inspection card.

Additional Work :

- XIC -

Compliance
Statement
CARRIED OUT

Sign & Date

Company Lic. No.: 8640
23/AUG/2023


(Engineer In Charge)

Signature


(Technical Manager)

AIRCRAFT CHECK WORK SUMMARY
(Form: SCA/MTC/051)

DATE OF ISSUED	JO/WO #	TYPE OF MAINTENANCE	DATE OF ACCOMPLISHED
23 Aug 2023	WO/061B-SNS/VIII/2023	CARGO POD INSTALLATION	23 Aug. 2023

A/C Type	Mfg. Serial Number	A/C Registration
C208B	C208B-2341	PK-SNS

AIRCRAFT DATA

Subject	Pos #	Serial Number (SN)	TTSN/TCSN
Engine	#1	PCE-PC306	612:09 / 760
	#2	-	
Propeller/Rotor	#1	081043	1151:59 /
	#2	-	
Landing Gear	NLG		7141:25 / 8145
	LH MLG		7141:25 / 8145
	RH MLG		7141:25 / 8145

PACKAGE COVERED

No	Subject	Qty	Remark
1	Non-Routine Card	1	
2	Inspection Card	1	
3	Work Order	1	
4	Summary Inspection List	1	
5	Material and Tool List		
6	Escalation form	-	
7	CRS (SMI / Unscheduled Maintenance)	-	

INSPECTION CARD (IC) LIST (Finding during maintenance)

No	Taskcard Ref	Subject	Status		Name/ Sign & Stamp
			Open	Close	
<u>IC-001</u>					
<u>IC-002</u>					
<u>IC-003</u>					

Prepared by :
Technical Support

Checked by :
Chief Maintenance

Verified by :
Chief Inspector

Approved by :
Technical Manager








SUMMARY INSPECTION ITEMS
(Form: SCA/MTC/050)

WO Ref: WO/061B-SNS/VIII/2023

NO.	TASK CARD NO.	DESCRIPTION	DATE	EST MHR	NAME	STAMP
1	25-52-00	CARGO POD INSTALLATION	23/ 08.2023		Amin m. SMD	

		INSPECTION CARD (Form: SCA/MTC/ 048)			TECHNICAL DEPARTMENT	
--	--	--	--	--	-------------------------	--

1. CARD#	2. JOWO#	3. ORIGINATOR	4. CARD REF	5. DATE	
		AMIN		23 AUG. 2023	
6. A/C REG/MSN	7. A/C TYPE	8. TRADE	12. VENDOR ORDER#		
PK-SNS	C208B				
9. ZONE	10. STA	11. MTC TYPE			
CARGO POD	NABRE				

13. DESCRIPTION/DEFECT-IF FINDING OF CPCP INSPECTION, PLEASE COMPLETE SET. 20	14	15
	PPC/ENG	DATE
CARGO POD INSTALLATION		23 / 23 08

16. CORRECTIVE ACTION	17	18	19
	MECH	ENG. LIC	DATE
PERFORMED CARGO POD INSTALLATION, CHECK GOOD REF AMM: 25-52-00 Performed at A/C TT : 7191:25..... A/C TC /LDG : 0195.....	Aug		23 / 23 08

20. CORROSION INFORMATION			
LOCATION	CAUSE OF DAMAGE		
	☐ Environment		
	☐ Internal Leakage		
CORROSION ☐ Isolated ☐ Widespread	☐ Chemical Spill		
CORROSION LVL ☐ 1 ☐ 2 ☐ 3	☐ LAV/Galley Spill		
PROPOSED ACTION ☐ Doublers	☐ Blocked Drain		
☐ Others	☐ Wet Insulation Blanket		
	☐ Other		

21. If the defect is RII, Please Sign this card finally by RII Inspector	INSP	DATE
NOTICE OF INSPECTOR		

22. PARTS REQUIRED						
PART DESCRIPTION	PART NO	QTY	SERIAL NO		STATUS	
			ON	OFF	CLOSE	OPEN

23. TOOLS REQUIRED			
DESCRIPTION	PART NO. / MODEL	NEXT CALIBRATION DATE	STATUS
GENERAL TOOLS	NPV	0%	Good



NON ROUTINE CARD (Form: SCA/MTC/047)

1. JO/WO #	2. DATE	3. MTC TYPE	4. A/C REG/MSN
WO/061-B/SNS/VIII/2023		INSTALLATION	PK-SNS
5. CARD #	6. ATA SPEC	7. TRADE	8. STA
001	25		NABIRE
9. ZONE	10. PANEL	-	
CARGO POD			

11. DESCRIPTION			
PERFORM CARGO POD INSTALLATION			
REFERENCE	☒ AMM Ch. 25-52-00	☐	☐ OTHER
RII (*)	☐ Y	☒ N	MHR :

12. RESULT		MECH	ENG	INSP (*)
		<i>Ans</i>	<i>Ans</i>	
Performed at A/C TT : <i>F141</i> : <i>25</i> A/C TC /LDG : <i>8145</i>				
FINDING	☐ Y	☐ N	ACT MHR :	DATE/TIME (DD/MM/YY)
INSPECTION CARD (IC) #			<i>23</i>	<i>Aug 2023</i>

13. PARTS REQUIRED				
DESCRIPTION	PART NO	QTY	REMARK	
			STOCK	STATUS

14. TOOLS REQUIRED			
DESCRIPTION	PART NO / MODEL	NEXT CALIBRATION DATE	STATUS
GENERAL TOOL'S	NPN	%c	Good