



PT. SMART CAKRAWALA AVIATION

WORK ORDER

Form: SCA/MTC/030

Subject : Inspection Document 06, 07, 08 & Add. Task due at 2800 Hours.	No.	WO/068-SNV/V/2022
	Date	21 May 2022
	A/C Reg.	PK-SNV C208B-5551
Reference : MP C208B REV. 10	Prepared By	TS
	Checked By	CI
	Approved By	TM
To : Engineer In Charge		
Description : 1. Perform Inspection Document 06, 07, 08 & Add Task due at 2800 Hours. 2. Make an entry in Maintenance Log. 3. Return the Completed Work Order and Form to PPC. #If any finding, please close the routine card, and transferred to inspection card.		
Additional Work :		
Compliance Statement	Sign & Date 22 MAY 2022 Company Lic. No.: SCA 34  (Engineer In Charge)	Signature  (Technical Manager)

Appendix B - Form: SCA/MTC/030

AIRCRAFT CHECK WORK SUMMARY
(Form: SCA/MTC/051)

DATE OF ISSUED	JO/WO #	TYPE OF MAINTENANCE	DATE OF ACCOMPLISHED	
21 May 2022	WO/068-SNV/V/2022	Insp. Doc.06,07,08 Add Task	03 JUN 2022	
A/C Type	Mfg. Serial Number	A/C Registration		
C208B	C208B-5551	PK-SNV		
AIRCRAFT DATA				
Subject	Pos #	Serial Number (SN)	TTSN/TCSN	
Engine	#1	PCE-VA0723	2805:10 / 4934	
	#2	-		
Propeller/Rotor	#1	1801158	2805:10 / 4934	
	#2	-		
Landing Gear	NLG		2805:10 / 4934	
	LH MLG		2805:10 / 4934	
	RH MLG		2805:10 / 4934	
PACKAGE COVERED				
No	Subject	Qty	Remark	
1	Non-Routine Card	2	#001 #002	
2	Inspection Card	1		
3	Work Order	1		
4	Summary Inspection List	1		
5	Material and Tool List	-		
6	Escalation form	-		
7	CRS (SMI / Unscheduled Maintenance)	1		
INSPECTION CARD (IC) LIST (Finding during maintenance)				
No	Taskcard Ref	Subject	Status Open Close	Name/ Sign & Stamp
<u>IC-001</u>	F731004	FUEL NOZZLE CLEANING		✓ VANI ANANTA
<u>IC-002</u>				
<u>IC-003</u>				
<u>IC-004</u>				
<u>IC-005</u>				
<u>IC-006</u>				

<u>IC-007</u>				
<u>IC-008</u>				
<u>IC-009</u>				
<u>IC-010</u>				
<u>IC-011</u>				
<u>IC-012</u>				
<u>IC-013</u>				
<u>IC-014</u>				
<u>IC-015</u>				

Prepared by :
Technical Support



Checked by :
Chief Maintenance



Verified by :
Chief Inspector



Approved by :
Technical Manager



		INSPECTION CARD (Form: SCA/MTC/ 048)		TECHNICAL DEPARTMENT	
---	--	--	--	-------------------------	--

1. CARD #	2. JO/WO #	3. ORIGINATOR	4. CARD REF	5. DATE	
IC-001	WO/068-SNV/V/2022	-	F731004		
6. A/C REG/MSN	7. A/C TYPE	8. TRADE	12. VENDOR ORDER #		
PK-SNV/5551	C208B EX	ENGINE			
9. ZONE	10. STA	11. MTC TYPE			
130	PK-U	REPLACEMENT			

13. DESCRIPTION/DEFECT-IF FINDING OF CPCP INSPECTION, PLEASE COMPLETE SET. 20	14	15
	PPC/ENG	DATE
FUEL NOZZLE CLEANING DUE		03 / 2022 / JUN

16. CORRECTIVE ACTION	17	18	19
	MECH	ENG. LIC	DATE
REPLACED FUEL NOZZLE SET WITH SERVICEABLE ONE, OPE CHECK FOUND SATISFACTORY IAW ENGINE MAINTENANCE MANUAL CHAP 73.10.09 Performed at A/C TT : 2805:10 A/C TC /LDG : 4934			03 / 2022 / JUN

20. CORROSION INFORMATION			
LOCATION	CAUSE OF DAMAGE		
	☐ Environment		
	☐ Internal Leakage		
CORROSION ☐ Isolated ☐ Widespread	☐ Chemical Spill		
CORROSION LVL ☐ 1 ☐ 2 ☐ 3	☐ LAV/Galley Spill		
PROPOSED ACTION ☐ Doublers	☐ Blocked Drain		
☐ Others	☐ Wet Insulation Blanket		
	☐ Other		

21. If the defect is RII, Please Sign this card finally by RII Inspector	INSP	DATE
NOTICE OF INSPECTOR		

22. PARTS REQUIRED						
PART DESCRIPTION	PART NO	QTY	SERIAL NO		STATUS	
			ON	OFF	CLOSE	OPEN
FUEL NOZZLE SET	3077780-01A	14	3116836A		✓	

23. TOOLS REQUIRED			
DESCRIPTION	PART NO. / MODEL	NEXT CALIBRATION DATE	STATUS
TORQUE WRENCH			
GENERAL TOOL			

SUMMARY INSPECTION ITEMS (Form: SCA/MTC/050)

WO Ref: WO/068-SNV/V/2022

NO.	TASK CARD NO.	DESCRIPTION	DATE	EST MHR	NAME	STAMP
1	B03	PT6A-140 ENGINE GROUND RUN PERFORMANCE	01 / JUNE 2022		YOHAN S	
2	CHAPTER 12	INSPECTION DOCUMENT 06	02 / JUNE 2022		YOHAN S	
3	CHAPTER 13	INSPECTION DOCUMENT 07	02 / JUNE 2022		YOHAN S	
4	CHAPTER 14	INSPECTION DOCUMENT 08	03 / 2022 JUN		VANI ANANTA	
5	CHAPTER 51	ENGINE PT6A-140 100 HOUR INSPECTION/ MINOR INSPECTION	03 / JUNE 2022		YOHAN S	
6	CHAPTER 52	ENGINE PT6A-140 200 HOUR INSPECTION	03 / JUNE 2022		YOHAN S	
7	CHAPTER 53	ENGINE PT6A-140 200 HOUR / 6 MONTHS INSPECTION	03 / JUNE 2022		YOHAN S	
8	CHAPTER 54	ENGINE PT6A-140 400 HOUR INSPECTION	03 / 2022 JUN		VANI ANANTA	
9	SCA/MTC/023	EMERGENCY EQUIPMENT CHECK	02 / JUNE 2022		YOHAN S	
10	37-10-00-960	VACUUM SYSTEM CENTRAL AIR FILTER REPLACEMENT (AAD9-18-1)	01 / JUNE 2022		YOHAN S	
11	37-10-00-961	VACUUM RELIEF VALVE FILTER REPLACEMENT (B3-5-1)	01 / JUNE 2022		YOHAN S	
12		BORESCOPE INSPECTION	03 / 2022 JUN		VANI ANANTA	



PT. SMART CAKRAWALA AVIATION

CERTIFICATE RETURN TO SERVICE

SCHEDULED MAINTENANCE INSPECTION (CRS-SMI)

A/C TYPE : CESSNA C208B	TTSN : 2805:10
A/C REG : PK-SNV	TCSN : 4934
MSN : C208B-5551	DATE : 03 JUN 2022

TYPE OF INSPECTION : INSPECTION DOCUMENT 06, 07, 08 & ADD TASK
 DUE AT : 2800 HOURS
 REFF : MP C208B REV. 10

EXCEPTION

NO EXCEPTION

AUTHORIZED PERSON

I hereby certify that this aircraft has been maintained accordance with CASR and Maintenance Program.
 Aircraft safe and airworthy for flight

NAME	CAT	AMEL/OTR NO	SIGN&STAMP	DATE
VAPI ANANTA	AIRFRAME & POWER PLANT	9655 / SCA 30	 	03 / 2022 JUN
	EIRA			

THE NEXT DUE TYPE OF INSPECTION : 100 HOURS

DUE AT : 2900:00

Form: SCA/MTC/049

Reg. Mark : PK - SNV

WO/FML No. : WO/068-SNV/V/2022

PRE – INSPECTION	
Location	
Date	
Cycle	
Filed Barometric	
OAT	
Altitude	

POST – INSPECTION	
Location	PEKANBARU
Date	03 - JUNE - 2022
Cycle	
Filed Barometric	
OAT	35°
Altitude	

PRE – INSPECTION		
	Target	Actual
Tq		
Np		
ITT	°C	°C
Ng	%	%
Wf		
Oil Press		°C
Oil Temp		°C
Start Temp		°C

POST- INSPECTION		
	Target	Actual
Tq	2397	2397
Np	1900	1880 70
ITT	841 °C	840 °C
Ng	102.6 %	101.5 %
Wf	565	548
Oil Press		87 °C
Oil Temp		82 °C
Start Temp		637 °C

Engine Run Up Checks							
Inertial	☒	EPL	☒	OVG	☒	Stby Alt	☒
BOV	☐	Brake	☒	Randomn	☒		
NOTE:							
1. Brake system at Torque 2000 ft.-lbs.		3. EPL check can't exceed 4% Ng per second.		5. Low idle at 55.5 - 57% 40Amps.		6. High idle at 64 - 66% Ng 40Amps	
2. Inertial Separator at Torque 400 ft.-lbs.		4. Standby Alt at 80% Ng.					

Engine Performance Target Table (Cessna C208B EX)

OAT (°C)	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41
Tq (ft.lbs)	2397	2397	2397	2397	2397	2397	2397	2397	2397	2397	2397	2397	2397	2397	2397
Np	1900	1900	1900	1900	1900	1900	1900	1900	1900	1900	1900	1900	1900	1900	1900
ITT (°C)	835	837	839	841	841	841	841	841	841	842	843	844	846	846	846
Ng (%)	102.7	102.7	102.7	102.7	102.7	102.7	102.7	102.6	102.6	102.6	102.6	102.6	102.6	102.6	102.5
WF (PPH)	578	578	578	578	578	578	578	570	565	565	560	560	555	548	548

Note:

1. Make sure that inertial separator in normal condition, no bleed air extracted from the engine and air condition OFF.
2. This table only applies to altitude 0-500 feet MSL. For higher altitude, refer to EMM 72-00-00.
3. Max fuel flow is 580 lb/hr fuel flow is not more than 15 lbs/hr higher than the value shown in table.
4. If parameters are outside the target performance table to EMM chapter 71-00-00.

REMARKS:







PERFORMED BY			
Name	Sign & Stamp	Date	Location
YONAN S DEPARI		03 / JUNE 2022	PEKANBARU

MAINTENANCE PROGRAM CESSNA C208/C208B

Chapter 12 – Inspection Document 06



Reg. Mark : PK - SNV
MSN : C208B-5551
TSN / CSN : 2805:10 / 4934

Date : 01 JUNE - 2022
Station : PERANBARU
WO No. : WO/068-SNV/V/2022:

ITEM CODE NO.	ZONE	TASK	SIGNATURE	
			SIGN	STAMP
A110001	ALL	Interior and Exterior Placard and Decal Detailed Inspection Task 11-00-00-220		
D121001	121	Brake System Servicing Task 12-10-01-610		
D121003	710	Shimmy Damper Servicing Task 12-10-01-611		
C122101	700	Landing Gear Lubrication Task 12-21-03-640		
B236001	343 375 376 571 671	Static Discharge System Functional Check Task 23-60-00-720		
A255101	251 252 255 256 257 258	Cargo Nets Detailed Inspection Task 25-51-00-220		
C270001	215 216 226 373 374 503 525 603 625	Flight Controls Lubrication Task 27-00-00-640		
B273101	211 212 503	Stall Warning System Operational Check Task 27-31-00-710		
C275001	525 527 625 627	Flap Tracks and Rollers Lubrication Task 27-50-00-640		
B281001	575 675	Fuel Vent Line Float Valve Operational Check Task 28-10-03-710		
A281001	521 621	Fuel Filler Assembly Detailed Inspection Task 28-10-01-220		
B301003	122 AUX	Bleed Air Pressure Regulator Functional Check (without TKS and not incorporating CAB93-2) Task 30-10-00-720		
B322001	710	Shimmy Damper Functional Check Task 32-20-02-720		

MAINTENANCE PROGRAM CESSNA C208/C208B

Chapter 12 – Inspection Document 06


ITEM CODE NO.	ZONE	TASK	SIGNATURE	
			SIGN	STAMP
B341101	AUX	Pitot Tube Heaters Operational Check Task 34-11-00-710		
A353001	256	Oxygen Mask Detailed Inspection Task 35-30-00-220		
B761003	AUX	Emergency Power Lever Annunciator Light (EPL) Operational Check Task 76-10-01-710		
*** End of Inspection Document 06 Items ***				

PERSONNEL PARTICIPATING IN THIS INSPECTION			
NAME	POSITION	SIGNATURE	LICENSE NUMBER
YOHAN. S. DEPARI	ENGINEER		12128
VANI ANANTA	ENGINEER		9653

RETURN TO SERVICE

The work recorded above has been carried out in accordance with the requirements of the Civil Aviation Safety Regulation for the time being in force and in that respect the aircraft is consider fit for Release to Service.

Name : YOHAN. SEMBIRING. DEPARI Stamp : 

Signature :  Place/Date : PEKANBARU / 03. JUNE-2022



MAINTENANCE PROGRAM CESSNA C208/C208B

Chapter 13 – Inspection Document 07

Reg. Mark	: PK - SNV	Date	: 02 - JUNE - 2022
MSN	: C208B-5551	Station	: PEKANBARU
TSN / CSN	: 2805 : 10 / 4934	WO No.	: WO/068-SNV/V/2022

ITEM CODE NO.	ZONE	TASK	SIGNATURE	
			SIGN	STAMP
A243601	121	Standby Alternator Detailed Inspection Task 24-36-00-220		
B251001	221 232	Inertia Reel Operational Check Task 25-10-00-710		
B255201	901 902 903 904 905 906	Cargo Pod Drains Operational Check Task 25-52-00-710		
A261001	121 122	Engine Fire Detection System General Visual Inspection Task 26-10-00-210		
C271001	211 212 217 218 233 234 253 254 251 252 551 571 651 671	Aileron Trim System Lubrication Task 27-10-02-640		
B271005	551 571 651 671	Aileron Trim Tab (Free Play) Functional Check Task 27-10-02-720		
B273003	371 372 375 376	Elevator Trim Tab (Free Play) Functional Check Task 27-30-02-720		
D282101	130	Firewall Mounted Fuel Filter Servicing Task 28-21-00-610		
B282103	213 214 220	Firewall Fuel Shutoff Valve Control Operational Check Task 28-21-00-711		
C282301	231 232 511 611	Wing Shutoff Valve Linkage Lubrication Task 28-23-00-640		
B284101	ENG	Fuel Reservoir Warning System Operational Check Task 28-41-00-710		
B301001	122 AUX	Bleed Air Pressure Regulator Functional Check (Airplanes with de-ice boots installed) Task 30-10-00-720		
A353003	256	Portable Oxygen Cylinder Detailed Inspection Task 35-30-00-221		

Revision No. : 03
SCA/TEK/1-001
26 September 2019

Page 13.1

ITEM CODE NO.	ZONE	TASK	SIGNATURE	
			SIGN	STAMP
B611101	110	McCauley Propeller Functional Check Task 61-11-00-720		
A712001	130	Engine Mounts and Firewall Detailed Inspection Task 71-20-00-220		
A716001	130	Inertial Air Separator Detailed Inspection Task 71-60-00-220		
B761001	130 211 212 ENG	Engine Controls Functional Check Task 76-10-00-72		
A801001	130	Starter-Generator (Part Number 23081 Series only) Detailed Inspection Task 80-10-00-220		
*** End of Inspection Document 07 Items ***				

PERSONNEL PARTICIPATING IN THIS INSPECTION			
NAME	POSITION	SIGNATURE	LICENSE NUMBER
YOHAN S. DEPARI	ENGINEER		12128
VADI ANANTA	ENGINEER		5655

RETURN TO SERVICE


The work recorded above has been carried out in accordance with the requirements of the Civil Aviation Safety Regulation for the time being in force and in that respect the aircraft is consider fit for Release to Service.

Name : YOHAN SEMBIRING DEPARI

Stamp :



Signature :



Place/Date :


PEKANBARU / 03 JUNE - 2022

MAINTENANCE PROGRAM CESSNA C208/C208B

Chapter 14 – Inspection Document 08

Reg. Mark : PK - SNV
MSN : C208B-5551
TSN / CSN : 2805 : 10 / 4934

Date : 03-JUNE-2022
Station : PERANBARU
WO No. : WO/068-SNV/V/2022

ITEM CODE NO.	ZONE	TASK	SIGNATURE	
			SIGN	STAMP
B215001	121 122	Compressor Drive Belt Functional Check Task 21-50-00-720		
A322001	710	Nose Landing Gear Detailed Inspection Task 32-20-00-220		
*** End of Inspection Document 08 Items ***				

PERSONNEL PARTICIPATING IN THIS INSPECTION			
NAME	POSITION	SIGNATURE	LICENSE NUMBER
YOHAN. S. DEPARI	ENGINEER		12128
VANI ANANTA	ENGINEER		9659

RETURN TO SERVICE

The work recorded above has been carried out in accordance with the requirements of the Civil Aviation Safety Regulation for the time being in force and in that respect the aircraft is consider fit for Release to Service.

Name : VANI ANANTA  Stamp : 
Signature :  Place/Date : PERANBARU / 03 JUN 2022



MAINTENANCE PROGRAM CESSNA C208/C208B

Chapter 51 – Engine PT6A-140 100 Hours/Minor Inspection

Reg. Mark	: PK - SNV	Date	: 02 - JUNE - 2022
MSN	: C208B-5551	Station	: PEKANBARU
TSN / CSN	: 2805 : 10 / 4934	WO No.	: WO/068-SNV/V/2022

ITEM CODE NO.	ZONE	TASK	SIGNATURE	
			SIGN	STAMP
F710001	130	Do a check of the FCU manual override system for static operation. For the engines installed with a manual override system only.		
F710003	130	Do a compressor performance recovery wash		
F720000	130	Do a visual inspection of the Control Linkages and wiring.		
F720001	130	Do a visual inspection of the engine exhaust duct welds.		
F720002	130	Do a visual inspection of the engine exhaust duct for cracks.		
F720003	130	Do a visual inspection of the gas generator case and the center fireseal.		
F720004	130	Do a visual inspection of the rear fireseal mounting ring.		
F722001	130	Do a visual inspection of the air inlet screen.		
F723000	130	Do a visual inspection with a mirror or a borescope inspection of the First-stage Compressor Rotor and the inlet case for corrosion		
F725005	130	Do a detailed inspection of the turbine exhaust duct.		
F731002	130	Do a check for the fuel pump installation and leaks.		
F731003	130	Do a check of the oil-to- fuel heater installation		
F731035	130	Do a visual Inspection of the Fuel - Oil Heat Exchanger Fuel Filter Element (CLEANING / REPLACEMENT) P/N OFF: <u>AN 6235-3A</u> P/N ON: <u>AN 6235-3A</u>		

MAINTENANCE PROGRAM CESSNA C208/C208B


Chapter 51 – Engine PT6A-140 100 Hours/Minor Inspection

ITEM CODE NO.	ZONE	TASK	SIGNATURE	
			SIGN	STAMP
F731006	130	Do a check of the drain valve for installation and leaks		
F731007	130	Do a check of the flow divider for installation and leaks.		
F731008	130	Do a visual inspection of the P3 filter and drain valve.		
F731015	130	Do a visual inspection of Fuel Pump outlet filter. (CLEANING / REPLACEMENT) P/N OFF: <u>AN 6235-3A</u> P/N ON: <u>AN 6235-3A</u>		
F731018	130	Clean or replace the P3 filter based on condition, service experience or environment. Note: If corrossions are found, replace filter.		
F732001	130	Do a check of the FCU for installation, linkages and pneumatic tubes.		
F792000	130	Inspect and clean oil filter for debris.		
*** End of Engine PT6A-140 100 Hours Inspection Items ***				

PERSONNEL PARTICIPATING IN THIS INSPECTION			
NAME	POSITION	SIGNATURE	LICENSE NUMBER
YOHAN.S. DEPARI	ENGINEER		12128
VAPI AWANTA	ENGINEER		9659

RETURN TO SERVICE

The work recorded above has been carried out in accordance with the requirements of the Civil Aviation Safety Regulation for the time being in force and in that respect the aircraft is consider fit for Release to Service.

Name : YOHAN SEMBIRING DEPARI Stamp : 
Signature :  Place/Date : PEKANBARU / 03 - JUNE - 2022

MAINTENANCE PROGRAM CESSNA C208/C208B

Chapter 52 – Engine PT6A-140 200 Hours Inspection


Reg. Mark : PK - SNV Date : 03 - JUNE - 2022
MSN : C208B-5551 Station : PEKANBARU
TSN / CSN : 2805:10 / 4934 WO No. : WO/068-SNV/V/2022

ITEM CODE NO.	ZONE	TASK	SIGNATURE	
			SIGN	STAMP
F793001	130	Do a visual inspection of the chip detector for debris.		
*** End of Engine PT6A-140 200 Hours Inspection Items ***				

PERSONNEL PARTICIPATING IN THIS INSPECTION			
NAME	POSITION	SIGNATURE	LICENSE NUMBER
YOHAN.S. DEPARI	ENGINEER		12128

RETURN TO SERVICE

The work recorded above has been carried out in accordance with the requirements of the Civil Aviation Safety Regulation for the time being in force and in that respect the aircraft is consider fit for Release to Service.

Name : YOHAN. SEMBIRING. DEPARI Stamp : 
Signature :  Place/Date : PEKANBARU /
03 - JUNE - 2022


MAINTENANCE PROGRAM CESSNA C208/C208B

Chapter 53 – Engine PT6A-140 200 Hours or 6 Months Inspection

Reg. Mark : PK - SNV Date : 03 - JUNE - 2022
MSN : C208B-5551 Station : PEKANBARU
TSN / CSN : 2805 : 10 / 4934 WO No. : WO/068-SNV/V/2022

ITEM CODE NO.	ZONE	TASK	SIGNATURE	
			SIGN	STAMP
F793000	130	Do a visual inspection of the AGB internal scavenge oil pump inlet screen		
*** End of Engine PT6A- 140 200 Hours or 6 Months Inspection Items ***				

PERSONNEL PARTICIPATING IN THIS INSPECTION			
NAME	POSITION	SIGNATURE	LICENSE NUMBER
YUHAN.S. DEPARI	ENGINEER		12128

RETURN TO SERVICE			
The work recorded above has been carried out in accordance with the requirements of the Civil Aviation Safety Regulation for the time being in force and in that respect the aircraft is consider fit for Release to Service.			
Name	: YUHAN.S. DEPARI	Stamp	: 
Signature	: 	Place/Date	: PEKANBARU / 03 - JUNE - 2022

MAINTENANCE PROGRAM CESSNA C208/C208B

Chapter 54 – Engine PT6A-140 400 Hours Inspection

Reg. Mark	: PK - SNV	Date	: 03 JUN 2022
MSN	: C208B-5551	Station	: PERANBARU
TSN / CSN	: 2805:10 / 4934	WO No.	: WO/068-SNV/V/2022

ITEM CODE NO.	ZONE	TASK	SIGNATURE	
			SIGN	STAMP
F724000	130	Do borescope inspection of hot section components.		
F731004	130	Do a leak test and a functional test of the fuel manifold adapter and nozzle assemblies. Note: Engines ON fuel nozzle in-situ cleaning program (Ref. Task 71-00-00- 160-808). Test fuel nozzles and refurbish as necessary.		
F741001	130	Do a visual inspection of the ignition exciter.		
F741011	130	Do a visual inspection of the ignition cables.		
F742001	130	Do a functional check of the ignition cable.		
F742002	130	Do a visual inspection of the spark igniter/glow plugs. Note: Examine initially at 200 Hours.		
*** End of Engine PT6A-140 400 Hours Inspection Items ***				

PERSONNEL PARTICIPATING IN THIS INSPECTION			
NAME	POSITION	SIGNATURE	LICENSE NUMBER
YOHANIS DEPARA	ENGINEER		12128
VANI ANANTA	ENGINEER		9659

RETURN TO SERVICE

The work recorded above has been carried out in accordance with the requirements of the Civil Aviation Safety Regulation for the time being in force and in that respect the aircraft is consider fit for Release to Service.

Name	: VANI ANANTA	Stamp	: 
Signature	: 	Place/Date	: PERANBARU / 03 JUN 2022

	EMERGENCY EQUIPMENT LIST INSPECTION & MONITOR	PT. SMART CAKRAWALA AVIATION DEPARTMENT TEKNIK Form: SCAMTC/023
---	--	--

DATE : 01-JUNE-2022	A/C REG : PK-SNV	
A/C TYPE : C208B EX	CHECKER : YOHAN S.	SIGN: 

No.	Description	P/N	S/N	Next Insp.	Remarks
1	Pilot Life Vest	P01202-201	19080030019	01-AUG-2029	Good
2	Co-Pilot Life Vest	P01202-201	19080030039	01-AUG-2029	Good
3	Pax Life Vest				
4	Pax Life Vest				
5	Pax Life Vest				
6	Pax Life Vest				
7	Pax Life Vest				
8	Pax Life Vest				
9	Pax Life Vest				
10	Pax Life Vest				
11	Pax Life Vest				
12	Pax Life Vest				
13	First Aid Kit	FL 220	0919-1381	01-JAN-2023	Good
14	Crash Axe Installed	LOCAL	NSN	ON CONDITION	Good
15	Fire Extinguisher	AMEREX 4352	K-60589867	30-OCT-2022	Good
16	Life Raft (If Installed)				
17	Survival Kit (If Installed)	FL 220	5714	NOV 2024	Good.
OTHERS					

NON ROUTINE CARD
(Form: SCA/MTC/047)

1. JO/WO #	2. DATE	3. MTC TYPE	4. A/C REG/MSN
WO/068-SNV/V/2022	2022	REPLACEMENT	PK-SNV/208B-5551
5. CARD #	6. ATA SPEC	7. TRADE	8. STA
#001	37		
9. ZONE	10. PANEL		

11. DESCRIPTION			
PERFORM REPLACE VACUUM SYSTEM CENTRAL AIR FILTER DISCARD PN: AAD9-18-1			
REFERENCE	☒ AMM Ch. 37-10-00-960	☐ EMM Ch	☐ OTHER
RII (*)	☐ Y	☒ N	MHR :

12. RESULT		MECH	ENG	INSP (*)
Performed at A/C TT : 2805 : 10 A/C TC /LDG : 4934				
FINDING	☐ Y ☐ N	ACT MHR :		DATE/TIME (DD/MM/YY)
INSPECTION CARD (IC) #		01	06	2022

13. PARTS REQUIRED				
DESCRIPTION	PART NO	QTY	REMARK	
			STOCK	STATUS
FILTER	AAD9-18-1	1		

14. TOOLS REQUIRED			
DESCRIPTION	PART NO / MODEL	NEXT CALIBRATION DATE	STATUS
GENERAL TOOLS	-	-	Good



NON ROUTINE CARD
(Form: SCA/MTC/047)

1. JO/WO #	2. DATE	3. MTC TYPE	4. A/C REG/MSN
WO/068-SNVN/2022	2022	REPLACEMENT	PK-SNV/208B-5551
5. CARD #	6. ATA SPEC	7. TRADE	8. STA
#002	37		
9. ZONE	10. PANEL		

11. DESCRIPTION

PERFORM REPLACE VACUUM RELIEF VALVE FILTER DISCARD
PN: B3-5-1

REFERENCE	☒ AMM Ch. 37-10-00-961	☐ EMM Ch	☐ OTHER
RII (*)	☐ Y	☒ N	MHR :

12. RESULT		MECH	ENG	INSP (*)
Performed at A/C TT : 2805:10 A/C TC /LDG : 4934			<i>[Signature]</i>	
FINDING	☐ Y ☐ N	ACT MHR :		DATE/TIME (DD/MM/YY)
INSPECTION CARD (IC) #		01	06	2022

13. PARTS REQUIRED

DESCRIPTION	PART NO	QTY	REMARK	
			STOCK	STATUS
VACUUM FILTER	B3-5-1	1		

14. TOOLS REQUIRED

DESCRIPTION	PART NO / MODEL	NEXT CALIBRATION DATE	STATUS
GENERAL TOOLS	-	-	GOOD



DOCUMENT FORM BORESCOPE INSPECTION FORM

Page | - 1 -

Engine Borescope Inspection

Job No: **WO/068-SNV/V/2022**

<u>Engine Serial Number</u> PCE-VA0607	<u>Date</u>	<u>Base / Location</u>	<u>Aircraft Registration</u> PK-SNV
<u>Aircraft Total Time</u>	<u>Aircraft Total Cycle</u>	<u>Reason For Borescope</u> 400 HOURS INSPECTION	

Note:

Record any discrepancies found during inspection, and/or take photographic evidence.

If None, then write No Findings. If you find defects, please quote EMM (Engine Maintenance Manual)

Reference and Limitations.

Item	Work Description	SIGN	STAMP
1	Remove fuel manifold adapter as necessary (Ref. 73-10-04).		
2	Perform inspection of the First Stage Compressor. <u>Defects:</u> <u>If defects found, quote MM Limitation and References :</u>		

Photo of First Stage Compressor 1st Quadrant

Photo of First Stage Compressor 2nd Quadrant

Photo of First Stage Compressor 3rd Quadrant

Photo of First Stage Compressor 4th Quadrant